FIRST QUANTUM MINERALS LTD.

# Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 403527 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 13/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>234-Backhoe<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | BHL-0000-004 |
| **Manufacturer / Fabricante** | Caterpillar |
| **Model Desc. / Desc. Modelo** | Caterpillar 426f2 Backhoe Retroexcavadora |
| **P&ID** | P&ID |
| **Parent / Padre** | BH Backhoes |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PM CAMBIO FILTROS Y ACEITE |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5100335 | FILTER,FLUID,OIL | | 1.000 | EA |
| 5311373 | AIR FILTER,PRIMARY | | 1.000 | EA |
| 5311374 | AIR FILTER,SECONDARY | | 1.000 | EA |
| 5311391 | FILTER,FLUID,FUEL | | 1.000 | EA |
| 5311418 | OIL FILTER,TRANSMISSION | | 1.000 | EA |
| 5217691 | ELEMENT,HYD | | 1.000 | EA |
| 5122504 | FILTER ELEMENT,AIR,CAB HEATER | | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

PM CAMBIO FILTROS Y ACEITE

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

| Employee Code / | Name / Nombre | Initial / | OPS / Sec. | Act. Hours |
|---|---|---|---|---|

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 403527 WM | Re-Print | |
| **Start Date / Fecha Inicio** | 13/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>234-Backhoe<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Código Empleado | Iniciales | Op | /H. Actual |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CRISTIAN AGUILERA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **30/03/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FAX_INFO:408429:EXM-0000-201:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 408429 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 07/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>006-Excavator<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | EXM-0000-201 |
| **Manufacturer / Fabricante** | Caterpillar |
| **Model Desc. / Desc. Modelo** | Caterpillar 336DL Excavator EX014 |
| **P&ID** | P&ID |
| **Parent / Padre** | EX Excavators |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PM CAMBIO DE FILTROS Y ACEITE |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5120149 | OIL FILTER,ENG,ADVANCED EFFICI | | 1.000 | EA |
| 5142259 | SEPARATOR,WATER,LIQUID FUEL | | 1.000 | EA |
| 5120142 | FILTER,FLUID,FUEL | | 1.000 | EA |
| 5111649 | AIR FILTER,AS,PRIMARY | | 1.000 | EA |
| 5111654 | AIR FILTER,AS,SECONDARY | | 1.000 | EA |
| 5109541 | OIL FILTER,ULTRA HIGH EFFICIEN | | 1.000 | EA |
| 5137322 | FILTER ELEMENT,GP,AIR,CAB | | 1.000 | EA |
| 5137323 | FILTER ELEMENT-CAB AIR | | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

PM CAMBIO DE FILTROS Y ACEITE

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 408429 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 07/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>006-Excavator<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Comments / Comentarios**

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CRISTIAN AGUILERA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **28/04/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FAX_INFO:408280:GS217:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 408280 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 23/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>008-Generator<br>-.<br>Maintenance<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | GS217 GENERADORES |
| **Manufacturer / Fabricante** | SDMO |
| **Model Desc. / Desc. Modelo** | GS217 T16 SDMO T16 SDMO |
| **P&ID** | P&ID |
| **Parent / Padre** | GS217 GS217 T16 SDMO |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PREVENTIVE MAINTENANCE |

| Work Order Parts / Lista de Partes | | | |
|---|---|---|---|
| **JDE Number / Número JDE** | **Spare Description / Descripción de la Parte** **Op No./No.O2** | **Qty / Cant.** | **Unit / Unidad** |

| Equipment and Instructions / Equipo e Instrucciones | |
|---|---|
| | PREVENTIVE MAINTENANCE |

| Tooling / Herramientas | | | |
|---|---|---|---|
| **JDE Number / Número JDE** | **Spare Description / Descripción de la Parte** | **Qty / Cant.** | **Unit / Unidad** |

| Labor Allocated / Descripción Mano Obra | | | |
|---|---|---|---|
| **Crew Size / No. Personas** | **Work Center / Centro de Trabajo** | **OPS / Sec. Op** | **Est. Hours / Horas Est.** |

| Timesheet / Hoja de Tiempo | | | |
|---|---|---|---|
| **Employee Code / Código Empleado** | **Name / Nombre** **Initial / Iniciales** | **OPS / Sec. Op** | **Act. Hours /H. Actual** |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| Comments / Comentarios |
|---|
| |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 408280 WM | Re-Print | |
| **Start Date / Fecha Inicio** | 23/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>008-Generator<br>-.<br>Maintenance<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **VLADIMIR SHEPEL** |
| **WO Raised Date: / Fecha Creacion Orden:** | **27/04/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 404677 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 12/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>007-Forklift<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | THM-0000-101 |
| **Manufacturer / Fabricante** | Manitou |
| **Model Desc. / Desc. Modelo** | Manitou Mht-X1490 9t Telehand Telehandler |
| **P&ID** | P&ID |
| **Parent / Padre** | FL Forklifts |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PM CAMBIO FILTROS Y ACEITE |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|
| 5311613 | AIR FILTER,PRIMARY | 1.000 | EA |
| 5311614 | AIR FILTER,SECONDARY | 1.000 | EA |
| 5311615 | OIL FILTER,ENG | 1.000 | EA |
| 5311616 | SEPARATOR,WATER | 1.000 | EA |
| 5311617 | AIR FILTER,CABIN,EXT | 1.000 | EA |
| 5311618 | FILTER ELEMENT,FLUID,FUEL | 1.000 | EA |
| 5311619 | FILTER,VENT,CABIN,INTERIOR | 1.000 | EA |
| 5311620 | FILTER,FLUID,FUEL | 1.000 | EA |
| 5311621 | FILTER CARTRIDGE,HYD RETURN | 1.000 | EA |
| 5311622 | OIL FILTER,HYDROSTATIC PUMP | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

PM CAMBIO FILTROS Y ACEITE

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. | Work Center / Centro de Trabajo | OPS / Sec. | Est. Hours / |
|---|---|---|---|

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 404677 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 12/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>007-Forklift<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| **Personas** | | **Op** | **Horas Est.** |
|---|---|---|---|
| **Timesheet / Hoja de Tiempo** | | | |
| **Employee Code / Código Empleado** | **Name / Nombre** **Initial / Iniciales** | **OPS / Sec. Op** | **Act. Hours /H. Actual** |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CRISTIAN AGUILERA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **03/04/2020** |
| **Work Completed by: / Trabajo Completado por:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 404677 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 12/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>007-Forklift<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FAX_INFO:412062:ATR-0000-101:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 412062 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 27/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>242-Tractor<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | ATR-0000-101 |
| **Manufacturer / Fabricante** | John Deere |
| **Model Desc. / Desc. Modelo** | John Deere 9370R Tractor |
| **P&ID** | P&ID |
| **Parent / Padre** | ATR Agric Trators |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | MANTENIMIENTO PREVENTIVO |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5604535 | FILTER,HYDRAULIC | | -1.000 | EA |

| Equipment and Instructions / Equipo e Instrucciones |
|---|
| MANTENIMIENTO PREVENTIVO |

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Comments / Comentarios**

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 412062 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 27/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>242-Tractor<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

Se realizo el PM con 1,387.00

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CARLOS ANDRION** |
| **WO Raised Date: / Fecha Creacion Orden:** | **27/05/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FAX_INFO:409255:CRM-0000-201:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 409255 WM | Original Copy | |
| **Start Date / Fecha Inicio** | 06/05/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>218-Crane/Hoist<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | CRM-0000-201 |
| **Manufacturer / Fabricante** | Grove |
| **Model Desc. / Desc. Modelo** | Grove RT650E 45TON CR048 |
| **P&ID** | P&ID |
| **Parent / Padre** | CR Cranes |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | MANTENIMIENTO PREVENTIVO |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5603492 | FILTER,HYDRAULIC | | 1.000 | EA |
| 5313383 | AIR FILTER,PRIMARY | | 1.000 | EA |
| 5595748 | FILTER,ELEMENT,LUBE,SPIN-ON | | 1.000 | EA |
| 5603459 | FILTER,FUEL | | 1.000 | EA |
| 5313385 | AIR FILTER,PANEL | | 1.000 | EA |
| 5313384 | AIR FILTER,SAFETY | | 1.000 | EA |
| 5597709 | FILTER,ELEMENT,HYD | | 1.000 | EA |
| 5597663 | FILTER,FUEL&WATER | | 1.000 | EA |
| 5218607 | DEGREASER,LIQUID CLEANER,5 GAL | | 3.000 | EA |
| 5218608 | PAD,OIL ABSORBENT,30X150IN | | 2.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

MANTENIMIENTO PREVENTIVO

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. | Work Center / Centro de Trabajo | OPS / Sec. | Est. Hours / |
|---|---|---|---|

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 409255 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 06/05/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>218-Crane/Hoist<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Personas | | Op | Horas Est. |
|---|---|---|---|
| **Timesheet / Hoja de Tiempo** | | | |
| **Employee Code / Código Empleado** | **Name / Nombre** **Initial / Iniciales** | **OPS / Sec. Op** | **Act. Hours /H. Actual** |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CARLOS ANDRION** |
| **WO Raised Date: / Fecha Creacion Orden:** | **06/05/2020** |
| **Work Completed by: / Trabajo Completado por:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 409255 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 06/05/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>218-Crane/Hoist<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FAX_INFO:409890:SUT-0000-101:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 409890 WM | Original Copy | |
| **Start Date / Fecha Inicio** | 11/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>247-Sucker truck<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | SUT-0000-101 SU003 |
| **Manufacturer / Fabricante** | Freightliner |
| **Model Desc. / Desc. Modelo** | Freightliner M2 106 Sucker Tru Camion Succionador |
| **P&ID** | P&ID |
| **Parent / Padre** | TT Trucks |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | MANTENIMIENTO PREVENTIVO |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|

**Equipment and Instructions / Equipo e Instrucciones**

| | |
|---|---|
| | MANTENIMIENTO PREVENTIVO |

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Comments / Comentarios**

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 409890 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 11/05/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>247-Sucker truck<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CARLOS ANDRION** |
| **WO Raised Date: / Fecha Creacion Orden:** | **11/05/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FAX_INFO:411073:SSL-0000-007:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 411073 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 01/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>016-Skid Steer<br>-.<br>Maintenance Equipment OP / Island OP | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | SSL-0000-007 |
| **Manufacturer / Fabricante** | Caterpillar |
| **Model Desc. / Desc. Modelo** | Caterpillar 226b Skid Steer L Mini Cargador |
| **P&ID** | P&ID |
| **Parent / Padre** | SS Skid Steers Loaders |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PM CAMBIO DE FILTROS Y ACEITE |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5185957 | MOTOR OIL FILTER | | 1.000 | EA |
| 5311316 | FILTER,FLUID,FUEL | | 1.000 | EA |
| 5185949 | AIR FILTER,PRIMARY | | 1.000 | EA |
| 5185952 | AIR FILTER,SECONDARY | | 1.000 | EA |
| 5280639 | ELEMENT AS-F | | 1.000 | EA |
| 5280011 | ELEMENT AS | | 1.000 | EA |
| 5155091 | CAP,DUST | | 1.000 | EA |
| 5158023 | CAP,DUST | | 1.000 | EA |
| 5185953 | FILTER,1,CAB | | 1.000 | EA |
| 5185954 | FILTER,2,CAB | | 1.000 | EA |
| 5100330 | SEPARADOR DE AGUA | | 1.000 | EA |
| 5311256 | AIR FILTER,SECONDARY | | 1.000 | EA |
| 5125477 | AIR FILTER,AS,PRIMARY | | 1.000 | EA |
| 5311265 | OIL FILTER,ENG | | 1.000 | EA |
| 5100329 | FILTER,FLUID,OIL | | 1.000 | EA |
| 5311268 | FILTER,FLUID,FUEL | | 1.000 | EA |
| 5311261 | FILTER,AIRCOND,CABIN | | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 411073 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 01/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>016-Skid Steer<br>-.<br>Maintenance Equipment OP / Island OP | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | PM CAMBIO DE FILTROS Y ACEITE | | |
|---|---|---|---|
| **Tooling / Herramientas** | | | |
| **JDE Number / Número JDE** | **Spare Description / Descripción de la Parte** | **Qty / Cant.** | **Unit / Unidad** |
| **Labor Allocated / Descripción Mano Obra** | | | |
| **Crew Size / No. Personas** | **Work Center / Centro de Trabajo** | **OPS / Sec. Op** | **Est. Hours / Horas Est.** |

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Comments / Comentarios**

MANTENIMIENTO PREVENTIVO 97 HR

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 411073 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 01/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>016-Skid Steer<br>-.<br>Maintenance Equipment OP / Island OP | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **LUIS VALDIVE** |
| **WO Raised Date: / Fecha Creacion Orden:** | **20/05/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FAX_INFO:416011:TTH-0000-001:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 416011 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 22/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>017-Truck<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | TTH-0000-001 TT027 |
| **Manufacturer / Fabricante** | Freightliner |
| **Model Desc. / Desc. Modelo** | Freightliner M2 106 Hydroseedi Camion Hidrosembrador |
| **P&ID** | P&ID |
| **Parent / Padre** | TT Trucks |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | FABRICACION DE 1 MANGUERA |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|

**Equipment and Instructions / Equipo e Instrucciones**

| | |
|---|---|
| | FABRICACION DE 1 MANGUERA |

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Comments / Comentarios**

REEMPLAZO DE MANGUERA

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 416011 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 22/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>017-Truck<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CRISTIAN AGUILERA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **22/06/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 416763 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 29/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>252-Mule truck<br>-.<br>Maintenance Equipment OP / Island OP | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | TTT-0000-002 CS8264 |
| **Manufacturer / Fabricante** | Freightliner |
| **Model Desc. / Desc. Modelo** | Freightliner Columbia Cl112 Camion Mula |
| **P&ID** | P&ID |
| **Parent / Padre** | TT Trucks |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | PREVENTIVE MAINTENANCE 500Hr |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5311526 | FILTER,FLUID,FUEL | | 1.000 | EA |
| 5311530 | AIR FILTER,PRIMARY | | 1.000 | EA |
| 5311527 | FILTER,SEPARATOR,FUEL | | 1.000 | EA |
| 5311525 | OIL FILTER | | 1.000 | EA |
| 5311529 | AIR FILTER,CABIN | | 1.000 | EA |
| 5603678 | FILTER,LUBE,SPIN ON,FULL FLOW | | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

PREVENTIVE MAINTENANCE 500Hr

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 416763 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 29/06/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>252-Mule truck<br>-.<br>Maintenance Equipment OP / Island OP | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **CRISTIAN AGUILERA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **27/06/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FAX_INFO:444360:GRL-0000-301:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 444360 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 05/09/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>009-Grader<br>-.<br>Work Order Reference<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | GRL-0000-301 MG013 |
| **Manufacturer / Fabricante** | Caterpillar |
| **Model Desc. / Desc. Modelo** | Caterpillar 140K Grader |
| **P&ID** | P&ID |
| **Parent / Padre** | GR Motor Grader |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | Hoja de cuchilla danada |

| Work Order Parts / Lista de Partes | | | |
|---|---|---|---|
| **JDE Number / Número JDE** | **Spare Description / Descripción de la Parte** **Op No./No.O2** | **Qty / Cant.** | **Unit / Unidad** |
| 5156230 | EDGE-CUTTING (7-FT EACH) | 1.000 | EA |

| Equipment and Instructions / Equipo e Instrucciones | |
|---|---|
| | Hoja de cuchilla danada |

| Tooling / Herramientas | | | |
|---|---|---|---|
| **JDE Number / Número JDE** | **Spare Description / Descripción de la Parte** | **Qty / Cant.** | **Unit / Unidad** |

| Labor Allocated / Descripción Mano Obra | | | |
|---|---|---|---|
| **Crew Size / No. Personas** | **Work Center / Centro de Trabajo** | **OPS / Sec. Op** | **Est. Hours / Horas Est.** |

| Timesheet / Hoja de Tiempo | | | |
|---|---|---|---|
| **Employee Code / Código Empleado** | **Name / Nombre** **Initial / Iniciales** | **OPS / Sec. Op** | **Act. Hours /H. Actual** |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 444360 WM | | Original Copy |
| **Start Date / Fecha Inicio** | 05/09/20 | **Priority / Prioridad** | 1 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>009-Grader<br>-.<br>Work Order Reference Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical Mechanical Sup |

Se realiza cambio de cuchilla, se dejan instaladas y operativo

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **EDGARDO VERGARA** |
| **WO Raised Date: / Fecha Creacion Orden:** | **05/09/2020** |
| **Work Completed by: / Trabajo Completado por:** | |
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

FAX_INFO:443249:GSB-0000-603:

FIRST QUANTUM MINERALS LTD.

Cobre Panamá

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 443249 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 23/09/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>008-Generator<br>-.<br>Maintenance<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical GS&LT Sup |

| Asset General Information. / Información General Activo | |
|---|---|
| **Asset No. / No. Activo** | GSB-0000-603 GS260 |
| **Manufacturer / Fabricante** | PRAMAC |
| **Model Desc. / Desc. Modelo** | PRAMAC GSW80P 83 kVa Pit Office |
| **P&ID** | P&ID |
| **Parent / Padre** | GS Genset's |
| **Warranty / Garantia** | NO |

| Description of problem in Work Request. / Descripción del Problema | |
|---|---|
| **1.** | MANTENIMIENTO PREVENTIVO |

**Work Order Parts / Lista de Partes**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Op No./No.O2 | Qty / Cant. | Unit / Unidad |
|---|---|---|---|---|
| 5602521 | LUBE FILTER | | 1.000 | EA |
| 5605326 | FILTER,AIR,PRIMARY,RADIAL SEAL | | 1.000 | EA |
| 5607523 | FILTER,FUEL | | 1.000 | EA |
| 5606058 | DIESEL,FILTERS | | 1.000 | EA |

**Equipment and Instructions / Equipo e Instrucciones**

MANTENIMIENTO PREVENTIVO

**Tooling / Herramientas**

| JDE Number / Número JDE | Spare Description / Descripción de la Parte | Qty / Cant. | Unit / Unidad |
|---|---|---|---|

**Labor Allocated / Descripción Mano Obra**

| Crew Size / No. Personas | Work Center / Centro de Trabajo | OPS / Sec. Op | Est. Hours / Horas Est. |
|---|---|---|---|
| 1 | STMC MANTENIMIENTO PREVENTIVO | 1.00 | |

**Timesheet / Hoja de Tiempo**

| Employee Code / Código Empleado | Name / Nombre | Initial / Iniciales | OPS / Sec. Op | Act. Hours /H. Actual |
|---|---|---|---|---|
| | | | | |
| | | | | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:



Printed / Impreso: 18/10/20

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 443249 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 23/09/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>008-Generator<br>-.<br>Maintenance<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical GS&LT Sup |

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**Comments / Comentarios**

Mantenimiento preventvo de 300 hrs.
- cambio de aceite 15w40
- cambo de fltro de aceite BT216
- cambio de filtro de diesel 4816636
- cambio de filtro de aire RS5641

revision de nivel de collant y tension de correa, se revisa voltage AC y DC.

| | |
|---|---|
| **WO Raised by: / Orden Creada por:** | **VLADIMIR SHEPEL** |
| **WO Raised Date: / Fecha Creacion Orden:** | **03/09/2020** |
| **Work Completed by: / Trabajo Completado por:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

| Maintenance Work Order / Orden de Trabajo de Mantenimiento | | | |
|---|---|---|---|
| **Work Order No. / No. Orden Trabajo** | 443249 WM | | Re-Print |
| **Start Date / Fecha Inicio** | 23/09/20 | **Priority / Prioridad** | 2 |
| **Counter Reading / Lectura Medidor** | | **WO Type / Tipo Orden** | Corrective Order |
| **Category Code / Código Categoría** | -.<br>008-Generator<br>-.<br>Maintenance<br>Equip./Asset Condition | **Status / Estado** | WO Completed |
| | | **Supervisor** | Tactical GS&LT Sup |

| | |
|---|---|
| **Supervisor Review: / Revision del Supervisor:** | |
| **Date Completed / Fecha completada:** | |

Supervisor Name / Nombre Supervisor:

Supervisor Signature / Firma Supervisor:

| Numero Orden | Descripcion del número del activo | Descripcion del tipo d orden | Problema | Fecha de la orden | Equipo segunda descripcion | Numero del equipo | Numero de serie | Descripcion del estado de la orden | Cat 02 Descripcion |
|---|---|---|---|---|---|---|---|---|---|
| 409767 | PRAMAC GSW110P 82 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Tmf Laboratory | 62816 | PEE2628886 | WO Completed | Generator |
| 411633 | PRAMAC GSW170I 164 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Cobre Stp Back Up | 62817 | PEE2603478 | WO Completed | Generator |
| 410925 | PRAMAC GSW170I 164 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | Cobre Stp Back Up | 62817 | PEE2603478 | WO Completed | Generator |
| 411669 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Filtration Plant - Port Back U | 62751 | 152546 | WO Completed | Generator |
| 413555 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Filtration Plant - Port Back U | 62751 | 152546 | WO Completed | Generator |
| 411682 | Olympian GEP 88-3 64 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |
| 408311 | Olympian GEP 88-3 64 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |
| 413558 | Olympian GEP 88-3 64 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |
| 411433 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | Heliport | 62747 | J60U1200881 2 | WO Completed | Generator |
| 413552 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Heliport | 62747 | J60U1200881 2 | WO Completed | Generator |
| 408272 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | Valle Grande - Prestrip | 62763 | J60U1201501 7 | WO Completed | Generator |
| 411675 | SDMO T11UM 10 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Dorado Tower | 62760 | T11UM11005 091 | WO Completed | Generator |
| 410908 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | Petaquilla Camp | 62794 | PEE2608294 | WO Completed | Generator |
| 408942 | Olympian GEP18-6 18 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Vivero Rio Turbe - Environment | 62768 | MMG04468 | WO Completed | Generator |
| 409355 | Caterpillar 226b Skid Steer L | AC FAN REPLACEMENT | GANGE FAN | 07/05/2020 | Mini Cargador | 58490 | DXZ02134 | WO Completed | Skid Steer |
| 414079 | Mobile equipment | ACEITE A GRANEL COMPRESORES | ACEITE PARA MANTENIMIENTO | 11/06/2020 | | 58473 | | WO Completed | Area |
| 410138 | Caterpillar 740B EJ ADT | ACEITE DEL TRANSFER BAJO | ACEITE DEL TRANSFER BAJO | 14/05/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | Articulated dump truck |
| 409696 | Caterpillar 740B EJ ADT | BAJA PRESION DE ACEITE | BAJA PRESION DE ACEITE | 09/05/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | Articulated dump truck |
| 410060 | Broce broom RJT350 | BALINERA DE EJE AVERIADA | BALINERA DE EJE AVERIADA | 13/05/2020 | RB001 | 61686 | 408310 | WO Completed | Scrubber / Sweeper |
| 412414 | Broce broom RJT350 | BALINERA DEL EJE AVERIADA | BALINERA DEL EJE AVERIADA | 29/05/2020 | RB001 | 61686 | 408310 | WO Completed | Scrubber / Sweeper |
| 408774 | Freightliner M2 106 Sucker Tru | BARRA DE PTO AVERIADA | BARRA DE PTO AVERIADA | 01/05/2020 | Camion Succionador | 59978 | 1FVHCYDC27 HZ16885 | WO Completed | . |
| 414569 | Gallegos 28M3 Lime Tank | BOTELLA CON MANOMETROS AVERIAD | BOTELLA CON MANOMETROS AVERIAD | 14/06/2020 | Botella De Cal | 59986 | 3DG1N4083E G000229 | WO Completed | Trailer / Flatbed / Lime Tank |
| 413858 | PRAMAC GSW330V 315 kVa | BREAKDOWN | BATERIAS ROTAS | 08/06/2020 | Sed Pond 2 | 62809 | HEI0004675 | WO Completed | Generator |
| 413151 | Caterpillar 740B EJ ADT | CAMBIO 1 NEUMATICO | CORRECTIVO POSICION 2 | 03/06/2020 | | 61650 | L4E02294 | WO Completed | Articulated dump truck |
| 412532 | ATR-0000-001 4+320 AGRICO | Cambio 2 baterias | DESCARGADAS | 30/05/2020 | | 3900 | 1330200402 | WO Completed | Tractor |
| 410996 | Broce broom RJT350 | Cambio 2 llantas | DESGASTE | 20/05/2020 | RB001 | 61686 | 408310 | WO Completed | Scrubber / Sweeper |
| 409163 | Freightliner Columbia Cl112 | Cambio 2 llantas | DESGASTE | 05/05/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | . |
| 409103 | Caterpillar 740B EJ ADT | CAMBIO 2 NEUMATICO | CORRECTIVO KALTIRE | 04/05/2020 | | 61650 | L4E02294 | WO Completed | . |
| 416272 | Freightliner Columbia Cl112 | cambio 2 neumaticos | CORRECTIVO | 24/06/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | Mule truck |
| 411621 | Unimog Service Truck | cambio 2 neumaticos | CORRECTIVO KALTIRE | 24/05/2020 | Camion De Servicio | 59891 | 4351151W13 7405 | WO Completed | Truck |
| 412397 | Unimog Service Truck | CAMBIO 2 NEUMATICOS DELANTERA | CORRECTIVO KALTIRE | 29/05/2020 | Camion De Servicio | 59891 | 4351151W13 7405 | WO Completed | Truck |
| 413826 | Freightliner Columbia Cl112 | CAMBIO 4 LLANTAS | DESGASTE | 08/06/2020 | Camion Mula | 58534 | 3AKJF0CV9LD KZ8272 | WO Completed | Mule truck |
| 410000 | Caterpillar 426f2 Backhoe | CAMBIO DE 1 NEUMATICO | CORRECTIVO POSICION 1 KALTIRE | 13/05/2020 | Retroexcavadora | 58515 | EJ401044 | WO Completed | Backhoe |
| 416385 | Caterpillar 416F2 Backhoe | CAMBIO DE 1 NEUMATICO | CORRECTIVO | 25/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 409245 | PT049 HINO DUTRO 300 TOYOTA | CAMBIO DE 2 NEUMATICOS | CORRECTIVO KALTIRE | 06/05/2020 | HINO DUTRO 300 TOYOTA | 2946 | JHHMCL3HXJ K025518 | WO Completed | . |
| 408987 | Hyster H700 Forklift | CAMBIO DE 4 NEUMATICO | CORRECTIVO KALTIRE | 03/05/2020 | TH052 | 61672 | H008E02501 R | WO Completed | Forklift |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 416386 | Caterpillar 226b Skid Steer L | CAMBIO DE 4 NEUMATICOS | CORRECTIVO | 25/06/2020 | Mini Cargador | 58490 | DXZ02134 | WO Completed | Skid Steer |
| 415751 | Gallegos Flatbed Trailer | CAMBIO DE 6 NEUMATICOS | CORRECTIVO | 20/06/2020 | Cama Baja | 59880 | 3DG1P4098G G000115 | WO Completed | Trailer / Flatbed / Lime Tank |
| 410485 | JLG 450 AJ Manlift | CAMBIO DE BATERIA | CAMBIO DE BATERIA | 17/05/2020 | Elevador movil | 59955 | 300095682 | WO Completed | Manlift |
| 416159 | Freightliner Columbia Cl112 | CAMBIO DE BATERIAS | CORRECTIVO | 23/06/2020 | Camion Mula | 58529 | 3AKJF0CV0LD KZ8273 | WO Completed | Mule truck |
| 412970 | Grove RT600E 50TON | CAMBIO DE BOMBA DE AGUA | CORRECTIVO BACKLOG | 02/06/2020 | Grua Movil | 59935 | 228106 | WO Completed | Crane/Hoist |
| 414532 | Hyster H700 Forklift | CAMBIO DE COMPONENTES | CAMBIO ASIENTO Y ESPEJOS | 14/06/2020 | TH053 | 61673 | H008E03535 T | W/O In Planning | Forklift |
| 411989 | Caterpillar 226b Skid Steer L | CAMBIO DE COMPONENTES | CORRECTIVO MPSA | 27/05/2020 | Mini Cargador | 58489 | DXZ02133 | WO Completed | Skid Steer |
| 413800 | Caterpillar 416F2 Backhoe | CAMBIO DE DIENTES DE BALDE | CORRECTIVO | 08/06/2020 | Retroexcavadora | 59975 | LBF04160 | W/O In Planning | Backhoe |
| 412582 | Caterpillar 426f2 Backhoe | CAMBIO DE FILTROS Y ACEITE | CORRECTIVO | 31/05/2020 | Retroexcavadora | 58515 | EJ401044 | WO Completed | Backhoe |
| 409477 | Gallegos Flatbed Trailer | Cambio de llanta 2 | DESGASTE | 08/05/2020 | Cama Baja | 59878 | 3DG1P4098G G000113 | WO Completed | . |
| 412354 | Caterpillar 14M Motorgrader | Cambio de llanta P5 | DESGASTE | 29/05/2020 | Motoniveladora | 59969 | R9J00941 | WO Completed | Grader |
| 415749 | Manitou MHT10180L Telehandler | CAMBIO DE MANGUERAS HIDRAULICA | CORRECTIVO | 20/06/2020 | TH040 | 61684 | 761326 | WO Completed | Telehender |
| 409281 | Cargador 966H Wheel Loader | Cambio de palanca implemento | FALLA ELECTRICA | 06/05/2020 | Cargador Frontal | 59995 | RYF01462 | WO Completed | Loader |
| 412642 | Caterpillar 226b Skid Steer L | CAMBIO DE PASADOR | CORRECTIVO | 31/05/2020 | Mini Cargador | 58488 | DXZ02132 | WO Completed | Skid Steer |
| 417024 | Caterpillar 416F2 Backhoe | CAMBIO DE PERNOS | CORRECTIVO | 29/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 413028 | Caterpillar 426f2 Backhoe | Cambio de Puntas | DESDASTE | 03/06/2020 | Retroexcavadora | 58515 | EJ401044 | WO Completed | Backhoe |
| 412944 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | Mule truck |
| 412946 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58528 | 3AKJF0CV7LD KZ8271 | WO Completed | Mule truck |
| 412947 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58529 | 3AKJF0CV0LD KZ8273 | WO Completed | Mule truck |
| 412948 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58530 | 3AKJF0CV5LD KZ8270 | WO Completed | Mule truck |
| 412949 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58531 | 3AKJF0CV9LD KZ8269 | WO Completed | Mule truck |
| 412950 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58532 | 3AKJF0CV7LD KZ8276 | WO Completed | Mule truck |
| 412951 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58533 | 3AKJF0CV2LD KZ8274 | WO Completed | Mule truck |
| 412952 | Freightliner Columbia Cl112 | CAMBIO DE TAPON DE CARTER | CORRECTIVO | 02/06/2020 | Camion Mula | 58534 | 3AKJF0CV9LD KZ8272 | WO Completed | Mule truck |
| 412255 | Caterpillar 236d Skid Steer L | CARTER AVERIADO | CARTER AVERIADO | 28/05/2020 | Mini Cargador | 58487 | MPW02315 | WO Completed | Skid Steer |
| 412882 | Manitou Mht-X1490 9t Telehand | CHANGE TURBO CHARGER | CORRECTIVO | 01/06/2020 | Telehandler | 58778 | 775818 | WO Completed | Telehender |
| 414351 | PRAMAC GSW330V 315 kVa | CHANGES OF BATTERIES | CORRECTIVE WO 413858 | 13/06/2020 | Sed Pond 2 | 62809 | HEI0004675 | WO Completed | Generator |
| 412988 | Freightliner 8170ME Water Truc | COMPRESOR DE AIRE EN MAL ESTAD | COMPRESOR DE AIRE EN MAL ESTAD | 02/06/2020 | Camion Cisterna | 59991 | 3ALHCYCS5E DFK1128 | WO Completed | Water truck |
| 448089 | Mobile equipment | CONSUMIBLES DE JUNIO 20 | KALTIRE | 15/09/2020 | | 58473 | | WO Completed | Area |
| 410063 | Caterpillar 336DL Excavator | CUCHILLA DE BALDE DESAJUSTADA | CUCHILLA DE BALDE DESAJUSTADA | 13/05/2020 | EX014 | 61651 | J2F01045 | WO Completed | Excavator |
| 409375 | Caterpillar 740B EJ ADT | DANO EN FILTRO HIDRAULICO | DANO EN FILTRO HIDRAULICO | 07/05/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | . |
| 409205 | Cargador 966H Wheel Loader | DANOS ELECTRICO | DANOS ELECTRICO | 05/05/2020 | Cargador Frontal | 59995 | RYF01462 | WO Completed | Loader |
| 397878 | Wheels & Tyres | DESGASTE DE LLANTA POS 3,4 | DESGASTE DE LLANTA POS 3,4 | 15/03/2020 | | 6002 | | WO Completed | Dozer |
| 411460 | Caterpillar 226b Skid Steer L | DESMONTAJE DE MOTOR | DESMONTAJE DE MOTOR | 23/05/2020 | Mini Cargador | 58489 | DXZ02133 | WO Completed | Skid Steer |
| 412235 | Mobile equipment | Devolucion partes | DEVOLUCION DE REPUESTOS | 28/05/2020 | | 58473 | | WO Completed | Area |
| 411024 | Mobile equipment | Devolucion partes | DEVOLUCION | 20/05/2020 | | 58473 | | WO Completed | Area |
| 408840 | GS118 J60U SDMO | ELECTRICAL FAULT | ELECTRICAL FAULT | 02/05/2020 | J60U | 853 | J60U1500263 0 | WO Completed | Generator |
| 408837 | PRAMAC GSW560V 407 kVa | Emergency brakedown | EMERGENCY BRAKEDOWN | 02/05/2020 | Camp & Office Dorado | 62797 | HEI0003642 | WO Completed | Generator |
| 414026 | Caterpillar 426f2 Backhoe | EQUIPO FLAT | EQUIPO FLAT | 10/06/2020 | Retroexcavadora | 58517 | EJ401046 | WO Completed | Backhoe |
| 413853 | Manitou Mht-X1490 9t Telehand | EQUIPO FLAT | EQUIPO FLAT | 08/06/2020 | Telehandler | 58536 | C00775760 | WO Completed | Telehender |
| 411755 | Grove RT890 90TON | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 24/05/2020 | Grua Movil | 59933 | 230732 | WO Completed | Crane/Hoist |
| 412263 | Caterpillar 14H Motorgrader | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 28/05/2020 | Motoniveladora | 59974 | ASE01574 | WO Completed | Grader |
| 412663 | JLG 800 AJ Manlift | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 31/05/2020 | Elevador movil | 59949 | 300205969 | WO Completed | Manlift |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 413854 | JLG 800 AJ Manlift | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 08/06/2020 | Elevador movil | 59949 | 300205969 | WO Completed | Manliift |
| 414024 | JLG 1250 AJP Manlift | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 10/06/2020 | Elevador movil | 59959 | 300188132 | WO Completed | Manlift |
| 414025 | Caterpillar 226b Skid Steer L | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 10/06/2020 | Mini Cargador | 58492 | DXZ02136 | WO Completed | Skid Steer |
| 409206 | Manitou Mht-X1490 9t Telehand | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 05/05/2020 | Telehandler | 58520 | V00775291 | WO Completed | . |
| 409376 | JLG 450 AJ Manlift | EQUIPO NO ENCIENDE | EQUIPO NO ENCIENDE | 07/05/2020 | Elevador movil | 59951 | 300083634 | WO Completed | . |
| 412541 | JLG 800 AJ Manlift | EQUIPO NO ENCIENDE | EQUIPO NO ENCIENDE | 30/05/2020 | Elevador movil | 59949 | 300205969 | WO Completed | Manlift |
| 409892 | JLG 1250 AJP Manlift | EQUIPO NO ENCIENDE | EQUIPO NO ENCIENDE | 11/05/2020 | Elevador movil | 59959 | 300188132 | WO Completed | Manlift |
| 414413 | Freightliner M2 106 Hydroseedi | EQUIPO NO ENCIENDE | EQUIPO NO ENCIENDE | 13/06/2020 | Camion Hidrosembrador | 60079 | 3ALHCYCS7F DGK5278 | WO Completed | Truck |
| 414567 | Freightliner M2 106 Sucker Tru | EQUIPO NO SUCCIONA | EQUIPO NO SUCCIONA | 14/06/2020 | Camion Succionador | 59978 | 1FVHCYDC27 HZ16885 | WO Completed | Sucker truck |
| 414019 | Hyster H700 Forklift | EQUIPO PIERDE FUERZA | EQUIPO PIERDE FUERZA | 10/06/2020 | TH052 | 61672 | H008E02501 R | WO Ready to Schedule | Forklift |
| 412664 | Manitou Mht-X1490 9t Telehand | EQUIPO PIERDE FUERZA | EQUIPO PIERDE FUERZA | 31/05/2020 | Telehandler | 58778 | 775818 | WO Completed | Telehender |
| 414017 | Caterpillar 236d Skid Steer L | EQUIPO SE APAGA | EQUIPO SE APAGA | 10/06/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 416852 | Caterpillar 416F2 Backhoe | FABRICACION DE 1 MANGUERA | CORRECTIVO | 28/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 416252 | Grove GMK4100L 100TON | FABRICACION DE 1 MANGUERA | CORRECTIVO | 24/06/2020 | Grua Movil | 59942 | 7145824 | WO Completed | Crane/Hoist |
| 416011 | Freightliner M2 106 Hydroseedi | FABRICACION DE 1 MANGUERA | CORRECTIVO | 22/06/2020 | Camion Hidrosembrador | 60079 | 3ALHCYCS7F DGK5278 | WO Completed | Truck |
| 410002 | Caterpillar 236d Skid Steer L | FABRICACION DE 2 MANGUERAS | CORRECTIVO CENMAN | 13/05/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 410003 | Caterpillar 236d Skid Steer L | FABRICACION DE 2 MANGUERAS | CORRECTIVO CENMAN | 13/05/2020 | Mini Cargador | 58487 | MPW02315 | WO Completed | Skid Steer |
| 409695 | Caterpillar 14H Motorgrader | FALLO ELECTRICO | FALLO ELECTRICO | 09/05/2020 | Motoniveladora | 59974 | ASE01574 | WO Completed | Grader |
| 411373 | Freightliner 8170ME Water Truc | Filtro de enfriador desmontado | FILTRO DE ENFRIADOR DESMONTADO | 22/05/2020 | Camion Cisterna | 59990 | 3ALHCYCS3E DFK1127 | WO Completed | Water truck |
| 410403 | Caterpillar 426f2 Backhoe | FUGA HIDRAULICA | FUGA HIDRAULICA | 16/05/2020 | Retroexcavadora | 58515 | EJ401044 | WO Completed | Backhoe |
| 411267 | Hyster H800 32t Forklift (M) | FUGA HIDRAULICA | FUGA HIDRAULICA | 21/05/2020 | Porta Contenedor | 58776 | C917E02518T | WO Completed | Forklift |
| 411779 | JLG 1250 AJP Manlift | FUGA HIDRAULICA | CONFECCION DE MANGURA | 25/05/2020 | Elevador movil | 59962 | 300201101 | WO Completed | Manlift |
| 409693 | Caterpillar 236d Skid Steer L | FUGA HIDRAULICA | FUGA HIDRAULICA | 09/05/2020 | Mini Cargador | 58487 | MPW02315 | WO Completed | Skid Steer |
| 409870 | Mobile equipment | Herramienta Taller | HERRAMIENTA TALLER | 11/05/2020 | | 58473 | | WO Ready to Schedule | Area |
| 410406 | Caterpillar 740B EJ ADT | INJECTOR DEL BALDE DESCARRILAD | INJECTOR DEL BALDE DESCARRILAD | 16/05/2020 | Camion Articulado | 59896 | L4F00446 | WO Completed | Articulated dump truck |
| 410402 | Cargador 966H Wheel Loader | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 16/05/2020 | Cargador Frontal | 59995 | RYF01462 | WO Completed | Loader |
| 410405 | Caterpillar 307E Miniexcavator | INSPECCIONDE EQUIPO | INSPECCIONDE EQUIPO | 16/05/2020 | Mini Excavadora | 58484 | H1Y03602 | WO Completed | Excavator |
| 415681 | SDMO T11UM 10 kVa | INSPECTION & REVIEW | PREVENTIVE MAINTENANCE | 20/06/2020 | Tower Membrillal | 62761 | T11UM11005 092 | WO Completed | Generator |
| 412055 | Caterpillar 236d Skid Steer L | INSTALACION DE COBERTOR | INSTALACION DE COBERTOR | 27/05/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 390201 | SITE SERVICES | INSTALACION DE CORREA EN BOMBA | INSTALACION DE CORREA EN BOMBA | 29/02/2020 | FACILITIES &TACTICAL EQUIPMENT | 58472 | | WO Completed | . |
| 412808 | Freightliner Columbia Cl112 | INSTALACION DE FILTRO DE DIFER | INSTALACION DE FILTRO DE DIFER | 01/06/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | Mule truck |
| 417165 | PRAMAC GSW80P 83 kVa | INSTALACION DE GENERADOR | CONECCION DE CABLES DE POTENCIA | 30/06/2020 | Colina Prestrip | 62803 | PEE2613703 | WO Completed | Generator |
| 411753 | Caterpillar 226b Skid Steer L | INSTALACION DE LIMPIAPARABRISA | INSTALACION DE LIMPIAPARABRISA | 24/05/2020 | Mini Cargador | 58490 | DXZ02134 | WO Completed | Skid Steer |
| 380659 | Caterpillar 307E Miniexcavator | INSTALACION DE PROTECCION | PREVENTIVO | 11/02/2020 | Mini Excavadora | 58484 | H1Y03602 | WO Completed | Excavator |
| 414415 | Freightliner Columbia Cl112 | INSTALACION DE SENSOR DE TRANS | INSTALACION DE SENSOR DE TRANS | 13/06/2020 | Camion Mula | 58528 | 3AKJF0CV7LD KZ8271 | WO Completed | Mule truck |
| 412056 | Caterpillar 226b Skid Steer L | INSTALACION DE VIDRIO LATERAL | INSTALACION DE VIDRIO LATERAL | 27/05/2020 | Mini Cargador | 58489 | DXZ02133 | WO Completed | Skid Steer |
| 414414 | Freightliner M2 112 Sucker Tru | INSTALAR LLANTA | INSTALAR LLANTA | 13/06/2020 | Camion Succionador | 59981 | 3ALHC5CV1E DFK7520 | WO Completed | Sucker truck |
| 410025 | Caterpillar 226b Skid Steer L | Instalar tablero | MONTAJE | 13/05/2020 | Mini Cargador | 58490 | DXZ02134 | WO Completed | Skid Steer |
| 409691 | Caterpillar CS533E Compactor | LIQUEO HIDRAULICO | LIQUEO HIDRAULICO | 09/05/2020 | VC008 | 61648 | BZE02965 | WO Completed | Compactor |
| 413856 | Cummins C80D6 80 kVa | LLAMADA DE EMERGENCIA | UNIT INSPECTION BY BEAKDOWN | 08/06/2020 | Port Road - Km5 | 62779 | K151409436 | WO Completed | Generator |
| 416075 | Caterpillar D110 E2 110 kVa | LLAMADA DE EMERGENCIA | PARADA DE EMERGENCIA ACTIVADA | 22/06/2020 | Environment Nursery San Juan | 62791 | C44PECL0171 2 | WO Completed | Generator |
| 417167 | USP&E GP700S/V-A 700 kVa | LLAMADA DE EMERGENCIA | INSPECCION ELECTRICA | 30/06/2020 | Filtration Plant - Port Back U | 62751 | 152546 | WO Completed | Generator |
| 417168 | USP&E GP700S/V-A 700 kVa | LLAMADA DE EMERGENCIA | REVISION ELECTRICA | 30/06/2020 | Filtration Plant - Port Back U | 62752 | 152548 | WO Completed | Generator |
| 416492 | Olympian GEP 110-4 80 kVa | LLAMADA DE EMERGENCIA | GUARDA DAÃ'ADA | 25/06/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 416353 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | BOMBA ELECTRICA DE CEBA DIESEL | 24/06/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 415970 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | DESBALANCE DE CARGA | 22/06/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |
| 415377 | SDMO J60U 60 kVa | LLAMADA DE EMERGENCIA | CAMBIO DE FUSIBLE DE CONTROL | 19/06/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 | WO Completed | Generator |
| 416686 | PRAMAC GSW45P 48 kVa | LLAMADA DE EMERGENCIA & PMS | BREAKDOWN | 27/06/2020 | Caimito Senan Police | 62805 | PEE2617251 | WO Completed | Generator |
| 410779 | Freightliner M2 112 Sucker Tru | LLANTA DESINFLADA | LLANTA DESINFLADA | 19/05/2020 | Camion Succionador | 59981 | 3ALHC5CV1E DFK7520 | WO Completed | Sucker truck |
| 411156 | Manitou Mht-X1490 9t Telehand | Llanta flat | LLANTA FLAT | 20/05/2020 | Telehandler | 58778 | 775818 | WO Completed | Telehender |
| 414334 | PRAMAC GSW460V 460 kVa | LOCATE GENERATOR | RIO Z, PIT | 13/06/2020 | Dewatering Set Pond 2 | 62780 | HE10003266 | WO Completed | Generator |
| 414331 | Dossan | LOCATE GENERATOR | LOST | 13/06/2020 | Area 46 - Port | 62771 | 457513U1XE 54 | WO Completed | Generator |
| 414581 | GALLEGOS Lime Tank | MANOMETROS AVERIADOS | MANOMETROS AVERIADOS | 14/06/2020 | CT008 | 61662 | 3DG1N4082E G000223 | WO Completed | Trailer / Flatbed / Lime Tank |
| 408833 | GS014 GEP 200-4 OLYMPIAN | MANT PREVENTIVO | MANTENIMIENTO PREVENTIVO | 02/05/2020 | GEP 200-4 | 753 | LNY00271 | WO Completed | Generator |
| 415294 | Caterpillar D110 E2 110 kVa | MANTENIMIENTO COPRRECTIVO | CONECCION DE GENERADOR | 18/06/2020 | Environment Nursery San Juan | 62791 | C44PECL0171 2 | WO Completed | Generator |
| 416688 | PRAMAC GSW560V 407 kVa | MANTENIMIENTO CORRECTIVO | CAMBIO DE MOTORISADO DEL | 27/06/2020 | Camp & Office Dorado | 62797 | HEI0003642 | WO Completed | Generator |
| 415293 | Olympian GEP 88-3 64 kVa | MANTENIMIENTO CORRECTIVO | LLAMADA DE EMERGENCIA | 18/06/2020 | Villa Del Carmen | 62764 | LEJ00572 | WO Completed | Generator |
| 412062 | John Deere 9370R Tractor | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 27/05/2020 | | 58524 | CJP062109 | WO Completed | Tractor |
| 409255 | Grove RT650E 45TON | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 06/05/2020 | CR048 | 61667 | 227757 | WO Completed | Crane/Hoist |
| 410230 | Hyster E70xn 3t Forklift (E) | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 15/05/2020 | Montacarga Electrico | 58495 | A268N26201 S | WO Completed | Forklift |
| 410229 | Hyster E70xn 3t Forklift (E) | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 15/05/2020 | Montacarga Electrico | 58497 | A268N26184 S | WO Completed | Forklift |
| 411577 | Hyster H800 32t Forklift (M) | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 23/05/2020 | Porta Contenedor | 58777 | C917E02519T | WO Completed | Forklift |
| 415414 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACETE & FILTROS | 19/06/2020 | Pit Office | 62815 | PEE2620354 | WO Completed | Generator |
| 415979 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 22/06/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 415982 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEPLAZO DE ACEITES & FILTROS | 22/06/2020 | Kitchen-Laundry-Water Pumps Do | 62795 | HEI0004146 | WO Completed | Generator |
| 415983 | Olympian GEP 110-4 80 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 22/06/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 415373 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/06/2020 | Heliport | 62747 | J60U1200881 2 | WO Completed | Generator |
| 414899 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REMPLAZO DE ACEITE & FILTROS | 16/06/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 409890 | Freightliner M2 106 Sucker Tru | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 11/05/2020 | Camion Succionador | 59978 | 1FVHCYDC27 HZ16885 | WO Completed | Sucker truck |
| 410058 | Freightliner M112 Truck Tip | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 13/05/2020 | Camion Volquete | 58780 | 3ALMC5CVXL DKZ8280 | WO Completed | Tipper |
| 410061 | Freightliner M112 Truck Tip | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 13/05/2020 | Camion Volquete | 59065 | 3ALMC5CV3L DKZ8279 | WO Completed | Tipper |
| 414408 | Freightliner Columbia Cl112 | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 13/06/2020 | Camion Mula | 58532 | 3AKJF0CV7LD KZ8276 | WO Completed | Mule truck |
| 415669 | PRAMAC GBW15 14 kVa | MANTENIMIENTO PREVEVNTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/06/2020 | San Benito Emergency Gate | 62813 | PEE2621568 | WO Completed | Generator |
| 410232 | Cargador 966H Wheel Loader | NIVEL DE HIDRAULICO BAJO | NIVEL DE HIDRAULICO BAJO | 15/05/2020 | Cargador Frontal | 59994 | A6D02174 | WO Completed | Loader |
| 412060 | Caterpillar 740B EJ ADT | NIVEL DE HIDRQAULICO BAJO | NIVEL DE HIDRQAULICO BAJO | 27/05/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | Articulated dump truck |
| 415741 | Case 110JX Tractor Cable Handl | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | TC006 | 61596 | HFJI75884 | WO Completed | Tractor |
| 415742 | Caterpillar 426f2 Backhoe | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | Retroexcavadora | 58514 | EJ401043 | WO Completed | Backhoe |
| 415743 | Caterpillar 416F2 Backhoe | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 415744 | Samil Boom Truck | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | | 59902 | R62178 | WO Completed | Boom truck |
| 415764 | Manitou Mht-X1490 9t Telehand | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | Telehandler | 58520 | V00775291 | WO Completed | Telehender |
| 415871 | Unimog Service Truck | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 21/06/2020 | Camion De Servicio | 59904 | 4351151W12 9584 | WO Completed | Truck |
| 416734 | Freightliner M2 112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 27/06/2020 | Truck Crane | 62742 | IFVHC7CV48 H278447 | WO Completed | Boom truck |
| 416737 | Caterpillar 735B ADT | OIL & FILTER REPLACENT | PM 250 HOURS | 27/06/2020 | Camion Articulado | 59897 | L4D00383 | WO Completed | Articulated dump truck |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 416739 | Caterpillar 320DL | OIL & FILTER REPLACENT | MAINTENANCE PREVENTIVE | 27/06/2020 | EX051 | 62670 | KGF06997 | WO Completed | Excavator |
| 416746 | Hyster H800 32t Forklift (M) | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 27/06/2020 | Porta Contenedor | 58535 | C917E02517T | WO Completed | Forklift |
| 416749 | Manitou Mht-X1490 9t Telehand | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 27/06/2020 | Telehandler | 58536 | C00775760 | WO Completed | Telehender |
| 416767 | Freightliner Columbia Cl112 | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 27/06/2020 | Camion Mula | 58530 | 3AKJF0CV5LD KZ8270 | WO Completed | Mule truck |
| 410598 | GS002 GEP 110-4 OLYMPIAN | OIL & FILTERS REPLACEMENT | PREVENTIVE MAINTENANCE | 18/05/2020 | GEP 110-4 | 741 | LEN03263 | WO Completed | Generator |
| 416790 | Caterpillar C7.1 200 kVa | OIL & FILTERS REPLACEMENT | PREVENTIVE MAINTENANCE | 27/06/2020 | Secondary Crusher Warehouse (T | 62785 | EWC201369 | WO Completed | Generator |
| 412388 | Mobile equipment | PALLET CONTENCION DERRAMES | CONTROL DE DERRAMES ACEITE | 29/05/2020 | | 58473 | | WO Completed | Area |
| 415094 | Gallegos Flatbed Trailer | PARCHE DE NEUMATICO | CONSUMIBLES DE KALTIRE | 17/06/2020 | Cama Baja | 59878 | 3DG1P4098G G000113 | WO Completed | Trailer / Flatbed / Lime Tank |
| 415084 | Hyster H70ft 3t Forklift (M) | PARCHE DE NEUMATICO | CONSUMIBLES DE KALTIRE | 17/06/2020 | Montacarga Mecanico | 58504 | P177V12209 T | WO Completed | Forklift |
| 415082 | Hyster H70ft 3t Forklift (M) | PARCHE DE NEUMATICO | CONSUMIBLES DE KALTIRE | 17/06/2020 | Montacarga Mecanico | 58504 | P177V12209 T | WO Completed | Forklift |
| 415092 | Freightliner Columbia Cl112 | PARCHE DE NEUMATICO | CONSUMIBLES DE KALTIRE | 17/06/2020 | Camion Mula | 58533 | 3AKJF0CV2LD KZ8274 | WO Completed | Mule truck |
| 415095 | Freightliner Columbia Cl112 | PARCHE FRU 2 5125261KP | CONSUMIBLES DE KALTIRE | 17/06/2020 | Camion Mula | 58530 | 3AKJF0CV5LD KZ8270 | WO Completed | Mule truck |
| 412657 | Caterpillar 226b Skid Steer L | PERDIDA DE PIN | PERDIDA DE PIN | 31/05/2020 | Mini Cargador | 58488 | DXZ02132 | WO Completed | Skid Steer |
| 412410 | Gallegos Flatbed Trailer | PERNO AAVERIADO | PERNO AAVERIADO | 29/05/2020 | Cama Baja | 59877 | 3DG1P4098G G000112 | WO Completed | Trailer / Flatbed / Lime Tank |
| 414418 | Bell 225f 4t Forklift (M) | PESERVACION DE EQUIPO | PESERVACION DE EQUIPO | 13/06/2020 | Montacarga Mecanico 3 Ruedas | 58500 | AEBH884FH0 1100039 | WO Completed | Forklift |
| 409855 | Freightliner M2 106 Sucker Tru | PM | HORAS RECORRIDO | 11/05/2020 | Camion Succionador | 59978 | 1FVHCYDC27 HZ16885 | WO Completed | Sucker truck |
| 411786 | Terex RT5551 55TON | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 25/05/2020 | Grua Movil | 61666 | 160972 | WO Completed | Crane/Hoist |
| 408429 | Caterpillar 336DL Excavator | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVE MAINTENANCE | 28/04/2020 | EX014 | 61651 | J2F01045 | WO Completed | Excavator |
| 411031 | Caterpillar 236d Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58487 | MPW02315 | WO Completed | Skid Steer |
| 411046 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58488 | DXZ02132 | WO Completed | Skid Steer |
| 411065 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58489 | DXZ02133 | WO Completed | Skid Steer |
| 411069 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58490 | DXZ02134 | WO Completed | Skid Steer |
| 411072 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58491 | DXZ02135 | WO Completed | Skid Steer |
| 411073 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Mini Cargador | 58492 | DXZ02136 | WO Completed | Skid Steer |
| 410750 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 19/05/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | Mule truck |
| 416761 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 27/06/2020 | Camion Mula | 58527 | 3AKJF0CV4LD KZ8275 | WO Completed | Mule truck |
| 410751 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 19/05/2020 | Camion Mula | 58529 | 3AKJF0CV0LD KZ8273 | WO Completed | Mule truck |
| 410876 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Camion Mula | 58531 | 3AKJF0CV9LD KZ8269 | WO Completed | Mule truck |
| 410948 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Camion Mula | 58533 | 3AKJF0CV2LD KZ8274 | WO Completed | Mule truck |
| 410962 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | Camion Mula | 58534 | 3AKJF0CV9LD KZ8272 | WO Completed | Mule truck |
| 411880 | Unimog Service Truck | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 26/05/2020 | Camion De Servicio | 59891 | 4351151W13 7405 | WO Completed | Truck |
| 415738 | ATR-0000-001 4+320 AGRICO | PM CAMBIO FILTROS Y ACEITE | PREVENTIVO MPSA | 20/06/2020 | | 3900 | 1330200402 | WO Ready to Schedule | Tractor |
| 410004 | John Deere 9370R Tractor | PM CAMBIO FILTROS Y ACEITE | PREVENTIVE MAINTENANCE | 13/05/2020 | | 58524 | CJP062109 | WO Completed | Tractor |
| 403527 | Caterpillar 426f2 Backhoe | PM CAMBIO FILTROS Y ACEITE | PREVENTIVO MPSA | 30/03/2020 | Retroexcavadora | 58517 | EJ401046 | WO Completed | Backhoe |
| 404677 | Manitou Mht-X1490 9t Telehand | PM CAMBIO FILTROS Y ACEITE | PREVENTIVO MPSA | 03/04/2020 | Telehandler | 58519 | E00774969 | WO Completed | Forklift |
| 413660 | John Deere 9370R Tractor | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 07/06/2020 | | 58524 | CJP062109 | WO Completed | Tractor |
| 413659 | John Deere 9370R Tractor | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 07/06/2020 | | 58525 | KJP062003 | WO Completed | Tractor |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| | | | | | | 1RW9370RJK | | |
| 414564 | John Deere 9370R Tractor | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 14/06/2020 | 61670 | P064014 | WO Completed | Tractor |
| 413259 | Case 110JX Tractor Cable Handl | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 04/06/2020 TC007 | 61597 | HFJ175184 | WO Completed | Tractor |
| 413661 | Caterpillar 426f2 Backhoe | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 07/06/2020 Retroexcavadora | 58517 | EJ401046 | WO Completed | Backhoe |
| | | | | | | 1FVHC5CV55 | | |
| 413852 | Internation F2674 | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 BOOM TRUCK | 59886 | HU62906 | WO Completed | Boom truck |
| 413258 | Samil Boom Truck | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 04/06/2020 | 59905 | R215374 | WO Completed | Boom truck |
| 410066 | Grove GMK 4080 80TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/05/2020 Grua Movil | 59937 | 40802311 | WO Completed | Crane/Hoist |
| 413851 | Grove GMK4100L 100TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59942 | 7145824 | WO Completed | Crane/Hoist |
| 410065 | Grove RT600E 50TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/05/2020 Grua Movil | 59934 | 229424 | WO Completed | Crane/Hoist |
| 413846 | Grove RT600E 50TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59934 | 229424 | WO Completed | Crane/Hoist |
| 413847 | Grove RT600E 50TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59935 | 228106 | WO Completed | Crane/Hoist |
| 413845 | Grove RT600E 50TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 61665 | 232538 | WO Completed | Crane/Hoist |
| 413374 | Grove RT650E 45TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 05/06/2020 CR048 | 61667 | 227757 | WO Completed | Crane/Hoist |
| 413848 | Terex RT670 64TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59938 | 160657 | WO Completed | Crane/Hoist |
| 413850 | Grove RT700E 60TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59941 | 227787 | WO Completed | Crane/Hoist |
| 410064 | Grove RT880E 75TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/05/2020 Grua Movil | 59939 | 230973 | WO Completed | Crane/Hoist |
| 413849 | Grove RT880E 75TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 08/06/2020 Grua Movil | 59939 | 230973 | WO Completed | Crane/Hoist |
| 411161 | GROVE RT530E 30TON | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 20/05/2020 CR058 | 61683 | 224254 | WO Completed | Crane/Hoist |
| 412659 | Caterpillar D8T Dozer | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 31/05/2020 Tractor De Oruga | 59930 | J8B02953 | WO Completed | Dozer |
| | | | | | | A268N26201 | | |
| 409287 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 06/05/2020 Montacarga Electrico | 58495 | S | WO Completed | Forklift |
| | | | | | | A268N26201 | | |
| 409286 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 06/05/2020 Montacarga Electrico | 58495 | S | WO Completed | Forklift |
| | | | | | | A268N26183 | | |
| 411144 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 20/05/2020 Montacarga Electrico | 58496 | S | WO Completed | Forklift |
| | | | | | | A268N26183 | | |
| 414411 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/06/2020 Montacarga Electrico | 58496 | S | WO Completed | Forklift |
| | | | | | | A268N26184 | | |
| 409288 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 06/05/2020 Montacarga Electrico | 58497 | S | WO Completed | Forklift |
| | | | | | | A268N26195 | | |
| 411145 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 20/05/2020 Montacarga Electrico | 58498 | S | WO Completed | Forklift |
| | | | | | | A268N26195 | | |
| 414412 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/06/2020 Montacarga Electrico | 58498 | S | WO Completed | Forklift |
| | | | | | | AEBH884FP0 | | |
| 414420 | Bell 225f 4t Forklift (M) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 13/06/2020 Montacarga Mecanico 3 Ruedas | 58502 | 1100046 | WO Completed | Forklift |
| | | | | | | P177V12113 | | |
| 411377 | Hyster H70ft 3t Forklift (M) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 22/05/2020 Montacarga Mecanico | 58503 | T | WO Completed | Forklift |
| 411149 | Hyster H800 32t Forklift (M) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 20/05/2020 Porta Contenedor | 58777 | C917E02519T | WO Completed | Forklift |
| 414777 | Caterpillar DP50 Forklift (M) | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 15/06/2020 Montacarga Mecanico | 59966 | AT28C60323 | WO Completed | Forklift |
| | | | | | | 1HTWEAZR9 | | |
| 413662 | International 7400 SBA Fire Tr | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 07/06/2020 Camione Bombero | 60081 | DJ191990 | WO Completed | Fire truck |
| | | | | | | 9ADVSRA3CD | | Trailer / Flatbed / Lime Tank |
| 412877 | Randon SR-Sl-TV-03-27 Lime Tan | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 01/06/2020 Botella De Cal | 59983 | M357868 | WO Completed | |
| | | | | | | 9ADVSRA3CD | | Trailer / Flatbed / Lime Tank |
| 412878 | Randon SR-Sl-TV-03-27 Lime Tan | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 01/06/2020 Botella De Cal | 59984 | M357866 | WO Completed | |
| | | | | | | 3DG1N4083E | | Trailer / Flatbed / Lime Tank |
| 412880 | Gallegos 28M3 Lime Tank | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 01/06/2020 Botella De Cal | 59986 | G000229 | WO Completed | |
| | | | | | | 3DG1N4087E | | Trailer / Flatbed / Lime Tank |
| 412881 | Gallegos 28M3 Lime Tank | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 01/06/2020 Botella De Cal | 59987 | G000220 | WO Completed | |
| | | | | | | CATRM500JT | | |
| 411370 | Caterpillar RM500 Reclaimer | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 22/05/2020 RM002 | 61688 | AS00143 | WO Completed | Reclaimer |
| | | | | | | | | Scrubber / |
| 411269 | Tennant T7 Scrubber | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 21/05/2020 Restregadora | 58510 | 10872394 | WO Completed | Sweeper |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 411268 | Tennant S30 Sweeper | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 21/05/2020 | Barredora | 58477 | 9199 | WO Completed | Scrubber / Sweeper |
| 412989 | Manitou MHT10180L Telehandler | PRESERVACION DE EQUIPO | PRESERVACION DE EQUIPO | 02/06/2020 | TH040 | 61684 | 761326 | WO Completed | Telehender |
| 412660 | ATR-0000-001 4+320 AGRICO | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 31/05/2020 | | 3900 | 1330200402 | WO Completed | Tractor |
| 414563 | John Deere 9370R Tractor | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 14/06/2020 | | 61670 | 1RW9370RJK P064014 | WO Completed | Tractor |
| 410783 | Case 110JX Tractor Cable Handl | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 19/05/2020 | TC007 | 61597 | HFJ175184 | WO Completed | Tractor |
| 410781 | Freightliner FL112 Boom Truck | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 19/05/2020 | Camione Grua | 60078 | 1FVHBGCVX3 HM00395 | WO Completed | Boom truck |
| 413369 | Samil Boom Truck | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 05/06/2020 | | 59902 | R62178 | WO Completed | Boom truck |
| 414560 | Grove GMK 4080 80TON | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 14/06/2020 | Grua Movil | 59937 | 40802311 | WO Completed | Crane/Hoist |
| 413373 | Grove RT600E 50TON | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 05/06/2020 | Grua Movil | 61665 | 232538 | WO Completed | Crane/Hoist |
| 410778 | Caterpillar 740B EJ ADT | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 19/05/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | Articulated dump truck |
| 411123 | Hyster E70xn 3t Forklift (E) | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 20/05/2020 | Montacarga Electrico | 58496 | A268N26183 S | WO Completed | Forklift |
| 411154 | International 7400 SBA Fire Tr | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 20/05/2020 | Camione Bombero | 60081 | 1HTWEAZR9 DJ191990 | WO Completed | Fire truck |
| 411580 | JLG 450 AJ Manlift | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 23/05/2020 | Elevador movil | 59952 | 300196882 | WO Completed | Manlift |
| 411375 | Caterpillar CW34 Compactor | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 22/05/2020 | Compactadora Neumatica | 59926 | C3400208 | WO Completed | Compactor |
| 411163 | FARESIN FH3000 Telehandler | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 20/05/2020 | TH042 | 61659 | FM3017E394 8 | WO Completed | Telehender |
| 413370 | Unimog Service Truck | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 05/06/2020 | Camion De Servicio | 59901 | 4374212V21 5427 | WO Completed | Truck |
| 413371 | Unimog Service Truck | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 05/06/2020 | Camion De Servicio | 59893 | 4.35115E+13 | WO Completed | Truck |
| 413372 | International 7400 SBA Water T | PRESERVACION DE EQUIPOS | PRESERVACION DE EQUIPOS | 05/06/2020 | Camion Cisterna | 59992 | 3HTWGADT2 CN124852 | WO Completed | Water truck |
| 411162 | Terex RT5551 55TON | PRESERVACION DEEQUIPOS | PRESERVACION DEEQUIPOS | 20/05/2020 | Grua Movil | 61666 | 160972 | WO Completed | Crane/Hoist |
| 411147 | Hyster H300 13t Forklift (M) | PRESERVCION DE EQUIPO | PRESERVCION DE EQUIPO | 20/05/2020 | Montacarga Mecanico | 58507 | L019E01641T | WO Completed | Forklift |
| 410782 | GROVE GMK 2035E 35TON | PRESEVACION DE EQUIPOS | PRESEVACION DE EQUIPOS | 19/05/2020 | CR045 | 61681 | 20352086 | WO Completed | Crane/Hoist |
| 413298 | Caterpillar 426f2 Backhoe | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | Retroexcavadora | 58516 | EJ401045 | WO Completed | Backhoe |
| 413301 | Internation F2674 | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | BOOM TRUCK | 59886 | 1FVHC5CV55 HU62906 | WO Completed | Boom truck |
| 413304 | Freightliner FL112 Boom Truck | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | Camione Grua | 60078 | 1FVHBGCVX3 HM00395 | WO Completed | Boom truck |
| 413345 | GROVE RT9130E 120TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | CR025 | 61676 | 230656 | W/O In Planning | Crane/Hoist |
| 413307 | Grove RT600E 50TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | Grua Movil | 59934 | 229424 | WO Completed | Crane/Hoist |
| 412536 | Grove RT600E 50TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | Grua Movil | 59935 | 228106 | WO Completed | Crane/Hoist |
| 413348 | GROVE RT600E 50TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | CR030 | 61677 | 229428 | WO Completed | Crane/Hoist |
| 413351 | Broderson IC80-EF 9TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | CR039 | 61679 | 26271 | WO Completed | Crane/Hoist |
| 412614 | Caterpillar 740B EJ ADT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | Camion Articulado | 59896 | L4F00446 | WO Completed | Articulated dump truck |
| 412616 | Caterpillar 740B EJ ADT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | | 61650 | L4E02294 | WO Completed | Articulated dump truck |
| 412619 | Caterpillar D8T Dozer | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | | 61645 | J8B03476 | WO Completed | Dozer |
| 413425 | Caterpillar 307E Miniexcavator | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Mini Excavadora | 58484 | H1Y03602 | WO Completed | Excavator |
| 413428 | Bell 225f 4t Forklift (M) | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Montacarga Mecanico 3 Ruedas | 58499 | AEBH884FE0 1100057 | WO Completed | Forklift |
| 413430 | Bell 225f 4t Forklift (M) | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Montacarga Mecanico 3 Ruedas | 58500 | AEBH884FH0 1100039 | WO Completed | Forklift |
| 413431 | Bell 225f 4t Forklift (M) | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Montacarga Mecanico 3 Ruedas | 58502 | AEBH884FP0 1100046 | WO Completed | Forklift |
| 413436 | Hyster H300 13t Forklift (M) | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Montacarga Mecanico | 58508 | L019E01642T | WO Completed | Forklift |
| 412626 | Caterpillar 12M Motorgrader | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | Motoniveladora | 59968 | B9200149 | WO Completed | Grader |
| 412627 | Caterpillar 14M Motorgrader | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | Motoniveladora | 59969 | R9J00941 | WO Completed | Grader |
| 411685 | GS013 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | GEP 200-4 | 752 | LEY00903 | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 409791 | GS013 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | GEP 200-4 | 752 | LEY00903 | WO Completed | Generator |
| 408941 | GS013 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | GEP 200-4 | 752 | LEY00903 | WO Completed | Generator |
| 412477 | GS013 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | GEP 200-4 | 752 | LEY00903 | WO Completed | Generator |
| 408954 | GS014 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | GEP 200-4 | 753 | LNY00271 | WO Completed | Generator |
| 410602 | GS014 GEP 200-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | GEP 200-4 | 753 | LNY00271 | WO Completed | Generator |
| 408968 | GS018 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | J60U-NEXYS | 757 | J60U1200632 8 | WO Completed | Generator |
| 410899 | GS023 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | T11UM | 762 | T11UM12007 716 | WO Completed | Generator |
| 411454 | GS023 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | T11UM | 762 | T11UM12007 716 | WO Completed | Generator |
| 408320 | GS032 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | J60U-NEXYS | 771 | J60U1300722 7 | WO Completed | Generator |
| 409763 | GS037 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | J60U-NEXYS | 774 | J60U1201501 6 | WO Completed | Generator |
| 412519 | GS037 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | J60U-NEXYS | 774 | J60U1201501 6 | WO Completed | Generator |
| 409732 | GS058 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | J60U-NEXYS | 795 | J60U1201502 0 | WO Completed | Generator |
| 408970 | GS058 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | J60U-NEXYS | 795 | J60U1201502 0 | WO Completed | Generator |
| 409793 | GS058 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | J60U-NEXYS | 795 | J60U1201502 0 | WO Completed | Generator |
| 414356 | GS082 GP700S/V-A USP&E | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/06/2020 | GP700S/V-A | 819 | 160019 | WO Completed | Generator |
| 408312 | GS097 GEP18-6 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | GEP18-6 | 834 | MMG04470 | WO Completed | Generator |
| 413561 | GS097 GEP18-6 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | GEP18-6 | 834 | MMG04470 | WO Completed | Generator |
| 408313 | GS112 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | J60U-NEXYS | 847 | 14010526 | WO Completed | Generator |
| 409772 | GS114 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 10/05/2020 | J60U-NEXYS | 849 | 14010527 | WO Completed | Generator |
| 409774 | GS118 J60U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | J60U | 853 | J60U1500263 0 | WO Completed | Generator |
| 408939 | GS118 J60U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | J60U | 853 | J60U1500263 0 | WO Completed | Generator |
| 410591 | GS119 J60U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | J60U | 854 | J60U1500262 6 | WO Completed | Generator |
| 411442 | GS119 J60U SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 23/05/2020 | J60U | 854 | J60U1500262 6 | WO Completed | Generator |
| 411456 | GS134 PN45 EXPERT POWER | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | PN45 | 2002 | M15F249394 | WO Completed | Generator |
| 410903 | GS134 PN45 EXPERT POWER | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | PN45 | 2002 | M15F249394 | WO Completed | Generator |
| 412504 | GS134 PN45 EXPERT POWER | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | PN45 | 2002 | M15F249394 | WO Completed | Generator |
| 408936 | GS135 PN45 EXPERT POWER | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | PN45 | 2003 | M15F249395 | WO Completed | Generator |
| 410594 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | C100D6 CUMMINS | 2130 | K151409431 | WO Completed | Generator |
| 408971 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | C100D6 CUMMINS | 2130 | K151409431 | WO Completed | Generator |
| 411443 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | C100D6 CUMMINS | 2130 | K151409431 | WO Completed | Generator |
| 408943 | GS141 P110-3 FGW | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | P110-3 FGW | 2132 | FGWPEP40AJ SD01923 | WO Completed | Generator |
| 413567 | GS148 T11UM SDMO | PREVENTIVE MAINTENANCE | PREVENTIVE MAINTENANCE | 07/06/2020 | T11UM SDMO | 2393 | T11UM14012 500 | WO Completed | Generator |
| 409787 | GS149 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | T11UM SDMO | 2394 | T11UM14012 718 | WO Completed | Generator |
| 409769 | GS153 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | T11UM SDMO | 2398 | T11UM14010 434 | WO Completed | Generator |
| 412520 | GS153 T11UM SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | T11UM SDMO | 2398 | T11UM14010 434 | WO Completed | Generator |
| 408945 | GS155 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | T11UM SDMO | 2400 | T11UM14012 728 | WO Completed | Generator |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 408314 | GS157 MMG80 MAGNUM | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | MMG80 MAGNUM | 2440 | 83345 | WO Completed | Generator |
| 409779 | GS161 P249H-3 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | P249H-3 CAT | 2444 | FGWNAV06L GK200275 | WO Completed | Generator |
| 413593 | GS161 P249H-3 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | P249H-3 CAT | 2444 | FGWNAV06L GK200275 | WO Completed | Generator |
| 408306 | GS162 MMG180 MAGNUM | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | MMG180 MAGNUM | 2445 | 68506 | WO Completed | Generator |
| 409739 | GS163 C7.1 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | C7.1 CAT | 2447 | EWC201368 | WO Completed | Generator |
| 408977 | GS163 C7.1 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | C7.1 CAT | 2447 | EWC201368 | WO Completed | Generator |
| 413594 | GS163 C7.1 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | C7.1 CAT | 2447 | EWC201368 | WO Completed | Generator |
| 410894 | GS163 C7.1 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | C7.1 CAT | 2447 | EWC201368 | WO Completed | Generator |
| 408978 | GS167 CAT C4.4 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | CAT C4.4 CAT | 2463 | ECL01537 | WO Completed | Generator |
| 409785 | GS168 CAT C4.4 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | CAT C4.4 CAT | 2464 | ECL01536 | WO Completed | Generator |
| 413568 | GS168 CAT C4.4 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | CAT C4.4 CAT | 2464 | ECL01536 | WO Completed | Generator |
| 409776 | GS180 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | D110 E2 CAT | 2534 | C44PECL0159 5 | WO Completed | Generator |
| 413569 | GS180 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | D110 E2 CAT | 2534 | C44PECL0159 5 | WO Completed | Generator |
| 410596 | GS181 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | D110 E2 CAT | 2535 | C44KECL0159 6 | WO Completed | Generator |
| 408946 | GS181 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2535 | C44KECL0159 6 | WO Completed | Generator |
| 412486 | GS184 D110 E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | D110 E2 CAT | 2537 | C44TECL0161 3 | WO Completed | Generator |
| 408958 | GS184 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2537 | C44TECL0161 3 | WO Completed | Generator |
| 411670 | GS185 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | D110 E2 CAT | 2538 | C44JECL0159 7 | WO Completed | Generator |
| 413595 | GS185 D110 E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | D110 E2 CAT | 2538 | C44JECL0159 7 | WO Completed | Generator |
| 410590 | GS186 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | D110 E2 CAT | 2539 | C44VECL0155 4 | WO Completed | Generator |
| 410603 | GS187 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | D110 E2 CAT | 2540 | C44KECL0171 3 | WO Completed | Generator |
| 408278 | GS190 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | D110 E2 CAT | 2543 | C44PECL0170 9 | WO Completed | Generator |
| 408937 | GS191 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2544 | C44TECL0171 1 | WO Completed | Generator |
| 413596 | GS191 D110 E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | D110 E2 CAT | 2544 | C44TECL0171 1 | WO Completed | Generator |
| 408948 | GS192 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2545 | C44TECL0170 8 | WO Completed | Generator |
| 408947 | GS192 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2545 | C44TECL0170 8 | WO Completed | Generator |
| 408951 | GS193 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D110 E2 CAT | 2546 | C44CECL0170 7 | WO Completed | Generator |
| 412478 | GS193 D110 E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | D110 E2 CAT | 2546 | C44CECL0170 7 | WO Completed | Generator |
| 408980 | GS194 D110 E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | D100 E2 CAT | 2547 | C44EECL0170 6 | WO Completed | Generator |
| 412507 | GS194 D110 E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | D100 E2 CAT | 2547 | C44EECL0170 6 | WO Completed | Generator |
| 409759 | GS195 T11 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | GENERADORES | 2565 | T11UM17005 782 | WO Completed | Generator |
| 413597 | GS195 T11 SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | GENERADORES | 2565 | T11UM17005 782 | WO Completed | Generator |
| 409780 | GS196 T11 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | GENERADORES | 2566 | T11UM17005 781 | WO Completed | Generator |
| 408292 | GS197 T11 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | T11 SDMO | 2578 | T11UM17005 783 | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 410895 | GS198 GSW45 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | GSW45 PRAMAC | 2579 | U464180B | WO Completed | Generator |
| 408959 | GS201 DE110E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | DE110E2 CAT | 2594 | 44KECL01923 | WO Completed | Generator |
| 410588 | GS203 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | DE110E2 CAT | 2596 | 44TECL01921 | WO Completed | Generator |
| 408960 | GS203 DE110E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | DE110E2 CAT | 2596 | 44TECL01921 | WO Completed | Generator |
| 408949 | GS204 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | DE110E2 CAT | 2597 | 44CECL01920 | WO Completed | Generator |
| 408293 | GS208 J30U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | J30U SDMO | 2618 | J30U1700283 2 | WO Completed | Generator |
| 411688 | GS216 GSW110 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | GSW110 PRAMAC | 2660 | PEE2610389 | WO Completed | Generator |
| 410583 | GS216 GSW110 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | GSW110 PRAMAC | 2660 | PEE2610389 | WO Completed | Generator |
| 408952 | GS216 GSW110 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | GSW110 PRAMAC | 2660 | PEE2610389 | WO Completed | Generator |
| 413598 | GS216 GSW110 PRAMAC | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | GSW110 PRAMAC | 2660 | PEE2610389 | WO Completed | Generator |
| 408982 | GS217 T16 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | T16 SDMO | 2661 | T16UM17009 188 | WO Completed | Generator |
| 408280 | GS217 T16 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | T16 SDMO | 2661 | T16UM17009 188 | WO Completed | Generator |
| 412508 | GS217 T16 SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | T16 SDMO | 2661 | T16UM17009 188 | WO Completed | Generator |
| 411681 | GS218 T16 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | T16 SDMO | 2662 | T16UM16000 164 | WO Completed | Generator |
| 409777 | GS218 T16 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | T16 SDMO | 2662 | T16UM16000 164 | WO Completed | Generator |
| 413572 | GS218 T16 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | T16 SDMO | 2662 | T16UM16000 164 | WO Completed | Generator |
| 408961 | GS220 GSW30P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | GSW30P PRAMAC | 2664 | PEE2604169 | WO Completed | Generator |
| 412487 | GS220 GSW30P PRAMAC | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | GSW30P PRAMAC | 2664 | PEE2604169 | WO Completed | Generator |
| 413599 | GS230 J30 SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | J30 SDMO | 2748 | J30U1700314 2 | WO Completed | Generator |
| 409773 | GS230 J30 SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | J30 SDMO | 2748 | J30U1700314 2 | WO Completed | Generator |
| 408310 | GS243 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | | 2986 | ECL02351 | WO Completed | Generator |
| 411689 | GS246 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | | 2989 | ECL02348 | WO Completed | Generator |
| 410585 | GS246 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | | 2989 | ECL02348 | WO Completed | Generator |
| 413574 | GS246 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | | 2989 | ECL02348 | WO Completed | Generator |
| 408962 | GS247 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | | 2990 | ECL02350 | WO Completed | Generator |
| 412488 | GS247 DE110E2 CAT | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | | 2990 | ECL02350 | WO Completed | Generator |
| 410593 | GS249 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | | 2997 | ELC02195 | WO Completed | Generator |
| 411691 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | | 2998 | ECL02196 | WO Completed | Generator |
| 410584 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | | 2998 | ECL02196 | WO Completed | Generator |
| 408950 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | | 2998 | ECL02196 | WO Completed | Generator |
| 413576 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | | 2998 | ECL02196 | WO Completed | Generator |
| 412479 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | | 2998 | ECL02196 | WO Completed | Generator |
| 412489 | GS255 GSW65 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | GENERATORS | 4924 | PEE2621054. | WO Completed | Generator |
| 410604 | GS263 GSW15P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | GENERATORS | 32056 | PEE2619927 | WO Completed | Generator |
| 411665 | GS264 GSW65P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | GENERATORS | 32057 | PEE2625926 | WO Completed | Generator |
| 409756 | GS264 GSW65P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | GENERATORS | 32057 | PEE2625926 | WO Completed | Generator |
| 412501 | GS264 GSW65P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | GENERATORS | 32057 | PEE2625926 | WO Completed | Generator |
| 408321 | GS270 GSW170 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | GENERATORS | 57743 | PEE2640723 | WO Completed | Generator |
| 410607 | Olympian GEP150 135 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | Lower Botija Warehouse Preserv | 62745 | B6T00648 | WO Completed | Generator |
| 410608 | Cummins C80D6 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | Port Road - Km5 | 62779 | K151409436 | WO Completed | Generator |
| 408976 | Cummins C80D6 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Port Road - Km5 | 62779 | K151409436 | WO Completed | Generator |
| 413590 | Cummins C80D6 80 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Port Road - Km5 | 62779 | K151409436 | WO Completed | Generator |
| 409738 | Cummins C80D6 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Port Road - Km5 | 62779 | K151409436 | WO Completed | Generator |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 408979 | Caterpillar D110 E2 110 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | Area 47 Port | 62789 | C44EECL0163 9 | WO Completed | Generator |
| 411677 | PRAMAC GSW110P 82 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Komatsu Assembly Area | 62814 | PEE2628894 | WO Completed | Generator |
| 409766 | PRAMAC GSW110P 82 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Komatsu Assembly Area | 62814 | PEE2628894 | WO Completed | Generator |
| 414353 | PRAMAC GSW110P 82 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/06/2020 | Komatsu Assembly Area | 62814 | PEE2628894 | WO Completed | Generator |
| 408940 | PRAMAC GSW80P 83 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Colina Prestrip | 62804 | PEE2612838 | WO Completed | Generator |
| 408966 | PRAMAC GSW80P 83 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Pit Office | 62815 | PEE2620354 | WO Completed | Generator |
| 412542 | PRAMAC GSW80P 83 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | Pit Office | 62815 | PEE2620354 | WO Completed | Generator |
| 409764 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Heavy Equipment Workshop | 62750 | 152545 | WO Completed | Generator |
| 410580 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | He Workshop & Main Offices Bac | 62753 | 160002 | WO Completed | Generator |
| 408944 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Dewatering Set Pond 2 | 62780 | HE10003266 | WO Completed | Generator |
| 413565 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Dewatering Set Pond 2 | 62780 | HE10003266 | WO Completed | Generator |
| 410595 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 409734 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 408972 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 413591 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 411446 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | Kitchen-Laundry-Water Pumps Do | 62781 | HE10003267 | WO Completed | Generator |
| 408973 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Kitchen-Laundry-Water Pumps Do | 62795 | HEI0004146 | WO Completed | Generator |
| 411457 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | Kitchen-Laundry-Water Pumps Do | 62795 | HEI0004146 | WO Completed | Generator |
| 409784 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Sed Pond 2 | 62808 | HEI0004525 | WO Completed | Generator |
| 408957 | Caterpillar C9 250 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | Colino Dewatering Yard | 62786 | LX900579 | WO Completed | Generator |
| 409786 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Camp & Office Dorado | 62797 | HEI0003642 | WO Completed | Generator |
| 408317 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | Camp & Office Dorado | 62797 | HEI0003642 | WO Completed | Generator |
| 411683 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Camp & Office Dorado | 62798 | HEI0003856 | WO Completed | Generator |
| 408318 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | Camp & Office Dorado | 62798 | HEI0003856 | WO Completed | Generator |
| 413571 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Camp & Office Dorado | 62798 | HEI0003856 | WO Completed | Generator |
| 411684 | Olympian GEP 110-4 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 409790 | Olympian GEP 110-4 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 408938 | Olympian GEP 110-4 80 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 413583 | Olympian GEP 110-4 80 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Vivero Valle Grande | 62746 | LEW00533 | WO Completed | Generator |
| 409758 | Caterpillar C7.1 200 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Secondary Crusher Warehouse (T | 62785 | EWC201369 | WO Completed | Generator |
| 413602 | PRAMAC GSW330V 315 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Sed Pond 2 | 62809 | HEI0004675 | WO Completed | Generator |
| 409761 | PRAMAC GSW705V 770 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Sed Pond 2 | 62810 | HEI0003520 | WO Completed | Generator |
| 414354 | PRAMAC GSW705V 770 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/06/2020 | Sed Pond 2 | 62810 | HEI0003520 | WO Completed | Generator |
| 413603 | PRAMAC GSW705V 770 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Sed Pond 2 | 62810 | HEI0003520 | WO Completed | Generator |
| 412546 | PRAMAC GSW705V 770 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | Sed Pond 2 | 62810 | HEI0003520 | WO Completed | Generator |
| 410927 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 409731 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 413589 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 413587 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 411632 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Patio De Mula - Logistics | 62775 | J60U1500228 5 | WO Completed | Generator |
| 408975 | SDMO J40U 40 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | Terpel Tmf | 62778 | J40U1401142 7 | WO Completed | Generator |
| 411686 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Pit Offices | 62783 | CAT00C44TE C900821 | WO Completed | Generator |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 410587 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | Pit Offices | 62783 | CAT00C44TEC900821 | WO Completed | Generator |
| 408955 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Pit Offices | 62783 | CAT00C44TEC900821 | WO Completed | Generator |
| 408984 | PRAMAC GSW45P 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Caimito Senan Police | 62805 | PEE2617251 | WO Completed | Generator |
| 413600 | PRAMAC GSW45P 48 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Caimito Senan Police | 62805 | PEE2617251 | WO Completed | Generator |
| 409735 | PRAMAC GSW90P 74 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | Communication Tower Dorado | 62806 | PEE2594731 | WO Completed | Generator |
| 408974 | PRAMAC GSW90P 74 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Communication Tower Dorado | 62806 | PEE2594731 | WO Completed | Generator |
| 414352 | PRAMAC GSW90P 74 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/06/2020 | Communication Tower Dorado | 62806 | PEE2594731 | WO Completed | Generator |
| 413601 | PRAMAC GSW90P 74 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Communication Tower Dorado | 62806 | PEE2594731 | WO Completed | Generator |
| 411452 | PRAMAC GSW90P 74 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | Communication Tower Dorado | 62806 | PEE2594731 | WO Completed | Generator |
| 411679 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | San Benito Main Gate | 62811 | PEE2621054 | WO Completed | Generator |
| 408963 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | San Benito Main Gate | 62811 | PEE2621054 | WO Completed | Generator |
| 413578 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | San Benito Main Gate | 62811 | PEE2621054 | WO Completed | Generator |
| 408985 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Dorado Main Gate | 62812 | PEE2622412 | WO Completed | Generator |
| 413604 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 07/06/2020 | Dorado Main Gate | 62812 | PEE2622412 | WO Completed | Generator |
| 411628 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 24/05/2020 | Dorado Main Gate | 62812 | PEE2622412 | WO Completed | Generator |
| 413557 | SDMO T11UM 10 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Tower Membrillal | 62761 | T11UM11005092 | WO Completed | Generator |
| 408981 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Petaquilla Camp | 62794 | PEE2608294 | WO Completed | Generator |
| 412544 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 30/05/2020 | Petaquilla Camp | 62794 | PEE2608294 | WO Completed | Generator |
| 410597 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | San Benito Emergency Gate | 62813 | PEE2621568 | WO Completed | Generator |
| 408964 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | San Benito Emergency Gate | 62813 | PEE2621568 | WO Completed | Generator |
| 411449 | PRAMAC GBW15 14 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 23/05/2020 | San Benito Emergency Gate | 62813 | PEE2621568 | WO Completed | Generator |
| 410586 | Olympian GEP18-6 18 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | Vivero Rio Turbe - Environment | 62768 | MMG04468 | WO Completed | Generator |
| 408983 | SDMO T16 16 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | Caimito | 62801 | T16UM17006736 | WO Completed | Generator |
| 412545 | SDMO T16 16 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/05/2020 | Caimito | 62801 | T16UM17006736 | WO Completed | Generator |
| 408967 | PRAMAC GSW25 17 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 03/05/2020 | Sed Pond 14 | 62820 | PEE2619403 | WO Completed | Generator |
| 413563 | Dossan | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 07/06/2020 | Area 46 - Port | 62771 | 457513U1XE54 | WO Completed | Generator |
| 412633 | JLG 800 AJ Manlift | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | Elevador movil | 59947 | 300187442 | WO Completed | Manlift |
| 413442 | Manitou Mht-X860 6t Telehand | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | Telehandler | 58518 | K00775108 | WO Completed | Telehender |
| 410749 | Caterpillar 236d Skid Steer L | PREVENTIVE MAINTENANCE 1000Hr | OIL & FILTERS REPLACEMENT | 19/05/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 410724 | Freightliner Columbia Cl112 | PREVENTIVE MAINTENANCE 500Hr | OIL & FILTERS REPLACEMENT | 19/05/2020 | Camion Mula | 58528 | 3AKJF0CV7LDKZ8271 | WO Completed | Mule truck |
| 416763 | Freightliner Columbia Cl112 | PREVENTIVE MAINTENANCE 500Hr | OIL & FILTERS REPLACEMENT | 27/06/2020 | Camion Mula | 58528 | 3AKJF0CV7LDKZ8271 | WO Completed | Mule truck |
| 410725 | Freightliner Columbia Cl112 | PREVENTIVE MAINTENANCE 500Hr | OIL & FILTERS REPLACEMENT | 19/05/2020 | Camion Mula | 58530 | 3AKJF0CV5LDKZ8270 | WO Completed | Mule truck |
| 412879 | Gallegos 28M3 Lime Tank | PRRESERVACION DE EQUIPO | PRRESERVACION DE EQUIPO | 01/06/2020 | Botella De Cal | 59985 | 3DG1N408XEG000230 | WO Completed | Trailer / Flatbed / Lime Tank |
| 410226 | Internation F2674 | RECOGER SOPORTES DE GRUA | RECOGER SOPORTES DE GRUA | 15/05/2020 | BOOM TRUCK | 59886 | 1FVHC5CV55HU62906 | WO Completed | Boom truck |
| 411792 | Gallegos Flatbed Trailer | REEMPLAZO DE 1 LLANTA | REEMPLAZO DE 1 LLANTA | 25/05/2020 | Cama Baja | 59880 | 3DG1P4098GG000115 | WO Completed | Trailer / Flatbed / Lime Tank |
| 411791 | Gallegos Flatbed Trailer | REEMPLAZO DE 2 LLANTAS | REEMPLAZO DE 2 LLANTAS | 25/05/2020 | Cama Baja | 59879 | 3DG1P4098GG000114 | WO Completed | Trailer / Flatbed / Lime Tank |
| 412809 | Freightliner Columbia Cl112 | REEMPLAZO DE FILTRO DE DIFEREN | REEMPLAZO DE FILTRO DE DIFEREN | 01/06/2020 | Camion Mula | 58528 | 3AKJF0CV7LDKZ8271 | WO Completed | Mule truck |
| 410748 | Caterpillar 236d Skid Steer L | REEMPLAZO DE FILTROS | REEMPLAZO DE FILTROS | 19/05/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 411780 | Caterpillar 236d Skid Steer L | REEMPLAZO DE MANGUERA HIDRAUL | REEMPLAZO DE MANGUERA HIDRAUL | 25/05/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 412398 | Freightliner FL112 Boom Truck | REEMPLAZO DE MANGUERAS | REEMPLAZO DE MANGUERAS | 29/05/2020 | Camione Grua | 60078 | 1FVHBGCVX3HM00395 | WO Completed | Boom truck |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 411807 | Gallegos Flatbed Trailer | REEMPLAZO DE PULMON DE AIRE | REEMPLAZO DE PULMON DE AIRE | 25/05/2020 | Cama Baja | 59873 | 3DG1P4098G G000108 | WO Completed | Trailer / Flatbed / Lime Tank |
| 412810 | Freightliner Columbia Cl112 | REEMPLAZO FILTRO DE DIFERENCIA | REEMPLAZO FILTRO DE DIFERENCIA | 01/06/2020 | Camion Mula | 58530 | 3AKJF0CV5LD KZ8270 | WO Completed | Mule truck |
| 412811 | Freightliner Columbia Cl112 | REEMPLAZO FILTRO DE DIFERENCIA | REEMPLAZO FILTRO DE DIFERENCIA | 01/06/2020 | Camion Mula | 58533 | 3AKJF0CV2LD KZ8274 | WO Completed | Mule truck |
| 413376 | Caterpillar 740B EJ ADT | RELLENAR GRASA | RELLENAR GRASA | 05/06/2020 | Camion Articulado | 60082 | L4F00441 | WO Completed | Articulated dump truck |
| 414023 | Hyster H70ft 3t Forklift (M) | REMOVER LLANTA FLAT | REMOVER LLANTA FLAT | 10/06/2020 | Montacarga Mecanico | 58504 | P177V12209 T | WO Completed | Forklift |
| 417944 | Caterpillar 226b Skid Steer L | REPAACION DE NEUMATICOS | CORRECTIVO | 05/07/2020 | Mini Cargador | 58488 | DXZ02132 | WO Completed | Skid Steer |
| 401170 | Samil Boom Truck | Repair cab & engine | REPAIR CAB & ENGINE | 22/03/2020 | | 59905 | R215374 | WO Ready to Schedule | Truck |
| 414344 | GS216 GSW110 PRAMAC | REPAIR OIL LEAK | CORRECTIVE WO 413598 | 13/06/2020 | GSW110 PRAMAC | 2660 | PEE2610389 | WO Completed | Generator |
| 414090 | Caterpillar 307E Miniexcavator | REPARACION DE 1 CILINDROS | CORRECTIVO MASTERTECH | 11/06/2020 | Mini Excavadora | 58484 | H1Y03602 | WO Completed | Excavator |
| 414091 | JLG 1250 AJP Manlift | REPARACION DE 1 CILINDROS | CORRECTIVO MASTERTECH | 11/06/2020 | Elevador movil | 59958 | 300188150 | WO Completed | Manlift |
| 409862 | Grove GMK4100L 100TON | REPARACION DE 5 CILINDROS | CORRECTIVO TECNO SERVICIOS | 11/05/2020 | Grua Movil | 59942 | 7145824 | WO Completed | Crane/Hoist |
| 414089 | BT019 345 IVECO GRUA 6X6 | REPARACION DE 6 CILINDROS | CORRECTIVO IMREPSA | 11/06/2020 | Brazo Palfinger PK32080 | 2502 | WJMN1VST0 0C104337 | WO Completed | . |
| 416287 | BT019 345 IVECO GRUA 6X6 | REPARACION DE BANDAS | REPARACION DE BANDAS | 24/06/2020 | Brazo Palfinger PK32080 | 2502 | WJMN1VST0 0C104337 | WO Completed | . |
| 412495 | Caterpillar 307E Miniexcavator | REPARACION DE CILINDRO | CORRECTIVO MASTERTECH | 30/05/2020 | Mini Excavadora | 58484 | H1Y03602 | WO Completed | Excavator |
| 414859 | USP&E GP700S/V-A 700 kVa | REPARACION DE FUGA DE COOLANT | REPARACION DE FUGA DE COOLANT | 16/06/2020 | He Workshop & Main Offices Bac | 62753 | 160002 | WO Completed | Generator |
| 417942 | Freightliner M2 112 Sucker Tru | Reparacion de Neumatico | CORRECTIVO | 05/07/2020 | Camion Succionador | 59980 | 3ALHC5CV5E DFK7519 | WO Completed | Sucker truck |
| 417947 | Freightliner M2 106 Sucker Tru | Reparacion de Neumatico | CORRECTIVE | 05/07/2020 | Camion Succionador | 59978 | 1FVHCYDC27 HZ16885 | WO Completed | Sucker truck |
| 415097 | Freightliner Columbia Cl112 | Reparacion de Neumatico | CONSUMIBLES DE KALTIRE | 17/06/2020 | Camion Mula | 58532 | 3AKJF0CV7LD KZ8276 | WO Completed | Mule truck |
| 417931 | Hyster H70ft 3t Forklift (M) | REPARACION DE NEUMATICOS | CORRECTIVO | 05/07/2020 | Montacarga Mecanico | 58504 | P177V12209 T | WO Completed | Forklift |
| 415102 | GALLEGOS Lime Tank | REPARACION DE NEUMATICOS | CONSUMIBLES DE KALTIRE | 17/06/2020 | CT016 | 61663 | 3DG1N4081E G000231 | WO Completed | Trailer / Flatbed / Lime Tank |
| 415101 | Freightliner Columbia Cl112 | REPARACION DE NEUMATICOS | CONSUMIBLES DE KALTIRE | 17/06/2020 | Camion Mula | 58531 | 3AKJF0CV9LD KZ8269 | WO Completed | Mule truck |
| 417945 | Freightliner Columbia Cl112 | REPARACION DE NEUMATICOS | CORRECTIVE | 05/07/2020 | Camion Mula | 58533 | 3AKJF0CV2LD KZ8274 | WO Completed | Mule truck |
| 415080 | Hyster H70ft 3t Forklift (M) | REPARACION DE PARCHE | CONSUMIBLES DE KALTIRE | 17/06/2020 | Montacarga Mecanico | 58503 | P177V12113 T | WO Completed | Forklift |
| 409285 | International 7400 SBA Water T | REPARACION FUGA DE AIRE | REPARACION FUGA DE AIRE | 06/05/2020 | Camion Cisterna | 59992 | 3HTWGADT2 CN124852 | WO Completed | . |
| 415100 | Gallegos Flatbed Trailer | REPARACION NEUMATICO | CONSUMIBLES DE KALTIRE | 17/06/2020 | Cama Baja | 59873 | 3DG1P4098G G000108 | WO Completed | Trailer / Flatbed / Lime Tank |
| 408836 | PRAMAC GSW65 48 kVa | Replacement V belt | BELT IS DAMAGE | 02/05/2020 | Dorado Main Gate | 62812 | PEE2622412 | WO Completed | Generator |
| 417950 | Manitou Mht-X1490 9t Telehand | REPRACION DE NEUMATICO | CORRECTIVE | 05/07/2020 | Telehandler | 58778 | 775818 | WO Completed | Telehender |
| 410213 | Mobile equipment | Retorno de parte WH | RETORNO PARTES | 15/05/2020 | | 58473 | | WO Completed | Area |
| 412610 | Mobile equipment | Retorno Partes | DEVOLUCION PARTES | 31/05/2020 | | 58473 | | WO Completed | Area |
| 409458 | Mobile equipment | RETURN PARTS FROM TF WS | RETURN PARTS FROM TF WS | 08/05/2020 | | 58473 | | WO Completed | Area |
| 411270 | Hyster E70xn 3t Forklift (E) | REVICION ELECTRICA | REVICION ELECTRICA | 21/05/2020 | Montacarga Electrico | 58498 | A268N26195 S | WO Completed | Forklift |
| 408773 | Hyster H300 13t Forklift (M) | REVISION CILINDROS DESPLAZAMIE | REVISION DE EQUIPO | 01/05/2020 | Montacarga Mecanico | 58507 | L019E01641T | WO Completed | Forklift |
| 413366 | Caterpillar 416F2 Backhoe | REVISION DE CASQUILLOS | REVISION DE CASQUILLOS | 05/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 413319 | Caterpillar 416F2 Backhoe | REVISION DE CUCHILLAS | REVISION DE CUCHILLAS | 05/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 410056 | Caterpillar 416F2 Backhoe | REVISION DE EQUIPO | REVISION DE EQUIPO | 13/05/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| 413375 | Caterpillar 416F2 Backhoe | REVISION DE EQUIPO | REVISION DE EQUIPO | 05/06/2020 | Retroexcavadora | 59975 | LBF04160 | WO Completed | Backhoe |
| 412258 | Caterpillar 740B EJ ADT | REVISION DE EQUIPO | REVISION DE EQUIPO | 28/05/2020 | Camion Articulado | 59896 | L4F00446 | WO Completed | Articulated dump truck |
| 410336 | Caterpillar 740B EJ ADT | REVISION DE EQUIPO | REVISION DE EQUIPO | 16/05/2020 | Camion Articulado | 59896 | L4F00446 | WO Completed | Articulated dump truck |
| 414410 | GALLEGOS Lime Tank | REVISION DE TUBERIAS OBSTRUIDA | REVISION DE TUBERIAS OBSTRUIDA | 13/06/2020 | CT008 | 61662 | 3DG1N4082EG000223 | WO Completed | Trailer / Flatbed / Lime Tank |
| 411578 | JLG 1250 AJP Manlift | REVISION ELECTRICA | REVISION ELECTRICA | 23/05/2020 | Elevador movil | 59960 | 300202101 | WO Completed | Manlift |
| 413657 | Caterpillar 236d Skid Steer L | REVISION ELECTRICA | REVISION ELECTRICA | 07/06/2020 | Mini Cargador | 58486 | MPW02317 | WO Completed | Skid Steer |
| 412261 | Caterpillar CS533E Compactor | REVISION ELECTRICA | REVISION ELECTRICA | 28/05/2020 | VC008 | 61648 | BZE02965 | WO Completed | Compactor |
| 408995 | Freightliner 8170ME Water Truc | REVISION ELECTRICA | REVISION ELECTRICA | 03/05/2020 | Camion Cisterna | 59990 | 3ALHCYCS3EDFK1127 | WO Completed | . |
| 412662 | Hyster H800 32t Forklift (M) | REVISION ELECTRICA SPREDAR | REVISION ELECTRICA SPREDAR | 31/05/2020 | Porta Contenedor | 58777 | C917E02519T | WO Completed | Forklift |
| 408775 | John Deere 9370R Tractor | RUIDO EN BOMBA | RUIDO EN BOMBA | 01/05/2020 | | 58524 | CJP062109 | WO Completed | . |
| 414776 | Hyster H700 Forklift | RUIDO EN CABINA | RUIDO EN CABINA | 15/06/2020 | TH053 | 61673 | H008E03535T | WO Completed | Forklift |
| 414524 | Freightliner Columbia Cl112 | SENSOR CHANGES | CORRECTIVO | 14/06/2020 | Camion Mula | 58529 | 3AKJF0CV0LDKZ8273 | WO Completed | Mule truck |
| 412661 | Caterpillar RM500 Reclaimer | SOPORTE AVERIADO | SOPORTE AVERIADO | 31/05/2020 | RM002 | 61688 | CATRM500JTAS00143 | WO Completed | Reclaimer |
| 398015 | Caterpillar 12M Motorgrader | TERMOSTAT REPLACEMENT | TERMOSTAT REPLACEMENT | 15/03/2020 | Motoniveladora | 59968 | B9200149 | WO Completed | Grader |
| 413334 | Grove RT600E 50TON | TORNAMESA AVERIADO | TORNAMESA AVERIADO | 05/06/2020 | Grua Movil | 59934 | 229424 | WO Completed | Crane/Hoist |
| 416400 | Mobile equipment | TOTEM DE ACEITE 68 TALLER | INSUMOS UIPO TACTICO | 25/06/2020 | | 58473 | | WO Completed | Area |
| 414580 | Gallegos 28M3 Lime Tank | TUBERIA DE DESCARGA AVERIADA | TUBERIA DE DESCARGA AVERIADA | 14/06/2020 | Botella De Cal | 59986 | 3DG1N4083EG000229 | WO Completed | Trailer / Flatbed / Lime Tank |
| 409692 | GALLEGOS Lime Tank | valvula de alivio averiadas | VALVULA DE ALIVIO AVERIADAS | 09/05/2020 | CT016 | 61663 | 3DG1N4081EG000231 | WO Completed | Trailer / Flatbed / Lime Tank |
| 412411 | Gallegos 28M3 Lime Tank | VALVULA DE ESCAPE DANADA | VALVULA DE ESCAPE DANADA | 29/05/2020 | Botella De Cal | 59987 | 3DG1N4087EG000220 | WO Completed | Trailer / Flatbed / Lime Tank |
| 413337 | Grove RT700E 60TON | WUINCHE PRINCIPAL ABERIADO | WUINCHE PRINCIPAL ABERIADO | 05/06/2020 | Grua Movil | 59941 | 227787 | WO Completed | Crane/Hoist |

| Numero Orden | Descripcion del número del activo | Descripcion del tipo d orden | Problema | Fecha de la orden | Comentario del | Tipo de descripcion OT | OT Descripcion del Estado | Cat 02 Descripcion |
|---|---|---|---|---|---|---|---|---|
| 416800 | GS208 J30U SDMO | ALTERNATOR INFORMATION | BUY ALTERNATOR | 27/06/2020 | 683 HORAS | Corrective Order | WO Completed | Generator |
| 429597 | Freightliner Columbia Cl112 | Cambio de 5 llantas | MANTIENE 5 LLANTAS EN MAL ESTADO | 07/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 428754 | Caterpillar 740B EJ ADT | Cambio de baterias | BATERIAS NO RETIENEN CARGA | 05/08/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 426558 | Caterpillar 226b Skid Steer L | CONEXION COUPLING A MOTOR | CORRECTIVO | 27/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 443229 | Caterpillar 140K | Do inspection | DO INSPECTION | 03/09/2020 | 11555.1hrs | Corrective Order | WO Completed | Grader |
| 408638 | MG012 16H CAT | INSTALAR EXTINTOR MANUAL | DETERIORADO | 30/04/2020 | | Corrective Order | WO Completed | Grader |
| 444568 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | EQUIPO SIN COMBUSTIBLE | 06/09/2020 | 24032 horas | Corrective Order | WO Completed | Generator |
| 430317 | Cargador 966H Wheel Loader | OIL & FILTER REPLACEMENT | PREVENTIVE | 08/08/2020 | 20098kms | Corrective Order | WO Completed | Loader |
| 443258 | GS022 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/09/2020 | 5020 horas | Corrective Order | WO Completed | Generator |
| 435167 | GS267 GSW200P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 21/08/2020 | 5451 hours | Corrective Order | WO Completed | Generator |
| 410921 | Olympian GEP150 135 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | | Corrective Order | WO Completed | Generator |
| 424310 | PRAMAC GSW170I 164 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/07/2020 | | Corrective Order | WO Completed | Generator |
| 441591 | PRAMAC GSW170i 164 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/08/2020 | 4040 horas | Corrective Order | WO Completed | Generator |
| 410589 | PRAMAC GSW330V 315 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | 8 042 | Corrective Order | WO Completed | Generator |
| 449649 | PRAMAC GSW330V 315 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/09/2020 | 8144 hours | Corrective Order | WO Completed | Generator |
| 424304 | SDMO T11UM 10 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/07/2020 | 3160 horas | Corrective Order | WO Completed | Generator |
| 435601 | Atlas Copco HILIGHT V5 Light T | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | | Corrective Order | WO Completed | Light Tower |
| 435602 | DOOSAND 1005 Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 29102 horas | Corrective Order | WO Completed | Light Tower |
| 435607 | DOOSAND 1005 Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 20949 horas | Corrective Order | WO Completed | Light Tower |
| 435609 | DOOSAND 1005 Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 18745 horas | Corrective Order | WO Completed | Light Tower |
| 435610 | DOOSAND 1005 Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 24145 horas | Corrective Order | WO Completed | Light Tower |
| 435611 | DOOSAND 1005 Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 7278 horas | Corrective Order | WO Completed | Light Tower |
| 435606 | MAGNUM Light Tower | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 22/08/2020 | 21796 horas | Corrective Order | WO Completed | Light Tower |
| 454085 | Freightliner Cl 120 | Problema con machine brake | SE REPARA SISTEMA DE FRENO | 28/09/2020 | 164414.9 kms | Corrective Order | WO Completed | Mule truck |
| 452383 | Freightliner Cl 120 | reparacion de llantas | LLANTAS FLAT | 24/09/2020 | | Corrective Order | WO Ready to Schedule | Mule truck |
| 447512 | Gallegos Flatbed Trailer | 1 FLAT TIRE IN THE MIDDLE AXLE | 1 FLAT TIRE IN THE MIDDLE AXLE | 13/09/2020 | | Corrective Order | WO Ready to Schedule | Trailer / Flatbed / Lime |
| 403433 | MG012 16H CAT | 16H - MAINTENANCE - 250HRS | 16H - MAINTENANCE - 250HRS | 30/03/2020 | | PM proposal JDE | WO Completed | Grader |
| 428261 | Coaster Bus | A/C REPAIR | CORRECTIVE MAINTENANCE | 03/08/2020 | | Corrective Order | WO Completed | Bus |
| 431794 | Mobile equipment | ACEITE PARA PM PUERTO | PREVENTIVO | 13/08/2020 | | Corrective Order | WO Completed | Area |
| 426319 | Mobile equipment | ACEITE PARA TALLER | ACEITE PARA MANTENIMIENTO | 26/07/2020 | | Corrective Order | WO Completed | Area |
| 430247 | Mobile equipment | ACEITE PARA TALLER | PREVENTIVO | 08/08/2020 | | Corrective Order | WO Completed | Area |
| 439849 | Mobile equipment | ACEITE PARA TALLER AREA 22 | STOCK DE ACEITE TALLER | 27/08/2020 | | Corrective Order | W/O In Planning | Area |
| 439869 | Mobile equipment | ACEITE PARA TALLER GENERADORES | STOCK DE ACEITE TALLER | 27/08/2020 | | Corrective Order | WO Completed | Area |
| 439870 | Mobile equipment | ACEITE PARA TALLER PUERTO | STOCK DE ACEITE TALLER | 27/08/2020 | | Corrective Order | WO Completed | Area |
| 421693 | JLG 1250 AJP Manlift | acople de manguera hidraulica | SOLICITUD DE ACOPLES DE MANGUERA HID | 13/07/2020 | | Corrective Order | WO Completed | Manlift |
| 447929 | Manitou Mht-X860 6t Telehand | AIRE ACONDICIONADO NO ENFRIA | CAMBIAR BLOWER DEL EVAPORADOR | 15/09/2020 | | Corrective Order | WO Ready to Schedule | Telehender |
| 433115 | Freightliner Columbia Cl112 | AJUSTE DE TORNILLOS | AJUSTE DE TORNILLOS | 16/08/2020 | | Corrective Order | WO Ready to Schedule | Mule truck |
| 447794 | JLG 800 AJ Manlift | ALTENATOR BELT CHANGING | CORRECTIVE MAINTENANCE | 14/09/2020 | | Corrective Order | W/O In Planning | Manlift |
| 417775 | GS193 D110 E2 CAT | ALTERNATOR CHANGES | REPAIR | 04/07/2020 | | Corrective Order | WO Completed | Generator |
| 435899 | Caterpillar 236d Skid Steer L | attend to engine problem | ATTEND TO ENGINE PROBLEM | 23/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 439160 | Caterpillar 320DL Excavator | Attend to oil ;leak | ATTEND TO OIL ;LEAK | 26/08/2020 | 2098.3 hrs | Corrective Order | WO Completed | Excavator |
| 433913 | Shuttlelift RTCD5540F 15TON | BAJAR BOMBA HIDRAULICA | BAJAR BOMBA HIDRAULICA | 17/08/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 454092 | John Deere 9370R Tractor | Bajo nivel aceite motor | REVISAR Y DESCARTAR FUGAS | 28/09/2020 | 3062.1 hrs | Corrective Order | WO Completed | Tractor |
| 439267 | Hyster E70xn 3t Forklift (E) | BATTERY CHANGING | PREVENTIVE MAINTENANCE | 26/08/2020 | 1265 hrs | Corrective Order | WO Completed | Forklift |
| 428421 | FG WILSON P88-3 80 kVa | BATTERY CHANGING | CORRECTIVE MAINTENANCE | 04/08/2020 | | Corrective Order | WO Completed | Generator |
| 426714 | PRAMAC GSW170I 164 kVa | BATTERY CHANGING | CORRECTIVE MAINTENANCE | 28/07/2020 | | Corrective Order | WO Completed | Generator |
| 427193 | USP&E GP700S/V-A 700 kVa | BATTERY CHANGING | CORRECTIVE MAINTENANCE | 30/07/2020 | | Corrective Order | WO Completed | Generator |
| 439258 | Hyster E70xn 3t Forklift (E) | BATTERY MAINTENANCE | PREVENTIVE MAINTENANCE | 26/08/2020 | 1176 hrs | Corrective Order | WO Completed | Forklift |
| 439263 | Hyster E70xn 3t Forklift (E) | BATTERY MAINTENANCE | PREVENTIVE MAINTENANCE | 26/08/2020 | | Corrective Order | WO Completed | Forklift |
| 439268 | Hyster E70xn 3t Forklift (E) | BATTERY MAINTENANCE | PREVENTIVE MAINTENANCE | 26/08/2020 | 2027hrs | Corrective Order | WO Completed | Forklift |
| 444164 | USP&E GP700S/V-A 700 kVa | BREAKDOWN | CORREAS ROTAS | 05/09/2020 | 34538 horas | Corrective Order | WO Completed | Generator |
| 445484 | PRAMAC GSW460V 460 kVa | BREAKDOWN | FALLO POR SOBRECARGA | 08/09/2020 | 24662 horas | Corrective Order | WO Completed | Generator |
| 448990 | PRAMAC GSW460V 460 kVa | BREAKDOWN | FALLO POR NO SINCRONISMO CON GS145 | 16/09/2020 | 24255 hours | Corrective Order | WO Completed | Generator |
| 392863 | Unimog Service Truck | CAB LIFT KIT INSTAL | CAB LIFT KIT INSTAL | 05/03/2020 | 70486.6 km | Corrective Order | WO Completed | Truck |
| 392864 | Unimog Service Truck | CAB LIFT KIT INSTAL | CAB LIFT KIT INSTAL | 05/03/2020 | 49856.5 hrs | Corrective Order | WO Completed | Truck |
| 392865 | Unimog Service Truck | CAB LIFT KIT INSTAL | CAB LIFT KIT INSTAL | 05/03/2020 | 54640 kms | Corrective Order | WO Completed | Truck |
| 392866 | Unimog Service Truck | CAB LIFT KIT INSTAL | CAB LIFT KIT INSTAL | 05/03/2020 | | Corrective Order | WO Completed | Truck |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 392868 | Unimog Service Truck | CAB LIFT KIT INSTAL | CAB LIFT KIT INSTAL | 05/03/2020 | 49676.2 kms | Corrective Order | WO Completed | Truck |
| 425685 | Mobile equipment | CABLE DE DIAGNOSTICO | HERRAMIENTA DE DIAGNOSTICO | 24/07/2020 | | Corrective Order | WO Completed | Area |
| 426858 | Mobile equipment | CABLES DE COMUNICACION GRUAS | HERRAMIENTAS DIAGNOSTICO | 28/07/2020 | | Corrective Order | WO Completed | Area |
| 453490 | JLG 1250 AJP Manlift | CALIBRACION DE TELESCOPICO | CALIBRACION DE TELESCOPICO | 26/09/2020 | | Corrective Order | WO Completed | Manlift |
| 424656 | GROVE GMK 5170 170TON | CALIBRACION DE TRANSMISION | CORRECTIVO | 21/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 434469 | Caterpillar 416F2 Backhoe | CAMBIO 1 LLANTA | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | Backhoe |
| 428278 | Coaster Bus | Cambio 2 baterias | CORRECTIVE MAINTENANCE | 03/08/2020 | | Corrective Order | WO Completed | Bus |
| 456162 | Gallegos 28M3 Lime Tank | Cambio 2 llantas | DESGASTE | 30/09/2020 | | Corrective Order | WO Ready to Schedule | Trailer / Flatbed / Lime |
| 434468 | GALLEGOS Lime Tank | Cambio 2 llantas | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 434467 | Freightliner M2 106 Sucker Tru | Cambio 2 llantas | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 412531 | Caterpillar D8T Dozer | Cambio 4 Baterias | DESCARGADAS POR TIEMPO | 30/05/2020 | 242 h | Corrective Order | WO Completed | Dozer |
| 432159 | Freightliner M2 106 Sucker Tru | CAMBIO 4 LLANTAS | DESGASTE | 14/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 434465 | Freightliner Columbia Cl112 | Cambio 8 llantas | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 432283 | Unimog Service Truck | CAMBIO ACEITE DE MOTOR | PREVENTIVO | 14/08/2020 | | Corrective Order | WO Completed | Truck |
| 425960 | Caterpillar 320DL | CAMBIO CILINDRO Y MOTOR GIRO | BACKLOG DESPUES DE INSPECCION | 25/07/2020 | 16809 hrs | Corrective Order | WO Completed | Excavator |
| 429682 | Hyster H300 Forklift | CAMBIO DE 1 NEUMATICO | CORRECTIVO | 07/08/2020 | | Corrective Order | WO Completed | Forklift |
| 444038 | Caterpillar 14H Motorgrader | CAMBIO DE 02 NEUMATICOS | CORRECTIVO | 05/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Grader |
| 456163 | GALLEGOS Lime Tank | Cambio de 1 llanta | DESGASTE | 30/09/2020 | | Corrective Order | WO Ready to Schedule | Trailer / Flatbed / Lime |
| 424453 | PB013 COASTER TOYOTA | CAMBIO DE 1 NEUMATICO | CAMBIO DE 1 NEUMATICO | 20/07/2020 | | Corrective Order | WO Completed | Bus |
| 424454 | PB016 COASTER TOYOTA | CAMBIO DE 1 NEUMATICO | CORRECTIVO | 20/07/2020 | | Corrective Order | WO Completed | Bus |
| 425539 | Gallegos Flatbed Trailer | CAMBIO DE 2 NEUMATICOS | CORRECTIVO | 24/07/2020 | | Corrective Order | W/O In Planning | Trailer / Flatbed / Lime |
| 428696 | Freightliner M2 112 Sucker Tru | Cambio de 2 llantas | MANTIENE 2 LLANTAS EN MAL ESTADO | 05/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 430916 | Freightliner Columbia Cl112 | Cambio de 2 llantas delanteras | LLANTAS DELANTERAS EN MAL ESTADO | 10/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 395794 | Hyster H700 Forklift | cambio de 2 llantas nuevas | CAMBIO DE LLANTAS NUEVAS | 11/03/2020 | | Corrective Order | WO Completed | Forklift |
| 418548 | Hyster H300 13t Forklift (M) | CAMBIO DE 2 NEUMATICOS | CORRECTIVO | 08/07/2020 | | Corrective Order | W/O In Planning | Forklift |
| 449214 | Coaster Bus | CAMBIO DE 2 NEUMATICOS | CORRECTIVO | 17/09/2020 | | Corrective Order | WO Ready to Schedule | Bus |
| 429070 | PB012 COASTER TOYOTA | CAMBIO DE 2 NEUMATICOS | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Bus |
| 427698 | Freightliner M2 112 Sucker Tru | CAMBIO DE 2 NEUMATICOS | CORRECTIVO | 01/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 435237 | WT013 H7 CISTERNA SINOTRUK | CAMBIO DE 2 NEUMATICOS | CORRECTIVE MAINTENANCE | 21/08/2020 | | Non-Planned Job Order | WO Completed | . |
| 444996 | PB013 COASTER TOYOTA | CAMBIO DE 4 NEUMATICOS | CORRECTIVO | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 443019 | Caterpillar 236d Skid Steer L | CAMBIO DE 4 NEUMATICOS | CORRECTIVO | 02/09/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 443006 | Caterpillar 226b Skid Steer L | CAMBIO DE 4 NEUMATICOS | CORRECTIVO | 02/09/2020 | 1895.4hrs | Corrective Order | WO Completed | Skid Steer |
| 422693 | Gallegos Flatbed Trailer | CAMBIO DE 5 NEUMATICOS | CORRECTIVO | 18/07/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 428719 | Freightliner M2 112 Sucker Tru | Cambio de 6 llantas | MANTIENE LAS 6 LLANTAS EN MUL MAL ES | 05/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 430621 | Freightliner Columbia Cl112 | Cambio de 6 llantas | MANTIENE LLANTAS EN MAL ESTADO, REQ | 09/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 431241 | Freightliner Columbia Cl112 | Cambio de 6 llantas delanteras | MANTIENE SEIS LLANTAS EN MAL ESTADO | 11/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 430772 | Caterpillar 735B ADT | CAMBIO DE 6 NEUMATICOS | POSICION 1-2-3-4-5-6 | 09/08/2020 | 24131.7hrs | Corrective Order | WO Completed | Articulated dump truck |
| 446186 | Freightliner Columbia Cl112 | cambio de 8 llantas | CAMBIO DE 8 LLANTAS DANADAS | 10/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 440593 | John Deere 310K | CAMBIO DE ACEITE | MANTENIMIENTO PREVENTIVO | 28/08/2020 | | Corrective Order | WO Completed | Backhoe |
| 440589 | Phoenix MK7T | CAMBIO DE ACEITE | MANTENIMIENTO PREVENTIVO | 28/08/2020 | | Corrective Order | WO Completed | . |
| 439785 | Caterpillar 735B ADT | CAMBIO DE ACEITE Y FILTRO | MANTENCION PREVENTIVO | 27/08/2020 | 24131.7hrs | Corrective Order | WO Completed | Articulated dump truck |
| 446007 | Caterpillar 226b Skid Steer L | CAMBIO DE ACEITE Y FILTRO | MANTENIMIENTO PREVENTIVO | 09/09/2020 | 1070 kms | Corrective Order | WO Completed | Skid Steer |
| 449314 | Freightliner 8170ME Water Truc | CAMBIO DE ACEITE Y FILTRO | MANTENIMIENTO PREVENTIVO | 17/09/2020 | | Corrective Order | W/O In Planning | Water truck |
| 440602 | Caterpillar 416E | CAMBIO DE ACEITE Y FILTROS | MANTENIMIENTO PRENVENTIVO | 28/08/2020 | 909.0 hrs | Corrective Order | WO Completed | Backhoe |
| 428272 | Coaster Bus | CAMBIO DE BANDAS | CORRECTIVE MAINTENANCE | 03/08/2020 | | Corrective Order | WO Completed | Bus |
| 428961 | Caterpillar 12M Motorgrader | CAMBIO DE BATERIA | BATERIA NO RETIENEN CARGA | 06/08/2020 | | Corrective Order | WO Completed | Grader |
| 448086 | PB016 COASTER TOYOTA | CAMBIO DE BATERIA | CORRECTIVO BATERIA MAL ESTADO | 15/09/2020 | | Corrective Order | WO Completed | Bus |
| 425670 | JLG 1250 AJP Manlift | CAMBIO DE BATERIA | CORRETIVO | 24/07/2020 | | Corrective Order | WO Completed | Manlift |
| 425672 | JLG 1250 AJP Manlift | CAMBIO DE BATERIA | CORRECTIVO | 24/07/2020 | | Corrective Order | WO Completed | Manlift |
| 439274 | Case 110JX Tractor Cable Handl | cambio de bateriads | BATERIAS DANADAS | 26/08/2020 | | Corrective Order | WO Completed | Tractor |
| 428971 | Caterpillar D8T Dozer | CAMBIO DE BATERIAS | REQUIERE CAMBIO DE BATERIAS | 06/08/2020 | | Corrective Order | W/O In Planning | Dozer |
| 445854 | Caterpillar 14H Motorgrader | CAMBIO DE BATERIAS | EQUIPO NO ARRANCA | 09/09/2020 | | Corrective Order | WO Completed | Grader |
| 441222 | MG012 16H CAT | CAMBIO DE BATERIAS | BATERIAS EN MAL ESTADO | 29/08/2020 | | Corrective Order | WO Completed | Grader |
| 425673 | JLG 1250 AJP Manlift | CAMBIO DE BATERIAS | CORRECTIVO | 24/07/2020 | 4722 hrs | Corrective Order | WO Completed | Manlift |
| 419007 | Manitou Mht-X860 6t Telehand | Cambio de bomba | CORRECTIVO | 10/07/2020 | | Corrective Order | WO Completed | Telehender |
| 412972 | Grove RT650E 45TON | CAMBIO DE BOMBA DE AGUA | CORRECTIVO BACKLOG | 02/06/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 412971 | Grove RT700E 60TON | CAMBIO DE BOMBA DE AGUA | CORRECTIVO BACKLOG | 02/06/2020 | 1762.3hrs | Corrective Order | WO Completed | Crane/Hoist |
| 425460 | Freightliner M2 106 Sucker Tru | CAMBIO DE BOMBA DE AGUA | CORRECTIVO | 24/07/2020 | | Corrective Order | WO Completed | Sucker truck |
| 439779 | Caterpillar C9 250 kVa | CAMBIO DE BOMBA DE INJECCION | CORRECTIVO | 27/08/2020 | 13952 horas | Corrective Order | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 426627 | Freightliner M2 106 Sucker Tru | CAMBIO DE BOMBA DE SUCCION | CORRECTIVO | 27/07/2020 | | Corrective Order | W/O In Planning | Sucker truck |
| 429083 | Caterpillar 740B EJ ADT | Cambio de bomba de trasmision | BOMBA DE TRASMISION DEFECTUOSA, | 06/08/2020 | 24378.7 | Corrective Order | WO Completed | Articulated dump truck |
| 435704 | Caterpillar 226b Skid Steer L | Cambio de bombillos | CAMBIO DE BOMILLOS | 22/08/2020 | 1813.4hrs | Corrective Order | WO Completed | Skid Steer |
| 426751 | Freightliner 8170ME Water Truc | CAMBIO DE CAPO | CORRECTIVO POR DAÃ'O | 28/07/2020 | | Corrective Order | WO Ready to Schedule | Water truck |
| 428763 | Caterpillar 426f2 Backhoe | Cambio de casquillos de balde | CASQUILLO DE BALDE DESGASTADOS | 05/08/2020 | | Corrective Order | WO Completed | Backhoe |
| 411115 | Hyster H300 13t Forklift (M) | CAMBIO DE CILINDROS | DAÃ'O EN CILINDRO | 20/05/2020 | 1375hrs | Corrective Order | WO Completed | Forklift |
| 419239 | Freightliner M2 106 Sucker Tru | CAMBIO DE COMPONENTES | DAÃ'O EN FRENOS | 12/07/2020 | | Corrective Order | W/O In Planning | Sucker truck |
| 421892 | Tennant T7 Scrubber | CAMBIO DE COMPONENTES | CORRECTIVO | 14/07/2020 | | Corrective Order | W/O In Planning | Scrubber / Sweeper |
| 431515 | Caterpillar 320DL Excavator | Cambio de correa A/A | AIRE ACONDICIONADO NO FUNCIONA | 12/08/2020 | | Corrective Order | WO Completed | Excavator |
| 422298 | Caterpillar 236d Skid Steer L | CAMBIO DE CORREA ALTERNADOR | CORRECTIVO | 16/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 419008 | JLG 800 AJ Manlift | CAMBIO DE CORREA DE ALTERNADOR | CORRECTIVO | 10/07/2020 | | Corrective Order | W/O In Planning | Manlift |
| 431247 | Freightliner Boom Truck | cambio de correa de motor | CORREA DE MOTOR ROTA | 11/08/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| 441661 | Caterpillar 226b Skid Steer L | cambio de correa de motor | CORRECTIVO | 30/08/2020 | | PLANNED JOB | WO Completed | Skid Steer |
| 428897 | Caterpillar 14M Motorgrader | CAMBIO DE CUCHILLA | CUCHILLAS EN MAL ESTADO | 06/08/2020 | | Corrective Order | WO Completed | Grader |
| 424573 | Caterpillar 236d Skid Steer L | CAMBIO DE CUCHILLA | CORRECTIVO | 21/07/2020 | 2183.7 hrs | Corrective Order | WO Completed | Skid Steer |
| 428281 | Coaster Bus | CAMBIO DE ESCOLTA | CORRECTIVE MAINTENANCE | 03/08/2020 | | Corrective Order | WO Completed | Bus |
| 402892 | Freightliner Columbia Cl112 | CAMBIO DE ESPEJOS | CORRECTIVO | 28/03/2020 | 29403.6rs | Corrective Order | WO Completed | Truck |
| 402904 | Freightliner Columbia Cl112 | CAMBIO DE ESPEJOS | CORRECTIVO | 28/03/2020 | 21965.6 hrs | Corrective Order | WO Completed | Truck |
| 438673 | Cargador 966H Wheel Loader | cambio de filtro aceite hidrau | CAMBIO DE FILTRO DE ACEITE HIDRAULIC | 26/08/2020 | | Corrective Order | WO Completed | Loader |
| 446283 | PB002 COASTER TOYOTA | CAMBIO DE FILTRO DE DIESEL | CAMBIO DE FILTRO DE DIESEL | 10/09/2020 | | Corrective Order | WO Completed | Bus |
| 418412 | John Deere 9370R Tractor | CAMBIO DE FILTRO HIDRAULICO | CORRECTIVO | 08/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Tractor |
| 433238 | Shuttlelift RTCD5540F 15TON | CAMBIO DE FILTRO HIDRAULICO | CORRECTIVO | 16/08/2020 | AUTO CLOSED | Corrective Order | WO Completed | Crane/Hoist |
| 451325 | USP&E GP700/V-A 700 kVa | CAMBIO DE GENERADOR | DESCONECCION & MOVIMIENTO DE GENER | 21/09/2020 | 10185 horas | Corrective Order | WO Completed | Generator |
| 447687 | Freightliner M2 106 Refrigerat | CAMBIO DE LLANTAS DELANTERAS | CAMBIO LLANTAS | 14/09/2020 | | Corrective Order | WO Completed | Refrigerator truck |
| 422562 | Caterpillar 226b Skid Steer L | CAMBIO DE MANGUERA RADIADOR | CORRECTIVO | 17/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 428721 | Cargador 966H Wheel Loader | Cambio de para Brisas | MANTIENE VIDRIO LIMPIA BRISA ROTO | 05/08/2020 | | Corrective Order | WO Completed | Loader |
| 428346 | Cargador 966H Wheel Loader | CAMBIO DE PARABRISA | CORRECTIV | 03/08/2020 | | Corrective Order | WO Completed | Loader |
| 440404 | Internation F2674 | CAMBIO DE PARABRISAS | CORRECTIVO | 28/08/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 419085 | Caterpillar 226b Skid Steer L | CAMBIO DE PEDAL | CORRECITVO | 11/07/2020 | 1070 kms | Corrective Order | WO Completed | Skid Steer |
| 449307 | Cargador 966H Wheel Loader | CAMBIO DE PERNOS | CAMBIO DE PERNOS | 17/09/2020 | | Corrective Order | WO Ready to Schedule | Loader |
| 428980 | Caterpillar 740B EJ ADT | Cambio de pernos de carroceria | CARROCERIA DELANTERA DERECHA SUELTA | 06/08/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 454242 | Caterpillar 236d Skid Steer L | Cambio de pines y bujes | CAMBIO DE PINES Y BUJES | 28/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 453208 | Freightliner M2 106 Sucker Tru | Cambio de radiador y bases | CAMBIO DE RADIADOR Y ASES DE RADIADO | 26/09/2020 | | Corrective Order | WO Ready to Schedule | Sucker truck |
| 425443 | Caterpillar 236d Skid Steer L | CAMBIO DE RODAMIENTO | CORRECTIVO | 24/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 422243 | Caterpillar 320DL | CAMBIO DE ROLLER | CORRECTIVO | 16/07/2020 | 16809hrs | Corrective Order | WO Completed | Excavator |
| 443301 | Unimog Service Truck | Cambio de sensor | RETIRAR 60012206 | 03/09/2020 | 106411.1 kms | Corrective Order | WO Completed | Truck |
| 438009 | Case 110JX Tractor Cable Handl | Cambio de swith ignicion | FALLA ELECTRICA | 24/08/2020 | | Corrective Order | WO Ready to Schedule | Tractor |
| 432536 | Caterpillar 226b Skid Steer L | CAMBIO DE VIDRIO FRONTAL | CORRECTIVO | 15/08/2020 | AUTO CLOSED | Corrective Order | WO Completed | Skid Steer |
| 447427 | Caterpillar 226b Skid Steer L | CAMBIO DE VIDRIO Y NEUMATICOS | CAMBIO DE VIDRIO Y NEUMATICOS | 13/09/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 443744 | FG WILSON P88-3 80 kVa | CAMBIO DE VOLTAGE & INTALACION | REEMPLAZO DE GENERADOR | 04/09/2020 | 16420 hours | Corrective Order | WO Completed | Generator |
| 433829 | Caterpillar 236d Skid Steer L | cambio filtro combustible | SATURADO | 17/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 453739 | Caterpillar 735B ADT | Cambio fltros Hyd | SATURADOS | 27/09/2020 | | Corrective Order | WO Ready to Schedule | Articulated dump truck |
| 428427 | Caterpillar 416F2 Backhoe | CAMBIO GETS | DESGASTE | 04/08/2020 | | Corrective Order | WO Ready to Schedule | Backhoe |
| 434551 | WT014 H7 CISTERNA SINOTRUK | Cambio llanta P1 | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | . |
| 434499 | WT014 H7 CISTERNA SINOTRUK | Cambio llanta P1 | DESGASTE | 19/08/2020 | | Corrective Order | WO Completed | . |
| 432019 | Mercedes Tipper Truck | Cambio manguera HYD freno | FUGA | 14/08/2020 | | Corrective Order | WO Ready to Schedule | Tipper |
| 448869 | Caterpillar 226b Skid Steer L | Cambio Parabriza Delt | ROTURA | 16/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 431734 | Caterpillar 740B EJ ADT | Cambio pernos | ROTURA | 13/08/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 444958 | MG012 16H CAT | CAMBIO POS 3 | CORTE EN LA BANDA | 07/09/2020 | | Corrective Order | WO Completed | Grader |
| 423494 | Caterpillar 226b Skid Steer L | CAMBIO SENSOR TEMPERATURA | CORRECTIVO | 19/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 438002 | Case 110JX Tractor Cable Handl | Cambio sicht arranque | FALLA INTERNA | 24/08/2020 | 2592.1hrs | Corrective Order | WO Completed | Tractor |
| 438012 | Case 110JX Tractor Cable Handl | Cambio swith arranque | FALLA ELECTRICA | 24/08/2020 | | Corrective Order | WO Completed | Tractor |
| 433825 | Caterpillar D8T Dozer | CAMBIO VALVULA DRENAJE ACEITE | FUGA | 17/08/2020 | | Corrective Order | WO Ready to Schedule | Dozer |
| 444833 | MG012 16H CAT | CAMBO DE ESCOBILLA WIPER | CAMBIO DE ESCOBILLA WPER | 07/09/2020 | | Corrective Order | WO Completed | Grader |
| 434457 | LT025 QLT-M10 ATLAS | CHANGE BATTERY | CHANGE BATTERY | 19/08/2020 | | Corrective Order | WO Completed | Light Tower |
| 434484 | LT064 QLT-M10 ATLAS | CHANGE BATTERY | CHANGE BATTERY | 19/08/2020 | 4062 horas | Corrective Order | WO Completed | Light Tower |
| 434485 | LT104 D1005 DOOSAN | CHANGE BATTERY | CHANGE BATTERY | 19/08/2020 | | Corrective Order | WO Completed | Light Tower |
| 395690 | Unimog Service Truck | CHANGE BRAKE PAD | CORRECTIVO MPSA | 11/03/2020 | 70484.8kms | Corrective Order | WO Completed | Truck |
| 395689 | Unimog Service Truck | CHANGE BRAKE PAD | CORRECTIVO MPSA | 11/03/2020 | | Corrective Order | WO Completed | Truck |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 443302 | Unimog Service Truck | CHANGE BRAKE PAD | RETIRAR PO 60012206 | 03/09/2020 | 106411.1 kms | Corrective Order | WO Completed | Truck |
| 378451 | Caterpillar 14M Motorgrader | CHANGE GLASS & WIN MOTOR | CHANGE GLASS & WIN MOTOR | 07/02/2020 | | Corrective Order | WO Ready to Schedule | Grader |
| 443580 | Caterpillar 320DL Excavator | Check Air conditioner | CHECK AIR CONDITIONER | 04/09/2020 | 2099.6hrs | Corrective Order | WO Completed | Excavator |
| 437995 | Caterpillar 226b Skid Steer L | Check charging system | CHECK CHARGING SYSTEM | 24/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 426717 | PRAMAC GSW460V 460 kVa | check high temperature | CHECK HIGH TEMPERATURE | 28/07/2020 | 23 133 | Corrective Order | WO Completed | Generator |
| 428083 | Mobile equipment | Collect Last PM information | CURRENT HOUR METER | 02/08/2020 | | Corrective Order | WO Completed | Area |
| 443238 | Caterpillar | Complete inspection | COMPLETE INSPECTION | 03/09/2020 | | Corrective Order | WO Completed | . |
| 445759 | Caterpillar C9 250 kVa | CONECCION & CAMBIO DE VOLTAGE | CAMBIO DE VOLTGE, CONECCION & ARRAI | 09/09/2020 | 15995 horas | Corrective Order | WO Completed | Generator |
| 447144 | JLG 1250 AJP Manlift | conector de manguera danado | SOLICITUD DE CONECTOR DE MANGUERA | 12/09/2020 | | Corrective Order | WO Completed | Manlift |
| 448171 | Mobile equipment | CONSUMIBLES AGOSTO | REPARACION DE NEUMATICO KALTIRE | 15/09/2020 | | Corrective Order | WO Completed | Area |
| 438555 | Mobile equipment | CONSUMIBLES PARA TALLER | LAMPARAS H7, 24V | 25/08/2020 | | Corrective Order | WO Completed | Area |
| 451418 | JLG 1250 AJP Manlift | Correa de alternador Rota | CORREA DE ALTERNADOR ROTA | 22/09/2020 | | Corrective Order | WO Ready to Schedule | Manlift |
| 443750 | Caterpillar 236d Skid Steer L | correas rotas | CAMBIO DE CORREAS DE COMPRESOR | 04/09/2020 | 2264.1 hrs | Corrective Order | WO Completed | Skid Steer |
| 432492 | Grove RT700E 60TON | Corrective maintenace | CHANGE PARTS, SEE ATTACHEMENTS | 15/08/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 427869 | Freightliner M2 106 Refrigerat | Defenza caida | DEFENZA CAIDA | 02/08/2020 | | Corrective Order | WO Completed | Refrigerator truck |
| 431649 | Internation 4400 SBA 6x4 Boom | DESINTALAR COMPUTADORA | DESINTALAR COMPUTADORA | 13/08/2020 | | Corrective Order | WO Completed | Boom truck |
| 453037 | Caterpillar 226b Skid Steer L | DESMONTAR HUB | DESMONTAR HUB | 25/09/2020 | | Corrective Order | WO Ready to Schedule | Skid Steer |
| 430855 | Caterpillar 740B EJ ADT | DESMONTAR PERNOS DE LA CARROCE | DESMONTAR PERNOS DE LA CARROCE | 10/08/2020 | | Corrective Order | WO Ready to Schedule | Articulated dump truck |
| 425914 | Mobile equipment | DEVOLUCION DE PARTES | RETORNO | 25/07/2020 | | Corrective Order | WO Completed | Area |
| 394451 | Caterpillar 14M Motorgrader | DIFFERENCIAL REPAIR | DIFFERENCIAL REPAIR | 09/03/2020 | | Corrective Order | WO Ready to Schedule | Grader |
| 435879 | Caterpillar 236d Skid Steer L | Do corrective repairs. | DO CORRECTIVE REPAIRS. | 23/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 424299 | GS157 MMG80 MAGNUM | ECU replacement | NEED PARTS INFO!!!! | 20/07/2020 | | Corrective Order | W/O In Planning | Generator |
| 416802 | Olympian GEP 88-3 64 kVa | ELECTRICAL INSPECTION & PMS | PUMP CHECK & OIL AND FILTER REPLACEMI | 27/06/2020 | 20392 horas | Corrective Order | WO Completed | Generator |
| 435902 | Caterpillar 226b Skid Steer L | Engine cutting out | ENGINE CUTTING OUT | 23/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 435904 | Caterpillar 226b Skid Steer L | Engine cutting out | ENGINE CUTTING OUT | 23/08/2020 | 1052 hrs | Corrective Order | WO Completed | Skid Steer |
| 435905 | Caterpillar 226b Skid Steer L | Engine cutting out | ENGINE CUTTING OUT | 23/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 453033 | Unimog Service Truck | ENGINE MECHANICAL INSPECTION | INSPECTION | 25/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Truck |
| 443065 | John Deere 9370R Tractor | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 2004 hrs | Corrective Order | WO Completed | Tractor |
| 443064 | Caterpillar 14M Motorgrader | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | Inoperativo, sin l | Corrective Order | WO Completed | Grader |
| 443050 | JLG 450 AJ Manlift | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 4290.1 hrs | Corrective Order | WO Completed | Manlift |
| 443049 | JLG 450 AJ Manlift | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 4028.7 hrs | Corrective Order | WO Completed | Manlift |
| 443053 | JLG 800 AJ Manlift | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 5834.2 hrs | Corrective Order | WO Completed | Manlift |
| 443054 | JLG 1250 AJP Manlift | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 6052.5 hrs | Corrective Order | WO Completed | Manlift |
| 443055 | JLG 1250 AJP Manlift | EQUIPMENT REVISION | MECHANICAL INSPECTION | 02/09/2020 | 4721.1 hrs | Corrective Order | WO Completed | Manlift |
| 453044 | Caterpillar 307E Miniexcavator | Equipo con fuga hidraulica | EQUIPO CON FUGA HIDRAULICA | 25/09/2020 | | Corrective Order | WO Completed | Excavator |
| 451303 | Caterpillar 426f2 Backhoe | EQUIPO FLAT | EQUIPO FLAT | 21/09/2020 | | Corrective Order | WO Completed | Backhoe |
| 452502 | Intraax 53121 Hendrickso | EQUIPO FLAT | EQUIPO FLAT | 24/09/2020 | | Corrective Order | WO Ready to Schedule | Trailer / Flatbed / Lime |
| 450912 | Manitou Mht-X860 6t Telehand | EQUIPO FLAT | EQUIPO FLAT | 20/09/2020 | | Corrective Order | WO Completed | Telehender |
| 451284 | Freightliner Columbia Cl112 | EQUIPO FLAT | EQUIPO FLAT | 21/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 451287 | Freightliner Columbia Cl112 | EQUIPO FLAT | EQUIPO FLAT | 21/09/2020 | | Corrective Order | WO Ready to Schedule | Mule truck |
| 446484 | Coaster Bus | EQUIPO NO ARRANCA | CAMBIO DE MOTOR DE ARRANQUE | 11/09/2020 | 9776.7 kms | Corrective Order | WO Completed | Bus |
| 427134 | Manitou MHT10180L Telehandler | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 30/07/2020 | | Corrective Order | WO Completed | Telehender |
| 450906 | TH017 LM 1745 New Holland | EQUIPO NO ARRANCA | EQUIPO NO ARRANCA | 20/09/2020 | | Corrective Order | WO Completed | . |
| 447430 | Unimog Service Truck | EQUIPO NO ARRANCA | MOTOR DE ARRANQUE DANADO | 13/09/2020 | | Corrective Order | WO Completed | Truck |
| 432531 | Mercedes Tipper Truck | EQUIPO NO AVANZA | EQUIPO NO AVANZA | 15/08/2020 | | Corrective Order | WO Ready to Schedule | Tipper |
| 449963 | Samil Boom Truck | EQUIPO NO ENCIENDE | EQUIPO NO ENCIENDE | 18/09/2020 | | Corrective Order | WO Completed | Boom truck |
| 452258 | Coaster Bus | EQUIPO NO ENCIENDE | REVISION DE SISTEMA ELECTRICO | 23/09/2020 | 1647 kms | Corrective Order | WO Completed | Bus |
| 446459 | Coaster Bus | EQUIPO NO ENCIENDE | BATERIAS DESCARGADAS | 11/09/2020 | 29734.1 kms | Corrective Order | WO Completed | Bus |
| 454102 | Freightliner Cl 120 | EQUIPO NO ENCIENDE | REVISAR SISTEMA DE ARRANQUE | 28/09/2020 | 285467.3 kms | Corrective Order | WO Ready to Schedule | Mule truck |
| 452612 | Caterpillar 236d Skid Steer L | EQUIPO PIERDE FUERZA | EQUIPO PIERDE FUERZA | 24/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 449895 | Caterpillar 236d Skid Steer L | EQUIPO PIERDE FUERZA | EQUIPO PIERDE FUERZA | 18/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 453205 | Caterpillar CS74 Compactor | EQUIPO PIERDE FUERZA | REVISAR SISTEMA ELECTRICO | 26/09/2020 | | Corrective Order | WO Ready to Schedule | Compactor |
| 428545 | Manitou Mht-X860 6t Telehand | EQUIPO SE BLOQUEA | EQUIPO SE BLOQUEA | 05/08/2020 | | Corrective Order | WO Completed | Telehender |
| 452400 | Cargador 966H Wheel Loader | Equipo se recalienta | SE INSPECCIONA RADIADOR ROTO | 24/09/2020 | | Corrective Order | WO Ready to Schedule | Loader |
| 450908 | Caterpillar 426f2 Backhoe | ERVISION DE EQUIPO | ERVISION DE EQUIPO | 20/09/2020 | | Corrective Order | WO Completed | Backhoe |
| 431107 | Cargador 966H Wheel Loader | ESCALERA EN MAL ESTADO | ESCALERA EN MAL ESTADO | 11/08/2020 | | Corrective Order | WO Completed | Loader |
| 425975 | Caterpillar 336DL Excavator | EVALAUR AIRE ACONCIONADO | INSPECCION | 25/07/2020 | 17619hrs | Corrective Order | WO Completed | Excavator |
| 425949 | Magni HTH 10,10 Telehandler | EVALUAR BATERIA Y EQUIPO | INSPECCION | 25/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Telehender |
| 419009 | JLG 800 AJ Manlift | EVALUAR PEDAL ACELERADOR | MECHANICAL INSPECTION | 10/07/2020 | 5098.6 hrs | Corrective Order | WO Completed | Manlift |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 416805 | Olympian GEP 110-4 80 kVa | EVALUATE DAMGES | DAMAGED GUARD | 27/06/2020 | 24439 HORAS | Corrective Order | WO Completed | Generator |
| 424576 | Grove RT700E 60TON | FABRICACION 8 MANGUERA HIDRAUL | CORRECTIVO | 21/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 428606 | Caterpillar 426f2 Backhoe | FABRICACION DE 1 MANGUERA | FABRICACION DE 1 MANGUERA | 05/08/2020 | | Corrective Order | WO Completed | Backhoe |
| 431789 | Manitou Mht-X1490 9t Telehand | FABRICACION DE 1 MANGUERA | CORRECTIVO | 13/08/2020 | | Corrective Order | WO Completed | Telehender |
| 430282 | Caterpillar 12M Motorgrader | Fabricacion de 4 mangueras | MANTIENE MANGUERAS EN MAL ESTADO, I | 08/08/2020 | | Corrective Order | WO Completed | Grader |
| 418406 | Grove RT650E 45TON | FABRICACION DE MANGUERA | CORRECTIVO CEMAN | 08/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 429574 | Grove RT700E 60TON | FABRICACION DE MANGUERA | MANGUERA DEFECTUOSA | 07/08/2020 | 1755.8 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 424620 | Caterpillar 336DL Excavator | FABRICACION DE MANGUERA | CORRECTIVO | 21/07/2020 | | Corrective Order | WO Completed | Excavator |
| 430181 | JLG 800 AJ Manlift | Fabricacion de mangueras | MANGUERAS DEFECTUOSAS | 08/08/2020 | | Corrective Order | WO Completed | Manlift |
| 421776 | JLG 1250 AJP Manlift | Fabricacion de mangueras | FABRICACION DE MANGUERAS | 14/07/2020 | | Corrective Order | WO Completed | Manlift |
| 452365 | Caterpillar 12M | Fabricacion de Niples | FABRICACION DE NIPLES DE MANGUERAS N | 24/09/2020 | | Corrective Order | WO Completed | Grader |
| 435488 | Freightliner M2 106 Truck | FALLA INTERMINTENTE DEL BOOM | CORRECTIVO | 22/08/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 434030 | Caterpillar 236d Skid Steer L | Fallo de combustible | FALLO DE COMBUSTIBLE | 18/08/2020 | | Corrective Order | WO Ready to Schedule | Skid Steer |
| 447930 | Manitou Mht-X860 6t Telehand | Fuga de aceite hidraulico | CAMBIO DE MOTOR DEL VENTILADOR MOT | 15/09/2020 | | Corrective Order | WO Ready to Schedule | Telehender |
| 450856 | Grove RT9130E 120TON | FUGA HIDRAULICA | FUGA HIDRAULICA | 20/09/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 432281 | Caterpillar 740B EJ ADT | FUGA HIDRAULICA | FUGA HIDRAULICA | 14/08/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 450156 | JLG 1250 AJP Manlift | FUGA HIDRAULICA | FUGA HIDRAULICA | 19/09/2020 | | Corrective Order | WO Completed | Manlift |
| 449939 | TH017 LM 1745 New Holland | FUGA HIDRAULICA | FUGA HIDRAULICA | 18/09/2020 | | Corrective Order | WO Completed | . |
| 451304 | TH017 LM 1745 New Holland | FUGA HIDRAULICA | FUGA HIDRAULICA | 21/09/2020 | | Corrective Order | WO Ready to Schedule | . |
| 455774 | Grove RT9130E 120TON | FUGA HIDRAULICA, manguera | FUGA HIDRAULICA, CAMB MANGUERA | 29/09/2020 | | Corrective Order | WO Ready to Schedule | Crane/Hoist |
| 454081 | GALLEGOS Lime Tank | Fuga por tapa de inspeccion | SE REPARA FUGA | 28/09/2020 | N/A | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 454087 | Freightliner Cl 120 | Fuga por valvulas de aire | FUGA POR VALVULA DE AIRE | 28/09/2020 | 164414.9 kms | Corrective Order | WO Completed | Mule truck |
| 431914 | Caterpillar CS74 Compactor | fugas de aceite Hidraulica | FUGAS DE ACEITE HIDRAULICA | 14/08/2020 | | Corrective Order | WO Completed | Compactor |
| 441398 | Mobile equipment | GAS PARA AIRE ACONDICIONADO | CORRECTIVO | 29/08/2020 | | Corrective Order | WO Completed | Area |
| 447511 | Gallegos Flatbed Trailer | GENERAL INSPECTION | RIGHT LIGHT BROKEN - 2 MISSING NUTS - LI | 13/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 443895 | Mobile equipment | GRASA PARA TALLER | INSUMOS PARA TALLER TACTICO | 05/09/2020 | | Corrective Order | W/O In Planning | Area |
| 412059 | Caterpillar 336DL Excavator | GRIETA EN BRAZO PRINCIPAL | GRIETA EN BRAZO PRINCIPAL | 27/05/2020 | | Corrective Order | WO Completed | Excavator |
| 431554 | Mobile equipment | Herramientas Taller | HERRAMIENTA DIAGNOSTICO | 12/08/2020 | | Corrective Order | W/O In Planning | Area |
| 444360 | Caterpillar 140K | Hoja de cuchilla danada | HOJA DE CUCHILLA DANADA | 05/09/2020 | | Corrective Order | WO Completed | Grader |
| 452623 | Internation 4400 SBA 6x4 Boom | HOOD PACKAGING AND MEASURING | HOOD PACKAGING AND MEASURING | 24/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Boom truck |
| 452622 | Freightliner M2 106 Sucker Tru | HOOD PACKAGING AND MEASURING | HOOD PACKAGING AND MEASURING | 24/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Sucker truck |
| 445077 | Caterpillar 740B EJ ADT | HOSE CHANGING | CORRECTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 432332 | Mobile equipment | HOUSEKEEPING WORK SHOP | PREVENTIVE | 15/08/2020 | | Corrective Order | WO Completed | Area |
| 451104 | Caterpillar CS533E Compactor | IDENTIFICACION DE FUGA HIDRAUL | IDENTIFICACION DE FUGA HIDRAUL | 21/09/2020 | | Corrective Order | WO Ready to Schedule | Compactor |
| 431415 | John Deere 9370R Tractor | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 12/08/2020 | | Corrective Order | WO Completed | Tractor |
| 450909 | Caterpillar 426f2 Backhoe | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 20/09/2020 | | Corrective Order | WO Completed | Backhoe |
| 428154 | Hyster E70xn 3t Forklift (E) | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 03/08/2020 | | Corrective Order | WO Completed | Forklift |
| 429787 | Caterpillar 12M Motorgrader | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 08/08/2020 | | Corrective Order | WO Completed | Grader |
| 432534 | Caterpillar 236d Skid Steer L | INSPECCION DE EQUIPO | INSPECCION DE EQUIPO | 15/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 451790 | Grove RT600E 50TON | INSPECCION DE GRUA | INSPECCION DE GRUA | 22/09/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 446343 | Freightliner Cl 120 | INSPECCION DE RADIADOR | EVALUACION MECANICA | 10/09/2020 | Requiere cambic | Corrective Order | WO Completed | Mule truck |
| 446340 | Freightliner Cl 120 | INSPECCION DE RADIADOR | EVALAUCION MECANICA | 10/09/2020 | 138811.90 kms | Corrective Order | WO Completed | Mule truck |
| 446341 | Freightliner Cl 120 | INSPECCION DE RADIADOR | EVALAUCION MECANICA | 10/09/2020 | 12227 kms | Corrective Order | WO Completed | Mule truck |
| 431563 | Mobile equipment | Inspeccion equipos carretera | SE INSPECCIONAN EQUIPOS DE CARRETERA | 12/08/2020 | | Corrective Order | WO Completed | Area |
| 450463 | Grove RT880E 75TON | INSPECCION FUGA DE REFRIGERANT | INSPECCION FUGA DE REFRIGERANT | 19/09/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 448974 | PB002 COASTER TOYOTA | INSPECCION GENERAL | INSPECCION GENERAL PARA ALISTAMIENTC | 16/09/2020 | 286.248 | Corrective Order | WO Completed | Bus |
| 446334 | Freightliner Cl 120 | INSPECCION GENERAL | REVISAR CONDICION OPERATIVA | 10/09/2020 | 384198 | Corrective Order | WO Completed | Mule truck |
| 419206 | WT013 H7 CISTERNA SINOTRUK | INSPECCION GENERAL | PREVENTIVO | 11/07/2020 | | Corrective Order | WO Completed | . |
| 419207 | WT014 H7 CISTERNA SINOTRUK | INSPECCION GENERAL | PREVENTIVO | 11/07/2020 | | Corrective Order | WO Completed | . |
| 419208 | WT015 H7 CISTERNA SINOTRUK | INSPECCION GENERAL | PREVENTIVO | 11/07/2020 | | Corrective Order | WO Completed | . |
| 446350 | Gallegos 28M3 Lime Tank | Inspeccion mecanica | EVALAUCION MECANICA | 10/09/2020 | N/A | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 446353 | Freightliner Cl 120 | Inspeccion mecanica | EVALUACION MECANICA | 10/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 446376 | Freightliner Cl 120 | Inspeccion mecanica | EVALUACION MECANICA | 10/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 446377 | Freightliner Cl 120 | Inspeccion mecanica | EVALUACION MECANICA | 10/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 425942 | JLG 1250 AJP Manlift | INSPECCION POR DAÃ±O EQUIPO | INSPECCION | 25/07/2020 | | Corrective Order | WO Completed | Manlift |
| 425945 | GROVE GMK 5170 170TON | inspeccion y evaluacion daÃ±o | INSPECCION | 25/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 443585 | International 7400 SBA Fire Tr | iNSPECT AIR CONDITIONER | INSPECT AIR CONDITIONER | 04/09/2020 | 12010hrs | Corrective Order | WO Completed | Fire truck |
| 416796 | SDMO T11UM 10 kVa | INSPECTION & REVIEW | PREVENTIVE MAINTENANCE | 27/06/2020 | 6329 HORAS | Corrective Order | WO Completed | Generator |
| 454383 | Manitou Mht-X1490 9t Telehand | INSTA;LACION DE MANGUERA HIDRA | INSTA;LACION DE MANGUERA HIDRA | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Telehender |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 435259 | Terex RT670 64TON | INSTALACION 3 CILINDROS | CORRECTIVO GARANTIA | 21/08/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 431417 | Freightliner M2 106 Sucker Tru | Instalacion de bandas de freno | INSTALACION DE BANDAS DE FRENO | 12/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 435257 | Internation F2674 | INSTALACION DE CILINDRO | CRORRECTIVO POR GARANTIA | 21/08/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 450490 | Manitou Mht-X1490 9t Telehand | INSTALACION DE MANGUERA DEL TU | INSTALACION DE MANGUERA DEL TU | 19/09/2020 | | Corrective Order | WO Completed | Telehender |
| 419214 | BT019 345 IVECO GRUA 6X6 | INSTALACION DE MANGUERAS | CAMBIO MANGUERAS FABRICADAS | 11/07/2020 | 19908 HRS | Corrective Order | WO Completed | . |
| 452064 | Intraax 53121 Hendrickso | INSTALACION DE PERNOS | INSTALACION DE PERNOS | 23/09/2020 | | Corrective Order | WO Ready to Schedule | Trailer / Flatbed / Lime |
| 453481 | Caterpillar 336DL Excavator | INSTALACION DE SENSOR DE COMBU | INSTALACION DE SENSOR DE COMBU | 26/09/2020 | | Corrective Order | WO Completed | Excavator |
| 431968 | Unimog Service Truck | INSTALACION DE TAPA DE MOTOR | INSTALACION DE TAPA DE MOTOR | 14/08/2020 | | Corrective Order | WO Completed | Truck |
| 432535 | Unimog Service Truck | INSTALACION DE VALVULA REGULAE | INSTALACION DE VALVULA REGULAE | 15/08/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| 431608 | Freightliner M2 106 Sucker Tru | INSTALACON DE EJE DE MANDO | INSTALACON DE EJE DE MANDO | 12/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 447840 | Caterpillar 735B ADT | LIFT CYLINDER REPAIRS | CORRECTIVE MAINTENANCE | 14/09/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 431360 | Hyster H700 Forklift | Limpieza de filtro de aire | SE APAGA, FALLA ACTIVA | 11/08/2020 | 4524 hrs | Corrective Order | WO Completed | Forklift |
| 433118 | Gallegos 28M3 Lime Tank | LINEAS DE DESCARGA OBSTRUIDA | LINEAS DE DESCARGA OBSTRUIDA | 16/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 419265 | GS119 J60U SDMO | LLAMADA DE EMERGENCIA | BAJO NIVEL DE ACEITE & PMS | 12/07/2020 | 23751 horas | Corrective Order | WO Completed | Generator |
| 424398 | PRAMAC GSW110 82 kVa | LLAMADA DE EMERGENCIA | FALLO POR TRIP DEL BREAKER | 20/07/2020 | 1541 horas | Corrective Order | WO Completed | Generator |
| 422714 | PRAMAC GSW110 82 kVa | LLAMADA DE EMERGENCIA | BREAKDOWN | 18/07/2020 | 1531 horas | Corrective Order | WO Completed | Generator |
| 422619 | PRAMAC GSW110 82 kVa | LLAMADA DE EMERGENCIA | FALLO POR BAJO NIVEL DE COMBUSTIBLE | 17/07/2020 | 1383 horas | Corrective Order | WO Completed | Generator |
| 422322 | PRAMAC GSW110 82 kVa | LLAMADA DE EMERGENCIA | FALLO POR BAJO NIVEL DE DIESEL | 16/07/2020 | 1353 horas | Corrective Order | WO Completed | Generator |
| 418509 | USP&E GP700S/V-A 700 kVa | LLAMADA DE EMERGENCIA | FALLA POR CILINDRO FRIO | 08/07/2020 | 33720 horas | Corrective Order | WO Completed | Generator |
| 418224 | USP&E GP700S/V-A 700 kVa | LLAMADA DE EMERGENCIA | FALLO DE BATERIA | 07/07/2020 | 33697 HORAS | Corrective Order | WO Completed | Generator |
| 422311 | USP&E GP700/V-A 700 kVa | LLAMADA DE EMERGENCIA | HIGH TEMPERATURE BREAKDOWN | 16/07/2020 | 9931 horas | Corrective Order | WO Completed | Generator |
| 421840 | USP&E GP700/V-A 700 kVa | LLAMADA DE EMERGENCIA | FALLA POR BAJA PRESION DE COMBUSTIBLI | 14/07/2020 | 9885 horas | Corrective Order | WO Completed | Generator |
| 418974 | USP&E GP700/V-A 700 kVa | LLAMADA DE EMERGENCIA | FALLO POR ALTA TEMPERATURA | 10/07/2020 | 9789 horas | Corrective Order | WO Completed | Generator |
| 442028 | USP&E GP700/V-A 700 kVa | LLAMADA DE EMERGENCIA | FALLO POR ALTA TEMPERATURA | 31/08/2020 | | Corrective Order | WO Completed | Generator |
| 441703 | USP&E GP700/V-A 700 kVa | LLAMADA DE EMERGENCIA | EQUIPO SIN COMBUSTIBLE | 30/08/2020 | 10162 HORAS | Corrective Order | WO Completed | Generator |
| 439125 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | EQUIPO SIN DIESEL | 26/08/2020 | 12380 nhoras | Corrective Order | WO Completed | Generator |
| 443325 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | CAMBIO DE TARGETA REGULADORA DE VOI | 03/09/2020 | 12410 horas | Corrective Order | WO Completed | Generator |
| 439230 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | DERRAME DE DIESEL | 26/08/2020 | 24381 horas | Corrective Order | WO Completed | Generator |
| 448985 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | FALLO POR CALENTAMIENTO, RADIADOR SI | 16/09/2020 | 24881 hours | Corrective Order | WO Completed | Generator |
| 445481 | PRAMAC GSW460V 460 kVa | LLAMADA DE EMERGENCIA | FALLO POR BAJO NIVEL DE COMBUSTIBLE | 08/09/2020 | 24064 horas | Corrective Order | WO Completed | Generator |
| 446356 | PRAMAC GSW560V 407 kVa | LLAMADA DE EMERGENCIA | FALLO POR CALENTAMIENTO DEL EQUIPO P | 10/09/2020 | 13873 hours | Corrective Order | WO Completed | Generator |
| 453492 | Olympian GEP 110-4 80 kVa | LLAMADA DE EMERGENCIA | FUGA DE COOLANT POR BOMBA DE AGUA I | 26/09/2020 | 26441 HORAS | Corrective Order | WO Completed | Generator |
| 445489 | Olympian GEP 110-4 80 kVa | LLAMADA DE EMERGENCIA | FUGA DE ACEITE | 08/09/2020 | 26024 horas | Corrective Order | WO Completed | Generator |
| 424397 | PRAMAC GSW705V 770 kVa | LLAMADA DE EMERGENCIA | FALLO DE BATERIA | 20/07/2020 | 9357 horas | Corrective Order | WO Completed | Generator |
| 421527 | PRAMAC GSW705V 770 kVa | LLAMADA DE EMERGENCIA | FALLO POR BATERIA DEFECTUOSA | 12/07/2020 | 9150 horas | Corrective Order | WO Completed | Generator |
| 424517 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | BREAKDOWN | 21/07/2020 | 20720 horas | Corrective Order | WO Completed | Generator |
| 422613 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | BALANCE DE CARGA & PMS | 17/07/2020 | 20648 horas | Corrective Order | WO Completed | Generator |
| 421946 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | BREAKDOWN | 15/07/2020 | 20600 horas | Corrective Order | WO Completed | Generator |
| 418811 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | EQUIPO PARADO POR FALLO | 10/07/2020 | 20629 horas | Corrective Order | WO Completed | Generator |
| 418501 | Olympian GEP 88-3 64 kVa | LLAMADA DE EMERGENCIA | FLUCTUACION DEL EQUIPO | 08/07/2020 | 20469 horas | Corrective Order | WO Completed | Generator |
| 439121 | SDMO J60U 60 kVa | LLAMADA DE EMERGENCIA | PROBLEMA DE ARRANQUE | 26/08/2020 | 21251 horas | Corrective Order | WO Completed | Generator |
| 424436 | Caterpillar DE88E0 58 kVa | LLAMADA DE EMERGENCIA | FALLO POR CALENTAMIENTO | 20/07/2020 | 27458 horas | Corrective Order | WO Completed | Generator |
| 448973 | Caterpillar DE88E0 58 kVa | LLAMADA DE EMERGENCIA | FALLO POR CORREA ROTA | 16/09/2020 | 28843 hours | Corrective Order | WO Completed | Generator |
| 449717 | PRAMAC GSW45 35 kVa | LLAMADA DE EMERGENCIA | FUGA DE ACEITE | 18/09/2020 | 10324 horas | Corrective Order | WO Completed | Generator |
| 424534 | PRAMAC GSW90P 74 kVa | LLAMADA DE EMERGENCIA | BREAKDOWN | 21/07/2020 | 17627 horas | Corrective Order | WO Completed | Generator |
| 447982 | PRAMAC GSW65 48 kVa | LLAMADA DE EMERGENCIA | FALLO POR CALENTAMINETO, BOMBA DE IN | 15/09/2020 | 16215 horas | Corrective Order | WO Completed | Generator |
| 454116 | Caterpillar 236d Skid Steer L | LLANTA EN MAL ESTADO | CAMBIO DE 2 LLANTAS | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Skid Steer |
| 453491 | Terex MAC25 25TON | Llanta flat | LLANTA FLAT | 26/09/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 451810 | Manitou Mht-X860 6t Telehand | Llanta flat | LLANTA FLAT | 22/09/2020 | | Corrective Order | WO Completed | Telehender |
| 450913 | Freightliner Columbia Cl112 | Llanta flat | LLANTA FLAT | 20/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 453211 | Freightliner Cl 120 | Llanta flat | REPARAR LLANTA FLAT | 26/09/2020 | 344703.0 kms | Corrective Order | WO Completed | Mule truck |
| 451968 | WT015 H7 CISTERNA SINOTRUK | Llanta flat | CAMBIO DE LLANTA | 23/09/2020 | | Corrective Order | WO Ready to Schedule | Water truck |
| 452248 | Intraax 53121 Hendrickso | Llantas en mal estado | CAMBIO DE LLANTAS | 23/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 449637 | Coaster Bus | Llantas en mal estado | CAMBIO DE LLANTAS DELANTERAS | 18/09/2020 | | Corrective Order | WO Completed | Bus |
| 445692 | Freightliner M2 106 Sucker Tru | Llantas en mal estado | SE REALIZA ARMADO DE LLANTAS PENDIEN | 09/09/2020 | 557173 kms | Corrective Order | WO Completed | Sucker truck |
| 446039 | Unimog Service Truck | Llantas en mal estado | CAMBIO DE 2 LLANTAS | 10/09/2020 | 49676.2 kms | Corrective Order | WO Completed | Truck |
| 450889 | Gallegos Flatbed Trailer | LLANTAS FLAT | LLANTAS FLAT | 20/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 435801 | Caterpillar 226b Skid Steer L | luces delanteras no funcionan | LUCES DELANTERAS NO FUNCIONAN | 23/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 450919 | Caterpillar 236d Skid Steer L | Luces no encienden | REVISION DE SISTEMA ELECTRICO | 20/09/2020 | | Corrective Order | WO Completed | Skid Steer |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 434558 | Grove RT700E 60TON | Maintenance | MAINTENANCE | 19/08/2020 | 1762.3 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 417372 | Freightliner M2 106 Truck | Manguera hidraulica rota | MANGUERA HIDRAULICA ROTA | 02/07/2020 | | Corrective Order | WO Completed | Boom truck |
| 449614 | Grove RT9130E 120TON | Manguera Hidraulica Rota | FBRICACION DE MANGUERA HIDRAULICA | 18/09/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 435720 | Caterpillar 336DL Excavator | Manguera rota | FABRICACION DE MANGUERAS | 22/08/2020 | | Corrective Order | WO Completed | Excavator |
| 443731 | Grove RT890 90TON | Mangueras danadas | CAMBIO DE DOS MANGUERAS | 04/09/2020 | 614 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 451019 | Freightliner Boom Truck | Mangueras en mal estado | CAMBIO DE MANGUERAS | 21/09/2020 | | Corrective Order | WO Completed | Boom truck |
| 417259 | PRAMAC GSW110 82 kVa | MANTENIMIEMNTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 01/07/2020 | 1010 HORAS | Corrective Order | WO Completed | Generator |
| 431393 | Unimog Service Truck | MANTENIMIENTO | MANTENIMIENTO | 11/08/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| 424313 | GS134 PN45 EXPERT POWER | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE Y FILTROS | 20/07/2020 | 9457 horas | Corrective Order | WO Completed | Generator |
| 433679 | GS134 PN45 EXPERT POWER | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE Y FILTROS | 17/08/2020 | 10341 hours | Corrective Order | WO Completed | Generator |
| 430868 | GS134 PN45 EXPERT POWER | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE Y FILTROS | 10/08/2020 | 10029 | Corrective Order | WO Completed | Generator |
| 443259 | GS134 PN45 EXPERT POWER | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE Y FILTROS | 03/09/2020 | 10545 horas | Corrective Order | WO Completed | Generator |
| 419245 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO CORRECTIVO | CAMBIO DE BOMBA DE INYECCION | 12/07/2020 | 10163 horas | Corrective Order | WO Completed | Generator |
| 423502 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO CORRECTIVO | LAVADO DE MAQUINA Y REPARACION DE E | 19/07/2020 | 33963 horas | Corrective Order | WO Completed | Generator |
| 450472 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO CORRECTIVO | REGULACION DE VOLTAGE, ARMADO DE BA | 19/09/2020 | 14143 hours | Corrective Order | WO Completed | Generator |
| 444170 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | CAMBIO DE CORREAS POR DEFECTUOSAS | 05/09/2020 | 12423 horas | Corrective Order | WO Completed | Generator |
| 449205 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | LAVADO DE RADIADOR Y PMS | 17/09/2020 | 24902 horas | Corrective Order | WO Completed | Generator |
| 424146 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 23 179 | Corrective Order | WO Completed | Generator |
| 419277 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 22824 horas | Corrective Order | WO Completed | Generator |
| 417498 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/07/2020 | 22572 horas | Corrective Order | WO Completed | Generator |
| 441012 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 23919 horas | Corrective Order | WO Completed | Generator |
| 433684 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 17/08/2020 | 23 627 hours | Corrective Order | WO Completed | Generator |
| 449796 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | LIMPIEZA DE RADIADORES & CAMBIO DE BO | 18/09/2020 | | Corrective Order | WO Completed | Generator |
| 447334 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 24459 hours | Corrective Order | WO Completed | Generator |
| 443266 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO CORRECTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 24685 horas | Corrective Order | WO Completed | Generator |
| 418976 | PRAMAC GSW560V 407 kVa | MANTENIMIENTO CORRECTIVO | FALLO DE TARGETA REGULADORA | 10/07/2020 | 12779 horas | Corrective Order | WO Completed | Generator |
| 424606 | PRAMAC GSW560V 407 kVa | MANTENIMIENTO CORRECTIVO | ARMADO DE TABLERO & PRUEBAS | 21/07/2020 | | Corrective Order | WO Completed | Generator |
| 438513 | Caterpillar DE88E0 58 kVa | MANTENIMIENTO CORRECTIVO | CAMBIO DE VOLTAGE | 25/08/2020 | | Corrective Order | WO Completed | Generator |
| 419243 | PRAMAC GSW45P 48 kVa | MANTENIMIENTO CORRECTIVO | EXTRACCION DE ESTATOR QUEMADO | 12/07/2020 | 7676 horas | Corrective Order | WO Completed | Generator |
| 433667 | Hyster H800 32t Forklift (M) | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 17/08/2020 | | Corrective Order | WO Completed | Forklift |
| 419271 | GS023 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE &N FILTROS | 12/07/2020 | 1783 horas | Corrective Order | WO Completed | Generator |
| 431122 | GS023 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE &N FILTROS | 11/08/2020 | 2307 | Corrective Order | WO Completed | Generator |
| 447321 | GS023 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE &N FILTROS | 13/09/2020 | 3156 horas | Corrective Order | WO Completed | Generator |
| 443242 | GS023 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE &N FILTROS | 03/09/2020 | 3058 horas | Corrective Order | WO Completed | Generator |
| 441026 | GS023 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE &N FILTROS | 29/08/2020 | 2720 HORAS | Corrective Order | WO Completed | Generator |
| 419123 | GS096 GEP18-6 OLYMPIAN | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 11/07/2020 | 2 461 | Corrective Order | WO Completed | Generator |
| 441027 | GS096 GEP18-6 OLYMPIAN | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 29/08/2020 | 24910 horas o 24 | Corrective Order | WO Completed | Generator |
| 424305 | GS118 J60U SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTRO | 20/07/2020 | 2573 horas | Corrective Order | WO Completed | Generator |
| 433675 | GS118 J60U SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTRO | 17/08/2020 | 3093 | Corrective Order | WO Completed | Generator |
| 442113 | GS149 T11UM SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 31/08/2020 | 7613 hours | Corrective Order | WO Completed | Generator |
| 433680 | GS163 C7.1 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 17/08/2020 | 21926 hours | Corrective Order | WO Completed | Generator |
| 424292 | GS163 C7.1 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 21629 | Corrective Order | WO Completed | Generator |
| 447329 | GS163 C7.1 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 22527 horas | Corrective Order | WO Completed | Generator |
| 441008 | GS163 C7.1 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 22217 horas | Corrective Order | WO Completed | Generator |
| 419275 | GS191 D110 E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 21198 hours | Corrective Order | WO Completed | Generator |
| 435147 | GS191 D110 E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 22112 hours | Corrective Order | WO Completed | Generator |
| 424142 | GS191 D110 E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 21 718 | Corrective Order | WO Completed | Generator |
| 423505 | GS195 T11 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE Y FILTROS | 19/07/2020 | 10 421 | Corrective Order | WO Completed | Generator |
| 447331 | GS195 T11 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 11250 horas | Corrective Order | WO Completed | Generator |
| 443264 | GS195 T11 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 11109 horas | Corrective Order | WO Completed | Generator |
| 435151 | GS218 T16 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 15172 hours | Corrective Order | WO Completed | Generator |
| 424293 | GS218 T16 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 14 837 | Corrective Order | WO Completed | Generator |
| 447336 | GS218 T16 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 15758 hours | Corrective Order | WO Completed | Generator |
| 441013 | GS218 T16 SDMO | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 15442 hours | Corrective Order | WO Completed | Generator |
| 433709 | GS246 DE110E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 17/08/2020 | 15023 | Corrective Order | WO Completed | Generator |
| 424302 | GS246 DE110E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 14 615 | Corrective Order | WO Completed | Generator |
| 443250 | GS246 DE110E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 15627 hours | Corrective Order | WO Completed | Generator |
| 435154 | GS246 DE110E2 CAT | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 15276 horas | Corrective Order | WO Completed | Generator |
| 441023 | GS264 GSW65P PRAMAC | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 11868 horas | Corrective Order | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 424301 | GS264 GSW65P PRAMAC | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 14 464 | Corrective Order | WO Completed | Generator |
| 449651 | GS264 GSW65P PRAMAC | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 18/09/2020 | 12,530 hours | Corrective Order | WO Completed | Generator |
| 443269 | GS264 GSW65P PRAMAC | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 12182 hours | Corrective Order | WO Completed | Generator |
| 447468 | FG WILSON P88-3 80 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE Y FILTROS | 13/09/2020 | 16640 horas | Corrective Order | WO Completed | Generator |
| 440274 | Caterpillar DE165E0 165 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 28/08/2020 | 13738 hours | Corrective Order | WO Completed | Generator |
| 424134 | PRAMAC GSW110 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | | Corrective Order | WO Completed | Generator |
| 421952 | PRAMAC GSW110 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 15/07/2020 | 1332 horas | Corrective Order | WO Completed | Generator |
| 419283 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | | Corrective Order | WO Completed | Generator |
| 418819 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 10/07/2020 | 3683 horas | Corrective Order | WO Completed | Generator |
| 435160 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 4754 hours | Corrective Order | WO Completed | Generator |
| 424300 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 4 419 | Corrective Order | WO Completed | Generator |
| 447343 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 5390 horas | Corrective Order | WO Completed | Generator |
| 441021 | PRAMAC GSW110P 82 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 5042 horas | Corrective Order | WO Completed | Generator |
| 424151 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 7 082 | Corrective Order | WO Completed | Generator |
| 419280 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 6813 hours | Corrective Order | WO Completed | Generator |
| 417499 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/07/2020 | 6457 horas | Corrective Order | WO Completed | Generator |
| 435163 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 7488 hours | Corrective Order | WO Completed | Generator |
| 431265 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 11/08/2020 | 15 875 | Corrective Order | WO Completed | Generator |
| 443249 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 8124 horas | Corrective Order | WO Completed | Generator |
| 441022 | PRAMAC GSW80P 83 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 7803 hours | Corrective Order | WO Completed | Generator |
| 424294 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | 33 963 | Corrective Order | WO Completed | Generator |
| 422723 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 18/07/2020 | 33963 horas | Corrective Order | WO Completed | Generator |
| 435128 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 34335 hours | Corrective Order | WO Completed | Generator |
| 449640 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 18/09/2020 | 34939 horas | Corrective Order | WO Completed | Generator |
| 417258 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 01/07/2020 | 19588 HORAS | Corrective Order | WO Completed | Generator |
| 440295 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 28/08/2020 | 20169 horas | Corrective Order | WO Completed | Generator |
| 453497 | USP&E GP700S/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | CAMBIO DE ENFRIADORES DE AIRE Y REVISI | 26/09/2020 | 14146 horas | Corrective Order | WO Completed | Generator |
| 418155 | USP&E GP700/V-A 700 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 06/07/2020 | | Corrective Order | WO Completed | Generator |
| 417495 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/07/2020 | 12228 horas | Corrective Order | WO Completed | Generator |
| 435135 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 12377 hours | Corrective Order | WO Completed | Generator |
| 423519 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 19/07/2020 | | Corrective Order | WO Completed | Generator |
| 419119 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 11/07/2020 | 23353 horas | Corrective Order | WO Completed | Generator |
| 417497 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 03/07/2020 | 23089 HORAS | Corrective Order | WO Completed | Generator |
| 441939 | PRAMAC GSW460V 460 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 31/08/2020 | 17845 horas | Corrective Order | WO Completed | Generator |
| 447681 | MODASA MP451 451 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES Y FILTROS | 14/09/2020 | 10622 horas | Corrective Order | WO Completed | Generator |
| 424124 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE FILTROS | 19/07/2020 | 30308 HORAS | Corrective Order | WO Completed | Generator |
| 419267 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE FILTROS | 12/07/2020 | 29665 horas | Corrective Order | WO Completed | Generator |
| 442026 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 31/08/2020 | 30401 horas | Corrective Order | WO Completed | Generator |
| 447320 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 13/09/2020 | 303 horas | Corrective Order | WO Completed | Generator |
| 443241 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 30401 | Corrective Order | WO Completed | Generator |
| 450495 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITES & FILTROS | 19/09/2020 | 21705 horas | Corrective Order | WO Completed | Generator |
| 424153 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 26 936 | Corrective Order | WO Completed | Generator |
| 419281 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 26664 hours | Corrective Order | WO Completed | Generator |
| 417689 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 04/07/2020 | 26352 horas | Corrective Order | WO Completed | Generator |
| 427876 | SDMO J60U 60 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 02/08/2020 | 27 372 | Corrective Order | WO Completed | Generator |
| 424145 | Caterpillar DE88E0 58 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 27 641 | Corrective Order | WO Completed | Generator |
| 419276 | Caterpillar DE88E0 58 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 27407 hours | Corrective Order | WO Completed | Generator |
| 417500 | Caterpillar DE88E0 58 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/07/2020 | 27047 horas | Corrective Order | WO Completed | Generator |
| 419262 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 12/07/2020 | 17636 hours | Corrective Order | WO Completed | Generator |
| 417725 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 04/07/2020 | 17325 horas | Corrective Order | WO Completed | Generator |
| 430861 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 10/08/2020 | 18363 | Corrective Order | WO Completed | Generator |
| 423532 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 19/07/2020 | 18 035 | Corrective Order | WO Completed | Generator |
| 449646 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 18/09/2020 | 18652 horas | Corrective Order | WO Completed | Generator |
| 441015 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 29/08/2020 | 18653 hours | Corrective Order | WO Completed | Generator |
| 435153 | PRAMAC GSW90P 74 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 21/08/2020 | 18364 | Corrective Order | WO Completed | Generator |
| 422361 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 17/07/2020 | 14803 hours | Corrective Order | WO Completed | Generator |
| 419288 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 12/07/2020 | 14862 horas | Corrective Order | WO Completed | Generator |
| 417729 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 04/07/2020 | 14527 horas | Corrective Order | WO Completed | Generator |
| 433711 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 17/08/2020 | 15 653 | Corrective Order | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 424295 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 20/07/2020 | 15 195 | Corrective Order | WO Completed | Generator |
| 447341 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 13/09/2020 | 16255 horas | Corrective Order | WO Completed | Generator |
| 441019 | PRAMAC GSW65 48 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZ DE ACEITE & FILTROS | 29/08/2020 | 15951 horas | Corrective Order | WO Completed | Generator |
| 418154 | PRAMAC GBW15 14 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 06/07/2020 | 14389 horas | Corrective Order | WO Completed | Generator |
| 443322 | PRAMAC GSW25 17 kVa | MANTENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 03/09/2020 | 427 horas | Corrective Order | WO Completed | Generator |
| 433668 | Cargador 966H Wheel Loader | MANTENIMIENTO PREVENTIVO | MANTENIMIENTO PREVENTIVO | 17/08/2020 | | Corrective Order | WO Completed | Loader |
| 424133 | Olympian GEP 88-3 64 kVa | MANTENMIENTO PREVENTIVO | REMMPLAZO DE ACEITE & FILTRO | 19/07/2020 | 2 093 | Corrective Order | WO Completed | Generator |
| 446483 | Gallegos Flatbed Trailer | Mantiene 2 llantas flat | SE REALIZA CAMBIO DE 2 LLANTAS | 11/09/2020 | N/A | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 446409 | Gallegos Flatbed Trailer | Mantiene 5 llantas en mal esta | REQUIERE CAMBIO DE 2 LLANTAS | 10/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 446416 | Gallegos Flatbed Trailer | Mantiene llantas en mal estado | CAMBIO DE 4 LLANTAS | 10/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 449794 | Olympian GEP150 135 kVa | MATENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 18/09/2020 | 519 horas | Corrective Order | WO Completed | Generator |
| 424311 | Olympian GEP 110-4 80 kVa | MATENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 20/07/2020 | | Corrective Order | WO Completed | Generator |
| 418865 | Olympian GEP 110-4 80 kVa | MATENIMIENTO PREVENTIVO | REEMPLAZO DE ACEITE & FILTROS | 10/07/2020 | 24612 horas | Corrective Order | WO Completed | Generator |
| 447846 | Intraax 53121 Hendrickso | MECHANICAL INSPECTION | INSPECTION | 14/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 449330 | JLG 800 AJ Manlift | MECHANICAL INSPECTION | INSPECTION | 17/09/2020 | | Corrective Order | WO Completed | Manlift |
| 449331 | JLG 1250 AJP Manlift | MECHANICAL INSPECTION | INSPECTION | 17/09/2020 | | Corrective Order | WO Completed | Manlift |
| 449334 | JLG 1850 AJ Manlift | MECHANICAL INSPECTION | INSPECTION | 17/09/2020 | | Corrective Order | WO Completed | Manlift |
| 447791 | JLG 450 AJ Manlift | MECHANICAL REPAIRS | CORRECTIVE MAINTENANCE | 14/09/2020 | | Corrective Order | W/O In Planning | Manlift |
| 439138 | MG011 16H CAT | MONTAJE DE LLANTA POS 4 Y 6 | TRABAJO MECANICO | 26/08/2020 | | Corrective Order | WO Completed | Grader |
| 446417 | Freightliner M2 106 Sucker Tru | Motor se recalienta | REQUIERE CAMBIO DE RADIADOR, BASE DE | 10/09/2020 | 557250.4 kms | Corrective Order | WO Completed | Sucker truck |
| 449643 | Coaster Bus | no arranca | REVISION SISTEMA ELECTRICO | 18/09/2020 | 297613 kms | Corrective Order | WO Completed | Bus |
| 431084 | Internation 4400 SBA 6x4 Boom | No arranca// Fabricar manguera | EQUIPO NO ARRANCA | 10/08/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| 439208 | Case 110JX Tractor Cable Handl | Noise on rear axle | NOISE ON REAR AXLE | 26/08/2020 | | Corrective Order | W/O In Planning | Tractor |
| 432308 | Cargador 966H Wheel Loader | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | 21563.4 hrs | Corrective Order | WO Completed | Loader |
| 433636 | GS013 GEP 200-4 OLYMPIAN | OIL & FILTER REMPLACENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 13795 hours | Corrective Order | WO Completed | Generator |
| 443251 | GS013 GEP 200-4 OLYMPIAN | OIL & FILTER REMPLACENT | PREVENTIVE MAINTENANCE | 03/09/2020 | 14303 hours | Corrective Order | WO Completed | Generator |
| 433638 | GS013 GEP 200-4 OLYMPIAN | OIL & FILTER REMPLACENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 14016 hours | Corrective Order | WO Completed | Generator |
| 433676 | GS118 J60U SDMO | OIL & FILTER REMPLACENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 3093 horas | Corrective Order | WO Completed | Generator |
| 435129 | GS118 J60U SDMO | OIL & FILTER REMPLACENT | PREVENTIVE MAINTENANCE | 21/08/2020 | 3093 horas | Corrective Order | WO Completed | Generator |
| 439217 | Case 110JX Tractor Cable Handl | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 26/08/2020 | 2592.1hrs | Corrective Order | WO Completed | Tractor |
| 415746 | Gmc Boom Truck | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 450384 | Samil Boom Truck | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 19/09/2020 | | Corrective Order | WO Completed | Boom truck |
| 415753 | Caterpillar 740B EJ ADT | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 20/06/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 433640 | GS014 GEP 200-4 OLYMPIAN | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 17/08/2020 | 22410 horas | Corrective Order | WO Completed | Generator |
| 433639 | GS014 GEP 200-4 OLYMPIAN | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 17/08/2020 | 22 144 | Corrective Order | WO Completed | Generator |
| 419255 | GS014 GEP 200-4 OLYMPIAN | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 12/07/2020 | 21 817 | Corrective Order | WO Completed | Generator |
| 447319 | GS014 GEP 200-4 OLYMPIAN | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 13/09/2020 | 22986 horas | Corrective Order | WO Completed | Generator |
| 433672 | GS014 GEP 200-4 OLYMPIAN | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 17/08/2020 | 22.743 horas | Corrective Order | WO Completed | Generator |
| 424154 | PRAMAC GSW65 48 kVa | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 19/07/2020 | | Corrective Order | WO Completed | Generator |
| 441018 | PRAMAC GSW65 48 kVa | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 29/08/2020 | 15876 hours | Corrective Order | WO Completed | Generator |
| 431259 | PRAMAC GSW65 48 kVa | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 11/08/2020 | 15 495 | Corrective Order | WO Completed | Generator |
| 447339 | PRAMAC GSW65 48 kVa | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 13/09/2020 | 16210 horas | Corrective Order | WO Completed | Generator |
| 417768 | PRAMAC GBW15 14 kVa | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 04/07/2020 | 14802 | Corrective Order | WO Completed | Generator |
| 432317 | Manitou Mht-X1490 9t Telehand | OIL & FILTER REPLACEMEN | PREVENTIVE MAINTENANCE | 15/08/2020 | 1962 h | Corrective Order | WO Completed | Telehender |
| 434830 | Caterpillar 426f2 Backhoe | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 20/08/2020 | 1538 hrs | Corrective Order | WO Completed | Backhoe |
| 432304 | Freightliner M2 106 Truck | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 422326 | Caterpillar D8T Dozer | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | | Corrective Order | WO Completed | Dozer |
| 422329 | Caterpillar 320DL Excavator | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | 20834 | Corrective Order | W/O In Planning | Excavator |
| 427808 | Hyster H70ft 3t Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | | Corrective Order | WO Completed | Forklift |
| 427809 | Hyster H70ft 3t Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | AUTO CLOSED | Corrective Order | WO Completed | Forklift |
| 443063 | Hyster H300 13t Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 02/09/2020 | 1887.0 hrs | Corrective Order | WO Completed | Forklift |
| 430379 | Hyster H300 13t Forklift (M) | OIL & FILTER REPLACEMENT | PREVNTIVE REPLACEMENT | 08/08/2020 | 3445 HR | Corrective Order | WO Completed | Forklift |
| 417799 | Hyster H800 32t Forklift (M) | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 04/07/2020 | 314 HR | Corrective Order | WO Completed | Forklift |
| 430382 | Hyster H800 32t Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Forklift |
| 427824 | Caterpillar DP50 Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 463 HRS | Corrective Order | WO Completed | Forklift |
| 427825 | Caterpillar DP50 Forklift (M) | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 492.0hrs | Corrective Order | WO Completed | Forklift |
| 417800 | Hyster H700 Forklift | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 04/07/2020 | | Corrective Order | W/O In Planning | Forklift |
| 432311 | Hyster H300 Forklift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | | Corrective Order | W/O In Planning | Forklift |
| 427827 | International 7400 SBA Fire Tr | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 11738km | Corrective Order | WO Completed | Fire truck |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 433673 | GS058 J60U-NEXYS SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 5290 hours | Corrective Order | WO Completed | Generator |
| 427721 | GS058 J60U-NEXYS SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 5045 | Corrective Order | WO Completed | Generator |
| 447317 | GS058 J60U-NEXYS SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 5866 horas | Corrective Order | WO Completed | Generator |
| 441000 | GS058 J60U-NEXYS SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 5535 horas | Corrective Order | WO Completed | Generator |
| 447324 | GS074 T30 SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 1210 hours | Corrective Order | WO Completed | Generator |
| 441001 | GS074 T30 SDMO | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 1102 horas | Corrective Order | WO Completed | Generator |
| 447330 | GS190 D110 E2 CAT | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 12834 hours | Corrective Order | WO Completed | Generator |
| 441009 | GS190 D110 E2 CAT | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 12542 hours | Corrective Order | WO Completed | Generator |
| 435148 | PRAMAC GSW110 82 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 21/08/2020 | 2357 hours | Corrective Order | WO Completed | Generator |
| 427700 | PRAMAC GSW110 82 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 1 968 | Corrective Order | WO Completed | Generator |
| 447332 | PRAMAC GSW110 82 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 2908 horas | Corrective Order | WO Completed | Generator |
| 441010 | PRAMAC GSW110 82 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 2916 horas | Corrective Order | WO Completed | Generator |
| 433700 | PRAMAC GSW80P 83 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 3 292 | Corrective Order | WO Completed | Generator |
| 427692 | PRAMAC GSW80P 83 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 2 880 | Corrective Order | WO Completed | Generator |
| 435152 | PRAMAC GSW80P 83 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 21/08/2020 | 3577 horas | Corrective Order | WO Completed | Generator |
| 427722 | USP&E GP700S/V-A 700 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 19 903 | Corrective Order | WO Completed | Generator |
| 430870 | PRAMAC GSW460V 460 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 10/08/2020 | 24 308 | Corrective Order | WO Completed | Generator |
| 427710 | PRAMAC GSW460V 460 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 23 947 | Corrective Order | WO Completed | Generator |
| 447327 | PRAMAC GSW460V 460 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 24902 horas | Corrective Order | WO Completed | Generator |
| 435138 | PRAMAC GSW460V 460 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 21/08/2020 | 24596 horas | Corrective Order | WO Completed | Generator |
| 433635 | Olympian GEP 110-4 80 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 25782 HORAS | Corrective Order | WO Completed | Generator |
| 433633 | Olympian GEP 110-4 80 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 17/08/2020 | 25 499 | Corrective Order | WO Completed | Generator |
| 427694 | Olympian GEP 110-4 80 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 25 189 | Corrective Order | WO Completed | Generator |
| 447318 | Olympian GEP 110-4 80 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 26441 horas | Corrective Order | WO Completed | Generator |
| 440997 | Olympian GEP 110-4 80 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 26120 horas | Corrective Order | WO Completed | Generator |
| 431258 | PRAMAC GSW705V 770 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 11/08/2020 | | Corrective Order | WO Completed | Generator |
| 427720 | PRAMAC GSW705V 770 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 9 522 | Corrective Order | WO Completed | Generator |
| 435159 | PRAMAC GBW15 14 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 21/08/2020 | 15562 hours | Corrective Order | WO Completed | Generator |
| 427708 | PRAMAC GBW15 14 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 15 089 | Corrective Order | WO Completed | Generator |
| 447342 | PRAMAC GBW15 14 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 13/09/2020 | 15562 hours | Corrective Order | WO Completed | Generator |
| 441020 | PRAMAC GBW15 14 kVa | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | 15959 hours | Corrective Order | WO Completed | Generator |
| 428302 | Coaster Bus | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 03/08/2020 | | Corrective Order | WO Completed | Bus |
| 425740 | Coaster Bus | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 25/07/2020 | | Corrective Order | WO Completed | Bus |
| 444990 | PB002 COASTER TOYOTA | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 441355 | PB004 COASTER TOYOTA | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 29/08/2020 | | Corrective Order | WO Completed | Bus |
| 445014 | PB006 COASTER TOYOTA | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 445013 | PB011 COASTER TOYOTA | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 444992 | PB013 COASTER TOYOTA | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 435528 | MG003 12M CAT | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 22/08/2020 | 11724.9 hrs | Corrective Order | WO Completed | Grader |
| 443290 | JLG T350 Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 03/09/2020 | 103 hrs | Corrective Order | WO Completed | Manlift |
| 427829 | JLG 450 AJ Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | | Corrective Order | WO Completed | Manlift |
| 443291 | JLG 450 AJ Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 03/09/2020 | 3907 hrs | Corrective Order | WO Completed | Manlift |
| 417801 | JLG 450 AJ Manlift | OIL & FILTER REPLACEMENT | MAINTENACE PREVENTIVE | 04/07/2020 | 5452.7 hrs | Corrective Order | WO Completed | Manlift |
| 434895 | JLG 800 AJ Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 20/08/2020 | | Corrective Order | WO Completed | Manlift |
| 445970 | JLG 800 AJ Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 09/09/2020 | | Corrective Order | W/O In Planning | Manlift |
| 430470 | JLG 1250 AJP Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Manlift |
| 430472 | JLG 1250 AJP Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 4722 hrs | Corrective Order | WO Completed | Manlift |
| 427832 | JLG 1250 AJP Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | | Corrective Order | WO Completed | Manlift |
| 427833 | JLG 1850 AJ Manlift | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | | Corrective Order | WO Completed | Manlift |
| 422324 | Caterpillar CW34 Compactor | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | | Corrective Order | WO Completed | Compactor |
| 422308 | Broce broom RJT350 | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENIVE | 16/07/2020 | | Corrective Order | W/O In Planning | Scrubber / Sweeper |
| 428022 | Caterpillar 236d Skid Steer L | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 02/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 427835 | Caterpillar 236d Skid Steer L | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 01/08/2020 | 2185.0hrs | Corrective Order | WO Completed | Skid Steer |
| 417803 | Caterpillar 226b Skid Steer L | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 04/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 417804 | Caterpillar 226b Skid Steer L | OIL & FILTER REPLACEMENT | MANITENANCE PREVENTIVE | 04/07/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 422330 | Freightliner M2 106 Refrigerat | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | | Corrective Order | WO Completed | Refrigerator truck |
| 422331 | Freightliner M2 106 Refrigerat | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | 463.1 hrs | Corrective Order | WO Completed | Refrigerator truck |
| 422332 | Freightliner M2 106 Refrigerat | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | 1553.1 hrs | Corrective Order | WO Completed | Refrigerator truck |
| 422333 | Freightliner M2 112 Sucker Tru | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | 1616km | Corrective Order | WO Completed | Sucker truck |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 422334 | Freightliner M2 106 Sucker Tru | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | | Corrective Order | WO Completed | Sucker truck |
| 422335 | Freightliner M2 106 Sucker Tru | OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | | Corrective Order | W/O In Planning | Sucker truck |
| 445988 | Manitou Mht-X860 6t Telehand | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 09/09/2020 | | Corrective Order | WO Completed | Telehender |
| 430384 | Manitou Mht-X860 6t Telehand | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 1702.4 HR | Corrective Order | WO Completed | Telehender |
| 432315 | Manitou Mht-X1490 9t Telehand | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | 987 HR | Corrective Order | WO Completed | Telehender |
| 430392 | Magni HTH 10,10 Telehandler | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Telehender |
| 432295 | Freightliner M112 Truck Tip | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | | Corrective Order | W/O In Planning | Tipper |
| 430468 | Freightliner M112 Truck Tip | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Tipper |
| 430265 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 22744.2 km | Corrective Order | WO Completed | Mule truck |
| 430287 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 430294 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 27407.6 kms | Corrective Order | WO Completed | Mule truck |
| 430299 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 430401 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 430401 kms 219( | Corrective Order | WO Completed | Mule truck |
| 430418 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 27407.6 | Corrective Order | WO Completed | Mule truck |
| 430396 | Freightliner Columbia Cl112 | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 23234.9 hrs | Corrective Order | WO Completed | Mule truck |
| 430363 | Unimog Service Truck | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | 25067 | Corrective Order | WO Completed | Truck |
| 430254 | Unimog Service Truck | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 08/08/2020 | | Corrective Order | WO Completed | Truck |
| 419205 | Caterpillar CS533E Compactor | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 11/07/2020 | | Corrective Order | WO Completed | Compactor |
| 417806 | Cargador 966H Wheel Loader | OIL & FILTER REPLACEMENT | MIANTENANCE PREVENTIVE | 04/07/2020 | | Corrective Order | W/O In Planning | Loader |
| 430286 | Freightliner 8170ME Water Truc | OIL & FILTER REPLACEMENT | PREVENTIV MAINTENANCE | 08/08/2020 | 103206.3 | Corrective Order | WO Completed | Water truck |
| 432305 | International 7400 SBA Water T | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 14/08/2020 | | Corrective Order | WO Completed | Water truck |
| 443066 | WT013 H7 CISTERNA SINOTRUK | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 02/09/2020 | | Corrective Order | WO Completed | Water truck |
| 452621 | WT015 H7 CISTERNA SINOTRUK | OIL & FILTER REPLACEMENT | PREVENTIVE MAINTENANCE | 24/09/2020 | 40218 kms | Corrective Order | WO Completed | Water truck |
| 439797 | Caterpillar 320DL | OIL & FILTER REPLACENT | MAINTENANCE PREVENTIVE | 27/08/2020 | 16809hrs | Corrective Order | WO Completed | Excavator |
| 424314 | GS168 CAT C4.4 CAT | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 20/07/2020 | | Corrective Order | WO Completed | Generator |
| 419112 | GS168 CAT C4.4 CAT | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 11/07/2020 | 19570 horas | Corrective Order | WO Completed | Generator |
| 416750 | Manitou Mht-X1490 9t Telehand | OIL & FILTER REPLACENT | PREVENTIVE MAINTENANCE | 27/06/2020 | 1978hrs | Corrective Order | WO Completed | Telehender |
| 448747 | Caterpillar 12M Motorgrader | Oil Leak Diff | OIL LEAK DIFF | 16/09/2020 | | Corrective Order | WO Completed | Grader |
| 417805 | Freightliner M2 112 Sucker Tru | OIL& FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 04/07/2020 | | Corrective Order | WO Ready to Schedule | Sucker truck |
| 422312 | Tennant S30 Sweeper | OIL& FILTER REPLACEMENT | MAINTENANCE PRECENTIVE | 16/07/2020 | 139 | Corrective Order | WO Completed | Scrubber / Sweeper |
| 422315 | Tennant S30 Sweeper | OIL& FILTER REPLACEMENT | MAINTENANCE PRECENTIVE | 16/07/2020 | 146 H | Corrective Order | WO Completed | Scrubber / Sweeper |
| 422321 | Tennant S30 Sweeper | OIL& FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 16/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Scrubber / Sweeper |
| 447507 | Mobile equipment | oxigeno acetileno descargado | OXIGENO ACETILENO | 13/09/2020 | | Corrective Order | WO Completed | Area |
| 386737 | Shuttlelift RTCD5540F 15TON | PLAN DE INSPECCIONES DE GRUAS | PARTS REQUEST TO PASS INSPECTION | 22/02/2020 | | Corrective Order | W/O In Planning | Crane |
| 439232 | John Deere 9370R Tractor | PM CAMBIO DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 26/08/2020 | 9.8hrs | Corrective Order | WO Completed | Tractor |
| 439237 | John Deere 9370R Tractor | PM CAMBIO DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 26/08/2020 | 12.4hrs | Corrective Order | WO Completed | Tractor |
| 439178 | Freightliner Boom Truck | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 26/08/2020 | | Corrective Order | WO Completed | Boom truck |
| 387519 | Caterpillar D8T Dozer | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 24/02/2020 | 242 h | Corrective Order | WO Completed | Dozer |
| 425215 | Caterpillar 336DL Excavator | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVE MAINTENANCE | 22/07/2020 | 17619hrs | Corrective Order | WO Completed | Excavator |
| 419188 | JLG T350 Manlift | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 11/07/2020 | | Corrective Order | WO Completed | Manlift |
| 400152 | JLG T350 Manlift | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 19/03/2020 | 0000 hrs | Corrective Order | WO Completed | . |
| 396933 | JLG 800 AJ Manlift | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 13/03/2020 | | Corrective Order | WO Completed | . |
| 396980 | JLG 800 AJ Manlift | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 13/03/2020 | | Corrective Order | W/O In Planning | . |
| 408425 | JLG 800 AJ Manlift | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 28/04/2020 | PREVENTIVE MA | Corrective Order | WO Completed | . |
| 419202 | Caterpillar RM500 Reclaimer | PM CAMBIO DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 11/07/2020 | | Corrective Order | WO Completed | Reclaimer |
| 439193 | Caterpillar RM500 Reclaimer | PM CAMBIO DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 26/08/2020 | 508 hrs | Corrective Order | WO Completed | Reclaimer |
| 439199 | Caterpillar 226b Skid Steer L | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 26/08/2020 | PREVENTIVO MP | Corrective Order | WO Completed | Skid Steer |
| 398979 | Manitou MHT10180L Telehandler | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 17/03/2020 | S/H | Corrective Order | WO Completed | Forklift |
| 410904 | Freightliner Columbia Cl112 | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 20/05/2020 | PREVENTIVO MP | Corrective Order | W/O In Planning | Mule truck |
| 439203 | Unimog Service Truck | PM CAMBIO DE FILTROS Y ACEITE | MANTENCION PREVENTIVA | 26/08/2020 | | Corrective Order | W/O In Planning | Truck |
| 439206 | Unimog Service Truck | PM CAMBIO DE FILTROS Y ACEITE | PREVENTIVO MPSA | 26/08/2020 | | Corrective Order | W/O In Planning | Truck |
| 434828 | Case 110JX Tractor Cable Handl | PM CAMBIO FILTROS Y ACEITE | PREVENTIVO MPSA | 20/08/2020 | 1838.3hrs | Corrective Order | WO Completed | Tractor |
| 440579 | Unimog U3000 Truck | PM CAMBIO SOLO ACEITE | MANTENIMIENTO PREVENTIVO | 28/08/2020 | | Corrective Order | WO Completed | Truck |
| 445985 | WT013 H7 CISTERNA SINOTRUK | PM CAMION DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 09/09/2020 | 3487 kms | PM Orders | WO Completed | Water truck |
| 441966 | WT015 H7 CISTERNA SINOTRUK | PM CAMION DE FILTROS Y ACEITE | MANTENIMIENTO PREVENTIVO | 31/08/2020 | 38848 hrs | PM Orders | WO Completed | Water truck |
| 422595 | Randon SR-Sl-TV-03-27 Lime Tan | PM LUBRICACION TANQUES DE CAL | PREVENTIVO | 17/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 422597 | Randon SR-Sl-TV-03-27 Lime Tan | PM LUBRICACION TANQUES DE CAL | PREVENTIVO | 17/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 422598 | Gallegos 28M3 Lime Tank | PM LUBRICACION TANQUES DE CAL | PREVENTIVO | 17/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 422601 | Gallegos 28M3 Lime Tank | PM LUBRICACION TANQUES DE CAL | PREVENTIVO | 17/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Trailer / Flatbed / Lime |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 422602 | GALLEGOS Lime Tank | PM LUBRICACION TANQUES DE CAL | PREVENTIVO | 17/07/2020 | AUTO CLOSED | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 425211 | TH012 LM 1745 New Holland | PM OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 22/07/2020 | 85160.9 hrs | Corrective Order | WO Completed | . |
| 425212 | TH015 LM 1745 New Holland | PM OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 22/07/2020 | 14213.4 hrs | Corrective Order | WO Completed | . |
| 425213 | TH016 LM 1745 New Holland | PM OIL & FILTER REPLACEMENT | MAINTENANCE PREVENTIVE | 22/07/2020 | | Corrective Order | W/O In Planning | . |
| 427800 | Internation F2674 | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 01/08/2020 | 152526.4 kms | Corrective Order | WO Completed | Boom truck |
| 450388 | Freightliner FL112 Boom Truck | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 19/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Boom truck |
| 413305 | Grove RT890 90TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 604.1hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413310 | Grove GMK 4080 80TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 039505.3hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413354 | GROVE GMK 5170 170TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 413338 | Grove RT600E 50TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 763.6hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413339 | Terex RT5551 55TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 9069.3hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413340 | Grove RT650E 45TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | | Corrective Order | WO Ready to Schedule | Crane/Hoist |
| 413312 | Terex RT670 64TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 413322 | Grove RT700E 60TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 12638.4 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413349 | GROVE RT700E 60TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 413316 | Grove RT880E 75TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 2638hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413318 | Shuttlelift RTCD5540F 15TON | PREVENTIVE MAINTENANCE | PREVENTIVE MAINTENANCE | 05/06/2020 | AUTO CLOSED | Corrective Order | WO Completed | Crane/Hoist |
| 413333 | Shuttlelift RTCD5540F 15TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 413329 | Terex MAC25 25TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 12706 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413357 | GROVE GMK 2035E 35TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 14549.9 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 413361 | GROVE RT530E 30TON | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 05/06/2020 | 1662 | Corrective Order | WO Completed | Crane/Hoist |
| 439795 | Caterpillar 740B EJ ADT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/08/2020 | | Corrective Order | WO Completed | Articulated dump truck |
| 413433 | Hyster H300 13t Forklift (M) | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 06/06/2020 | 1375hrs | Corrective Order | WO Completed | Forklift |
| 413950 | Hyster H700 Forklift | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/06/2020 | | Corrective Order | W/O In Planning | Forklift |
| 446004 | Caterpillar 12M Motorgrader | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 09/09/2020 | 9898.2 HRS | Corrective Order | WO Completed | Grader |
| 409783 | GS001 GEP 110-4 OLYMPIAN | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 37993 horas | Corrective Order | WO Completed | Generator |
| 419118 | GS037 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 11/07/2020 | 4756 horas | Corrective Order | WO Completed | Generator |
| 424303 | GS037 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 20/07/2020 | 5054 horas | Corrective Order | WO Completed | Generator |
| 410600 | GS083 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | | Corrective Order | WO Completed | Generator |
| 435920 | GS112 J60U-NEXYS SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/08/2020 | 14397 hours | Corrective Order | WO Completed | Generator |
| 441028 | GS119 J60U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 24301 hours | Corrective Order | WO Completed | Generator |
| 424121 | GS119 J60U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 19/07/2020 | 23 911 | Corrective Order | WO Completed | Generator |
| 423538 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 19/07/2020 | 4 586 | Corrective Order | WO Completed | Generator |
| 409733 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 4277 horas | Corrective Order | WO Completed | Generator |
| 435132 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 21/08/2020 | 5313 hours | Corrective Order | WO Completed | Generator |
| 430869 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/08/2020 | 4 997 | Corrective Order | WO Completed | Generator |
| 447326 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/09/2020 | 5954 horas | Corrective Order | WO Completed | Generator |
| 441005 | GS139 C100D6 CUMMINS | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 5622 horas | Corrective Order | WO Completed | Generator |
| 409762 | GS154 T11UM SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 12279 horas | Corrective Order | WO Completed | Generator |
| 409781 | GS157 MMG80 MAGNUM | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 28121 horas | Corrective Order | WO Completed | Generator |
| 408307 | GS171 GSW45 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/04/2020 | 16438 horas en p | Corrective Order | WO Completed | Generator |
| 409792 | GS209 J30U SDMO | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | | Corrective Order | WO Completed | Generator |
| 424309 | GS216 GSW110 PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/07/2020 | | Corrective Order | WO Completed | Generator |
| 433707 | GS238 GSW25P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 17/08/2020 | 2324 | Corrective Order | WO Completed | . |
| 409760 | GS238 GSW25P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 1 871 | Corrective Order | WO Completed | . |
| 449645 | GS238 GSW25P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/09/2020 | 3271 hours | Corrective Order | WO Completed | . |
| 443244 | GS238 GSW25P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/09/2020 | 2950 horas | Corrective Order | WO Completed | . |
| 441014 | GS238 GSW25P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 2636 horas | Corrective Order | WO Completed | . |
| 410901 | GS240 GSW80P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/05/2020 | | Corrective Order | WO Completed | . |
| 441031 | GS240 GSW80P PRAMAC | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 11580 horas | Corrective Order | WO Completed | . |
| 441593 | GS243 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 30/08/2020 | 7037 hours | Corrective Order | WO Completed | Generator |
| 410601 | GS245 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/05/2020 | | Corrective Order | WO Completed | Generator |
| 424148 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 19/07/2020 | 7 930 | Corrective Order | WO Completed | Generator |
| 419279 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 12/07/2020 | 7643 hours | Corrective Order | WO Completed | Generator |
| 416804 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 27/06/2020 | 7307 horas | Corrective Order | WO Completed | Generator |
| 433710 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 17/08/2020 | 8639 horas | Corrective Order | WO Completed | Generator |
| 431140 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/08/2020 | 8 366 | Corrective Order | WO Completed | Generator |
| 447337 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/09/2020 | 9297 hours | Corrective Order | WO Completed | Generator |
| 441016 | GS250 DE110E2 CAT | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 8997 horas | Corrective Order | WO Completed | Generator |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 419274 | Cummins C80D6 80 kVa | PREVENTIVE MAINTENANCE | INSPECTION & REVIEW | 12/07/2020 | 19548 horas | Corrective Order | WO Completed | Generator |
| 409782 | PRAMAC GSW80P 83 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | | Corrective Order | WO Completed | Generator |
| 409778 | Caterpillar DE110E 110 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 15 145 | Corrective Order | WO Completed | Generator |
| 431124 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/08/2020 | 34 355 | Corrective Order | WO Completed | Generator |
| 409754 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 25 115 | Corrective Order | WO Completed | Generator |
| 409755 | USP&E GP700S/V-A 700 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 18 041 | Corrective Order | WO Completed | Generator |
| 409770 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | | Corrective Order | WO Completed | Generator |
| 431141 | PRAMAC GSW460V 460 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/08/2020 | 5 018 | Corrective Order | WO Completed | Generator |
| 424308 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 20/07/2020 | | Corrective Order | WO Completed | Generator |
| 433685 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 17/08/2020 | 13630 hours | Corrective Order | WO Completed | Generator |
| 431138 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/08/2020 | 13 350 | Corrective Order | WO Completed | Generator |
| 449644 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/09/2020 | 14178 horas | Corrective Order | WO Completed | Generator |
| 433687 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 17/08/2020 | 13818 horas | Corrective Order | WO Completed | Generator |
| 419115 | PRAMAC GSW560V 407 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/07/2020 | | Corrective Order | WO Completed | Generator |
| 430864 | MODASA MP451 451 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/08/2020 | 10 290 | Corrective Order | WO Completed | Generator |
| 408953 | PRAMAC GSW330V 315 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 03/05/2020 | | Corrective Order | WO Completed | Generator |
| 430867 | Olympian GEP 88-3 64 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/08/2020 | Disconectes, hav | Corrective Order | WO Completed | Generator |
| 435130 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 21/08/2020 | 27660 horas | Corrective Order | WO Completed | Generator |
| 447325 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/09/2020 | 28314 | Corrective Order | WO Completed | Generator |
| 441004 | SDMO J60U 60 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 27988 horas | Corrective Order | WO Completed | Generator |
| 409757 | SDMO J30U 38 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 12 021 | Corrective Order | WO Completed | Generator |
| 435141 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 21/08/2020 | 28385 hours | Corrective Order | WO Completed | Generator |
| 431133 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 11/08/2020 | 28 049 | Corrective Order | WO Completed | Generator |
| 447328 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 13/09/2020 | 29089 horas | Corrective Order | WO Completed | Generator |
| 441007 | Caterpillar DE88E0 58 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 29/08/2020 | 28696 horas | Corrective Order | WO Completed | Generator |
| 449650 | PRAMAC GSW65 48 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 18/09/2020 | 16391 hours | Corrective Order | WO Completed | Generator |
| 411441 | Olympian GEP18-6 18 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 23/05/2020 | | Corrective Order | WO Completed | Generator |
| 409765 | PRAMAC GSW30Y 24 kVa | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 10/05/2020 | 14999 HORAS | Corrective Order | WO Completed | Generator |
| 427828 | JLG 450 AJ Manlift | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 01/08/2020 | | Corrective Order | WO Completed | Manlift |
| 412628 | JLG 450 AJ Manlift | PREVENTIVE MAINTENANCE | OIL & FILTERS REPLACEMENT | 31/05/2020 | | Corrective Order | WO Completed | Manlift |
| 417802 | Caterpillar 236d Skid Steer L | PREVENTIVE MAINTENANCE 1000Hr | OIL & FILTERS REPLACEMENT | 04/07/2020 | 1858.5 | Corrective Order | WO Completed | Skid Steer |
| 433109 | Hyster E70xn 3t Forklift (E) | PROBLEMA CON EL PLUG DEL CARGA | PROBLEMA CON EL PLUG DEL CARGA | 16/08/2020 | | Corrective Order | WO Ready to Schedule | Forklift |
| 432529 | Caterpillar CS74 Compactor | PROBLEMA ELECTICO | PROBLEMA ELECTICO | 15/08/2020 | | Corrective Order | WO Completed | Compactor |
| 446798 | Mercedes Tipper Truck | Problema sistema de frenos | CAMBIO DE PULMONES | 12/09/2020 | | Corrective Order | WO Completed | Tipper |
| 435497 | Internation 4400 SBA 6x4 Boom | PROBLEMAS SISTEMA COMBUSTIBLE | CORRECTIVO | 22/08/2020 | | Corrective Order | WO Completed | Boom truck |
| 433738 | Manitou Mht-X1490 9t Telehand | QUARANTY REPAIR | VALVE CHANGE | 17/08/2020 | 1592 hrs | Corrective Order | WO Completed | Telehender |
| 441426 | Freightliner M2 106 Sucker Tru | Radiador roto | RADIADOR ROTO | 29/08/2020 | | Corrective Order | W/O In Planning | Sucker truck |
| 445038 | Coaster Bus | REAR BUMPER CHANGING | CORRECTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 445043 | Coaster Bus | REAR GLASS CHANGING | CORRECTIVE MAINTENANCE | 07/09/2020 | | Corrective Order | WO Completed | Bus |
| 407708 | MG012 16H CAT | REEMP TORNILL ZAPATA -SOLDAR | REEMP TORNILL ZAPATA -SOLDAR | 23/04/2020 | | Corrective Order | WO Completed | Grader |
| 423536 | WL013 966H CAT | REEMPLAZO DE BATERIA | SIST ELECTRICO/ MAL ESTADO | 19/07/2020 | | Backlog | WO Completed | Loader |
| 449238 | Grove RT9130E 120TON | REEMPLAZO DE BATERIAS | REEMPLAZO DE BATERIAS | 17/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Crane/Hoist |
| 446553 | USP&E GP700S/V-A 700 kVa | REEMPLAZO DE BATERIAS | EQUIPO SIN BATERIAS | 11/09/2020 | 14144 horas | Corrective Order | WO Completed | Generator |
| 453757 | Caterpillar 320DL Excavator | REEMPLAZO DE CORREA COMPRESOR | REEMPLAZO DE CORREA COMPRESOR | 27/09/2020 | AUTO CLOSED | Corrective Order | WO Completed | Excavator |
| 452046 | Intraax 53121 Hendrickso | REEMPLAZO DE LLANTAS | REEMPLAZO DE LLANTAS | 23/09/2020 | | Corrective Order | W/O In Planning | Trailer / Flatbed / Lime |
| 451806 | Caterpillar 236d Skid Steer L | REEMPLAZO DE LLANTAS | REEMPLAZO DE LLANTAS | 22/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 448116 | Caterpillar 236d Skid Steer L | REEMPLAZO DE MANDO FINAL | REEMPLAZO DE MANDO FINAL | 15/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 453806 | Manitou Mht-X1490 9t Telehand | REEMPLAZO DE MANGUERA | REEMPLAZO DE MANGUERA | 27/09/2020 | | Corrective Order | WO Ready to Schedule | Telehender |
| 454371 | Caterpillar 236d Skid Steer L | REEMPLAZODE 2 LLANTAS | REEMPLAZODE 2 LLANTAS | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Skid Steer |
| 448000 | Cargador 966H Wheel Loader | REFVISION DE FUGA HIDRUQALICA | REFVISION DE FUGA HIDRUQALICA | 15/09/2020 | | Corrective Order | WO Completed | Loader |
| 407068 | GROVE GMK 5170 170TON | Repair after inspection | TO PASS ITS INSPECT ADDITIONAL | 19/04/2020 | | Corrective Order | W/O In Planning | Crane/Hoist |
| 394642 | GROVE GMK 5170 170TON | Repair after inspection | TO PASS ITS INSPECT | 09/03/2020 | | Corrective Order | WO Ready to Schedule | Crane/Hoist |
| 441986 | Caterpillar 236d Skid Steer L | Repair axle | REPAIR AXLE | 31/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 448718 | Cargador 966H Wheel Loader | REPAIR BUCKET | REPAIR BUCKET | 16/09/2020 | | Corrective Order | WO Completed | Loader |
| 401169 | Samil Boom Truck | Repair cab & engine | REPAIR CAB & ENGINE | 22/03/2020 | | Corrective Order | W/O In Planning | Truck |
| 407003 | Grove GMK 4080 80TON | REPAIR FOR ITS INSPECTION | BACKLOG | 19/04/2020 | | Corrective Order | W/O In Planning | Crane |
| 443239 | Unimog Service Truck | Repair fule leak | REPAIR FULE LEAK | 03/09/2020 | 51863.1hrs | Corrective Order | WO Completed | Truck |
| 438517 | Mercedes Tipper Truck | Repair lights | REPAIR LIGHTS | 25/08/2020 | 315256 | Corrective Order | WO Completed | Tipper |
| 396760 | Caterpillar 12M Motorgrader | REPAIR YOKE & CYL | REPAIR YOKE & CYL | 13/03/2020 | orden creada usi | Corrective Order | WO Completed | Grader |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 452957 | Hyster H700 Forklift | Repar cilindro levante LH | FUGA ACEITE | 25/09/2020 | | Corrective Order | W/O In Planning | Forklift |
| 378471 | JLG T350 Manlift | REPARACIÃ“N DESPUÃ‰S INSPECCIOI | REPARACION DESPES DE LA INSPECCION | 07/02/2020 | 0000 hrs | Corrective Order | WO Completed | . |
| 378457 | JLG 1250 AJP Manlift | REPARACIÃ“N DESPUÃ‰S INSPECCIOI | REPARACION DESPES DE LA INSPECCION | 07/02/2020 | 6116.6 hrs | Corrective Order | WO Completed | . |
| 378459 | JLG 1250 AJP Manlift | REPARACIÃ“N DESPUÃ‰S INSPECCIOI | REPARACION DESPES DE LA INSPECCION | 07/02/2020 | 5786.0 hrs | Corrective Order | WO Completed | . |
| 451722 | Caterpillar 740B EJ ADT | REPARACION CILINDRO EJECTOR | EVALUACION DE DAÃ‘O | 22/09/2020 | | Corrective Order | W/O In Planning | Articulated dump truck |
| 414088 | BT019 345 IVECO GRUA 6X6 | REPARACION DE 2 ASIENTOS | CORRECTIVO IMREPSA | 11/06/2020 | | Corrective Order | W/O In Planning | . |
| 431605 | WT014 H7 CISTERNA SINOTRUK | REPARACION DE 2 LLANTAS | MANTIENE 2 LLANTAS FLAT | 12/08/2020 | 4243 hrs | Corrective Order | WO Completed | . |
| 431414 | Unimog Service Truck | Reparacion de arnes y cableado | REPARACION DE ARNES Y CABLEADO | 12/08/2020 | | Corrective Order | WO Completed | Truck |
| 451787 | Freightliner M2 106 Truck | REPARACION DE CAPOT | CORRECTIVO EN DOLLARS | 22/09/2020 | | Corrective Order | W/O In Planning | Boom truck |
| 451780 | Freightliner M2 106 Sucker Tru | REPARACION DE CAPOT | PROVEDOR DOLLARS | 22/09/2020 | | Corrective Order | W/O In Planning | Sucker truck |
| 448920 | JLG 450 AJ Manlift | Reparacion de fuga | REPARACION DE FUGA | 16/09/2020 | | Corrective Order | WO Completed | Manlift |
| 454244 | JLG 450 AJ Manlift | REPARACION DE FUGA HIDRAULICA | REPARACION DE FUGA HIDRAULICA | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Manlift |
| 398539 | JLG 1250 AJP Manlift | REPARACION DE FUGA HIDRAULICA | REPARACION DE FUGA HIDRAULICA | 16/03/2020 | | Corrective Order | WO Completed | . |
| 454365 | Freightliner Boom Truck | REPARACION DE LLANTA | REPARACION DE LLANTA | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| 451811 | Gallegos 28M3 Lime Tank | REPARACION DE LLANTA | REPARACION DE LLANTA | 22/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 450457 | Gallegos 28M3 Lime Tank | REPARACION DE LLANTA | REPARACION DE LLANTA | 19/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 451813 | GALLEGOS Lime Tank | REPARACION DE LLANTA | REPARACION DE LLANTA | 22/09/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 449227 | Hyster H300 13t Forklift (M) | Reparacion de llantas | REPARACION DE LLANTAS | 17/09/2020 | | Corrective Order | WO Completed | Forklift |
| 454378 | Broce broom RJT350 | Reparacion de llantas | REPARACION DE LLANTAS | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Scrubber / Sweeper |
| 439675 | Cargador 966H Wheel Loader | Reparacion de luces traseras | REPARACION E LUCES TRASETRAS | 27/08/2020 | 20098hrs | Corrective Order | WO Completed | Loader |
| 451640 | Manitou Mht-X1490 9t Telehand | Reparacion de manguera hidraul | REPARACION DE MANGUERA HIDRAUL | 22/09/2020 | | Corrective Order | WO Ready to Schedule | Telehender |
| 446966 | Caterpillar 14H Motorgrader | REPARACION DE MANGUERAS | MANGUERAS ROTAS | 12/09/2020 | 11571 hrs | Corrective Order | WO Completed | Grader |
| 427069 | Coaster Bus | REPARACION DE MOTOR | CORRECTIVO DOLLARS | 29/07/2020 | | Corrective Order | WO Completed | Bus |
| 429056 | Caterpillar 416F2 Backhoe | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | AUTO CLOSED | Corrective Order | WO Completed | Backhoe |
| 429050 | Grove RT600E 50TON | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 429044 | Gallegos Flatbed Trailer | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 429040 | Gallegos Flatbed Trailer | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 429042 | Gallegos Flatbed Trailer | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 429034 | Hyster H70ft 3t Forklift (M) | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Forklift |
| 429026 | Hyster H300 13t Forklift (M) | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Forklift |
| 429017 | Hyster H300 13t Forklift (M) | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Forklift |
| 429007 | Hyster H700 Forklift | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Forklift |
| 429004 | Gallegos 28M3 Lime Tank | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 429002 | GALLEGOS Lime Tank | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 428998 | GALLEGOS Lime Tank | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Trailer / Flatbed / Lime |
| 428995 | LV208 HIACE TOYOTA | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Light Vehicles |
| 428993 | Hilux DC | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Pickup truck |
| 428992 | Hilux DC | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Pickup truck |
| 428991 | Landcruiser DC | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Pickup truck |
| 428962 | Landcruiser DC | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Pickup truck |
| 428990 | Hiace Bus | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Bus |
| 428988 | Ford F550 | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Pickup truck |
| 428986 | MG003 12M CAT | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Grader |
| 428985 | Caterpillar 236d Skid Steer L | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 428982 | Caterpillar 236d Skid Steer L | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 428969 | Caterpillar 226b Skid Steer L | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Skid Steer |
| 428968 | TH001 TL1055CLRC CAT | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | . |
| 428967 | TH004 MHTX1020 Manitou | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | . |
| 428965 | TH012 LM 1745 New Holland | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | . |
| 428964 | Freightliner Columbia Cl112 | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 428963 | Freightliner Columbia Cl112 | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Ready to Schedule | Mule truck |
| 428960 | Freightliner Columbia Cl112 | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 429060 | WT013 H7 CISTERNA SINOTRUK | Reparacion de Neumatico | CORRECTIVO | 06/08/2020 | | Corrective Order | WO Completed | . |
| 360705 | Grove RT9130E 120TON | REPARACION DE TRANSMISION | REPARACION DE TRANSMISION | 03/01/2020 | 13094 hrs | Corrective Order | WO Completed | Crane |
| 419012 | Iveco 380t38 Bitumen Truck | REPARACION DE TRANSMISION | CORRECTIVO | 10/07/2020 | | Corrective Order | WO Completed | Truck |
| 399839 | JLG 800 AJ Manlift | Reparacion electrica y calibra | REPARACION ELECTRICA Y CALIBRA | 18/03/2020 | | Corrective Order | WO Completed | . |
| 425822 | Caterpillar 12M Motorgrader | REPARACION EN TALLER | REPARACION EN TALLER | 25/07/2020 | | Corrective Order | WO Completed | Grader |
| 418484 | JLG 1850 AJ Manlift | REPARACION LINEAS COMBUSTIBLE | CORRECTIVO | 08/07/2020 | 5595 hrs | Corrective Order | WO Completed | Manlift |
| 413459 | BT019 345 IVECO GRUA 6X6 | REPARACION MAYOR | CORRECTIVOS | 06/06/2020 | | Corrective Order | WO Ready to Schedule | . |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 425359 | Coaster Bus | Reparacion Motor | FALLA CILINDRO 6 | 23/07/2020 | | Corrective Order | WO Completed | Bus |
| 434189 | SITE SERVICES | Reparacion tuberia | REPARACION TUBERIA | 18/08/2020 | | Corrective Order | WO Completed | Area |
| 411969 | Caterpillar 307E Miniexcavator | REPARACION Y CAMBIO COMPONENT | CORRECTIVO FUGA-VIDRIO QUEBRADO-BAI | 27/05/2020 | 740.6 hrs | Corrective Order | WO Completed | Excavator |
| 446291 | Phoenix MK7T | Reparar mangueras | REPARAR MANGUERAS | 10/09/2020 | | Corrective Order | WO Completed | . |
| 381754 | MG012 16H CAT | REPARAR SISTEMA ELECTRICO | SISTEMA ELECTRICO | 13/02/2020 | | Corrective Order | WO Completed | Grader |
| 441409 | Internation F2674 | reparCION DE MANGUERA DE FRENO | REPARAR MANGUERA DE FRENO | 29/08/2020 | | Corrective Order | WO Completed | Boom truck |
| 438533 | Caterpillar 320DL Excavator | rEPLACE BUCKET TIPS | REPLACE BUCKET TIPS | 25/08/2020 | | Corrective Order | WO Completed | Excavator |
| 435861 | Caterpillar 12M Motorgrader | Replace cutting edges | REPLACE CUTTING EDGES | 23/08/2020 | 9807.5 hrs | Corrective Order | WO Completed | Grader |
| 448763 | Caterpillar 12M | Replace cutting edges | REPLACE CUTTING EDGES | 16/09/2020 | | Corrective Order | WO Completed | Grader |
| 438528 | CAT 930K | Replace cutting edges | REPLACE CUTTING EDGES | 25/08/2020 | AUTO CLOSED | Corrective Order | WO Completed | Loader |
| 439840 | Caterpillar 12M | Replace scarifier tooth | REPLACE SCARIFIER TOOTH | 27/08/2020 | | Corrective Order | WO Completed | Grader |
| 442362 | Caterpillar 320DL | rEPLACE SLEW MOTOR | REPLACE SLEW MOTOR | 01/09/2020 | 16809 | Corrective Order | WO Completed | Excavator |
| 447446 | Unimog U3000 Truck | Replace starter motor | REPLACE STARTER MOTOR | 13/09/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| 429648 | PRAMAC GSW80P 83 kVa | Replace v belt | REPLACE V BELT | 07/08/2020 | | Corrective Order | WO Completed | Generator |
| 437960 | Caterpillar 226b Skid Steer L | Replace worn pins | REPLACE WORN PINS | 24/08/2020 | | Corrective Order | W/O In Planning | Skid Steer |
| 436016 | Caterpillar 226b Skid Steer L | Replace worn pins | REPLACE WORN PINS | 23/08/2020 | 1814.1hrs | Corrective Order | WO Completed | Skid Steer |
| 427083 | JLG 1250 AJP Manlift | retorno de partes | RETORNO | 29/07/2020 | | Corrective Order | WO Completed | Manlift |
| 427084 | Grove RT700E 60TON | RETORNO DEPARTES | RETORNO | 29/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 428270 | Grove GMK 4080 80TON | Retorno Partes | DEVOLUCION | 03/08/2020 | | Corrective Order | WO Ready to Schedule | Crane/Hoist |
| 441590 | GS183 D110 E2 CAT | REVIEW & STARTING | CHECK ALL PARAMETERS, CLEANING | 30/08/2020 | 2673 hours | Corrective Order | WO Completed | Generator |
| 441033 | USP&E GP700S/V-A 700 kVa | REVIEW & STARTING | CHECK ALL PARAMETERS, CLEANING | 29/08/2020 | 12912 horas | Corrective Order | WO Completed | Generator |
| 441034 | USP&E GP700S/V-A 700 kVa | REVIEW & STARTING | CHECK ALL PARAMETERS, CLEANING | 29/08/2020 | 15301 horas | Corrective Order | WO Completed | Generator |
| 441032 | USP&E GP700/V-A 700 kVa | REVIEW & STARTING | CHECK ALL PARAMETERS, CLEANING | 29/08/2020 | 26140 horas | Corrective Order | WO Completed | Generator |
| 441589 | PRAMAC GSW45 35 kVa | REVIEW & STARTING | CHECK ALL PARAMETERS, CLEANING | 30/08/2020 | 10323 horas | Corrective Order | WO Completed | Generator |
| 433677 | GS129 T11UM SDMO | Revision | PREVENTIVE MAINTENANCE | 17/08/2020 | | Corrective Order | WO Completed | Generator |
| 431125 | USP&E GP700S/V-A 700 kVa | Revision | PREVENTIVE MAINTENANCE | 11/08/2020 | | Corrective Order | WO Completed | Generator |
| 435158 | PRAMAC GSW65 48 kVa | Revision | REVISION | 21/08/2020 | 15748 hours | Corrective Order | WO Completed | Generator |
| 433114 | Freightliner M2 106 Sucker Tru | REVISION DE AIRE ACONDICIONADO | REVISION DE AIRE ACONDICIONADO | 16/08/2020 | | Corrective Order | WO Ready to Schedule | Sucker truck |
| 428395 | Terex MAC25 25TON | REVISION DE BANDAS DE FRENOS | REVISION DE BANDAS DE FRENOS | 04/08/2020 | 12462 hrs | Corrective Order | WO Completed | Crane/Hoist |
| 431858 | Shuttlelift RTCD5540F 15TON | REVISION DE BOMBA HIDRAULICA | REVISION DE BOMBA HIDRAULICA | 13/08/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 453406 | Caterpillar 236d Skid Steer L | REVISION DE EQUIPO | REVISION DE EQUIPO | 26/09/2020 | | Corrective Order | WO Completed | Skid Steer |
| 455746 | Unimog Service Truck | REVISION DE EQUIPO | REVISION DE EQUIPO | 29/09/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| 427864 | Unimog Service Truck | REVISION DE EQUIPO | REVISION DE EQUIPO | 02/08/2020 | | Corrective Order | WO Completed | Truck |
| 425702 | Caterpillar 226b Skid Steer L | REVISION DE EQUIPO NEUTRALIZAD | REVISION DE EQUIPO NEUTRALIZAD | 25/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| 449209 | Caterpillar 307E Miniexcavator | REVISION DE EQUIPOI | REVISION DE EQUIPOI | 17/09/2020 | | Corrective Order | WO Ready to Schedule | Excavator |
| 446946 | Mercedes Tipper Truck | revision de frenos | REVISAR FRENOS | 12/09/2020 | | Corrective Order | WO Ready to Schedule | Tipper |
| 453247 | Caterpillar 416F2 Backhoe | REVISION DE FUGA | REVISION DE FUGA | 26/09/2020 | | Corrective Order | WO Completed | Backhoe |
| 426172 | Terex MAC25 25TON | Revision de fuga hidraulica | REVISION DE FUGA HIDRAULICA | 26/07/2020 | | Corrective Order | WO Completed | Crane/Hoist |
| 434029 | Freightliner M2 106 Sucker Tru | Revision de luces delanteras | REVISION DE LUCES DELANTERAS | 18/08/2020 | | Corrective Order | WO Completed | Sucker truck |
| 433111 | Hyster H300 13t Forklift (M) | REVISION DE MOTOR DE LIMPIAPAR | REVISION DE MOTOR DE LIMPIAPAR | 16/08/2020 | | Corrective Order | WO Completed | Forklift |
| 431913 | Freightliner Columbia Cl112 | REVISION DE POLEA TENSORA | REVISION DE POLEA TENSORA | 14/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 431912 | Manitou Mht-X860 6t Telehand | Revision de problemas electric | REVISION DE PROBLEMAS ELECTRIC | 14/08/2020 | | Corrective Order | WO Completed | Telehender |
| 433570 | Unimog Service Truck | Revision de PTO | REVISION DE PTO | 16/08/2020 | | Corrective Order | WO Completed | Truck |
| 450914 | Power Curbers 5700-C | REVISION DE SENSORES DE ESTABI | REVISION DE SENSORES DE ESTABI | 20/09/2020 | | Corrective Order | WO Ready to Schedule | . |
| 419013 | Caterpillar D8T Dozer | REVISION DE TRANMISION | CORRECTIVO | 10/07/2020 | | Corrective Order | WO Completed | Dozer |
| 433669 | Freightliner M2 106 Sucker Tru | REVISION DEL AIRE ACONDICIONAD | REVISION DEL AIRE ACONDICIONAD | 17/08/2020 | | Corrective Order | WO Ready to Schedule | Sucker truck |
| 451302 | Freightliner Boom Truck | REVISION ELECTRICA | REVISION ELECTRICA | 21/09/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| 454380 | Hyster E70xn 3t Forklift (E) | REVISION ELECTRICA | REVISION ELECTRICA | 28/09/2020 | | Corrective Order | WO Ready to Schedule | Forklift |
| 450907 | JLG 1250 AJP Manlift | REVISION ELECTRICA | REVISION ELECTRICA | 20/09/2020 | | Corrective Order | WO Completed | Manlift |
| 433661 | Mercedes Tipper Truck | REVISION ELECTRICA | REVISION ELECTRICA | 17/08/2020 | | Corrective Order | WO Completed | Tipper |
| 455721 | Freightliner Columbia Cl112 | REVISION ELECTRICA | REVISION ELECTRICA | 29/09/2020 | | Corrective Order | WO Completed | Mule truck |
| 433662 | Unimog Service Truck | REVISION ELECTRICA | REVISION ELECTRICA | 17/08/2020 | | Corrective Order | WO Completed | Truck |
| 434027 | Unimog Service Truck | REVISION ELECTRICA | REVISION ELECTRICA | 18/08/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| 444507 | Caterpillar 320DL | Revision falla sist hidraulico | CORRECTIVO PERDIDA PRESION CILINDROS | 06/09/2020 | 16809 hrs | Corrective Order | WO Completed | Excavator |
| 433670 | Freightliner Columbia Cl112 | REVISION GENERAL | REVISION GENERAL | 17/08/2020 | | Corrective Order | WO Completed | Mule truck |
| 425922 | Unimog Service Truck | REVISION MECANICA COMPLETA | INSPECCION Y EVALUACION IMREPSA | 25/07/2020 | | Corrective Order | W/O In Planning | Truck |
| 441668 | Unimog Service Truck | REVISION MECANICA COMPLETA | INSPECCION Y EVALUACION IMREPSA | 30/08/2020 | | Repair/Assembly Order | W/O In Planning | Truck |
| 441670 | Unimog Service Truck | REVISION MECANICA COMPLETA | INSPECCION Y EVALUACION IMREPSA | 30/08/2020 | | Repair/Assembly Order | W/O In Planning | Truck |
| 419011 | Freightliner M2 106 Hydroseedi | REVISION SISTEMA ELECTRICO | CORRECTIVO | 10/07/2020 | | Corrective Order | W/O In Planning | Truck |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| | 425409 | Hyster H800 32t Forklift (M) | REVISION SISTEMA HIDRAULICO | REVISION SISTEMA HIDRAULICO | 24/07/2020 | | Corrective Order | WO Completed | Forklift |
| | 429773 | Freightliner M2 106 Truck | REVISON DE EQUIPO | REVISON DE EQUIPO | 07/08/2020 | | Corrective Order | WO Completed | Boom truck |
| | 436037 | Caterpillar 320DL | ROTURA DE VALVULA DE GIRO | CORRECTIVO | 23/08/2020 | 16809hrs | Corrective Order | WO Completed | Excavator |
| | 427135 | Caterpillar 226b Skid Steer L | RUIDO EN LAS RUEDAS | RUIDO EN LAS RUEDAS | 30/07/2020 | | Corrective Order | WO Completed | Skid Steer |
| | 447995 | Caterpillar 14M Motorgrader | Se recalienta aceite hidraulic | SE DEBE REVISAR SISTEMA HIDRAULICO | 15/09/2020 | | Corrective Order | WO Completed | Grader |
| | 375640 | Unimog Service Truck | SEATS & BREAKE CYL REPLACEMENT | SEATS & BREAKE CYL REPLACEMENT | 02/02/2020 | | Corrective Order | WO Ready to Schedule | Truck |
| | 431349 | PRAMAC GBW15 14 kVa | Service and repair | SERVICE AND REPAIR | 11/08/2020 | | Corrective Order | WO Completed | Generator |
| | 430656 | Mercedes Tipper Truck | Servicio de mantenimiento | SERVICIO IMREPSA | 09/08/2020 | | Corrective Order | WO Completed | Tipper |
| | 430641 | Mercedes Tipper Truck | SERVICIO DE MTTO Y REPARACION | SERVICIO IMREPSA | 09/08/2020 | | Corrective Order | W/O In Planning | Tipper |
| | 446464 | Freightliner Columbia Cl112 | Silenciador Danado | SE CAMBIA SILENCIADOR | 11/09/2020 | 2249.4 hrs | Corrective Order | WO Completed | Mule truck |
| | 433164 | Freightliner M2 112 | Sistema electrico | REPAIR | 16/08/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| | 433162 | Freightliner M2 112 | Sistema electrico | REPAIR | 16/08/2020 | | Corrective Order | WO Ready to Schedule | Boom truck |
| | 434024 | JLG 1250 AJP Manlift | SOLDAR PIPE DEL PISTON | SOLDAR PIPE DEL PISTON | 18/08/2020 | | Corrective Order | WO Ready to Schedule | Manlift |
| | 439185 | Coaster Bus | Tires danaged and worn out | TIRES DANAGED AND WORN OUT | 26/08/2020 | | Corrective Order | WO Completed | Bus |
| | 447509 | Freightliner Cl 120 | Tires fitting | TIRES FITTING | 13/09/2020 | | Corrective Order | WO Ready to Schedule | Mule truck |
| | 450910 | Freightliner M112 Truck Tip | Trabajos de soldadura | TRABAJOS DE SOLDADURA | 20/09/2020 | | Corrective Order | WO Completed | Tipper |
| | 427399 | Freightliner 8170ME Water Truc | TUBERIA DE DSCAGA PARTIDA | TUBERIA DE DSCAGA PARTIDA | 31/07/2020 | | Corrective Order | WO Completed | Water truck |
| | 427021 | PRAMAC GSW110P 82 kVa | V belt broken | V BELT BROKEN | 29/07/2020 | | Corrective Order | WO Completed | Generator |